



report date: 2024-03-28

General information

| | |
|---------------------|---------------------------|
| Make | CITROEN |
| Model | DS4 E-HDI DSTYLE AIRDREAM |
| Colour | Black |
| Year of manufacture | 2011 |
| Top speed | 118 mph |
| 0 - 60 mph | 12.4 seconds |
| Gearbox | 6 speed Semi-Automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 110 BHP |
| Max. torque | 270 Nm at 1.750 rpm |
| Engine capacity | 1.560 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 58.9 mpg |
| Consumption extra urban | 68.9 mpg |
| Consumption combined | 64.2 mpg |
| CO2 emission | 114 g/km |
| CO2 label | C |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-11-09 |
| Pictures | 0 |
| Listing price | View report |

source: [autotrader.co.uk](#)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-01-17 |
| MOT pass rate | 77 % |
| MOT passed | 10 |
| Failed MOT tests | 3 |
| Total advice items | 33 |
| Total items failed | 9 |

| | |
|------------------|------------------|
| MOT #13 | 2024-01-18 12:39 |
| MOT test number | 562705962022 |
| Result | ✓ Passed |
| Next expiry date | 2025-01-17 |

| | |
|-----------------|--|
| MOT #12 | 2022-11-14 12:16 |
| MOT test number | 998016772605 |
| Result | ✓ Passed |
| Advice | Front brake discs slight rusted inside |
| Advice | Front windscreen passenger side crack |
| Advice | Slight underbody corrosion |
| Advice | Nearside Rear Child Seat fitted not allowing full inspection of adult belt |
| Advice | Exhaust rusted |

| | |
|-----------------|------------------|
| MOT #11 | 2021-11-01 12:34 |
| MOT test number | 268281647923 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #10 | 2020-11-09 09:48 |
| MOT test number | 971791537285 |
| Result | ✓ Passed |

**MOT #9** 2019-11-16 09:32**MOT test number** 611089034954**Result** ✓ Passed**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**MOT #8** 2018-11-10 12:06**MOT test number** 295057381642**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #7** 2018-11-03 14:51**MOT test number** 890723210691**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Pass with rectification** Offside Headlamp aim so that beam "kick up" is not visible on the screen (4.1.2 (a))**Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))



MOT #62017-11-10 16:44

MOT test number382894013567

| Result | | ✓ Passed |
|--------|---|----------|
| Advice | Nearside Front Tyre worn close to the legal limit (4.1.E.1) | |
| Advice | Front brake pads are low | |
| Advice | Nearside Rear Tyre worn close to the legal limit (4.1.E.1) | |
| Advice | Undertray fitted | |
| Advice | Offside Front Tyre worn close to the legal limit (4.1.E.1) | |
| Advice | Slight corrosion to front brake discs (inner faces) | |
| Advice | Engine cover fitted | |

**MOT #5** 2017-11-09 14:39**MOT test number** 975776625772**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Engine cover fitted**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Front brake pads are low**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nail in o/s/r tyre**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Undertray fitted**Fail** Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**Advice** Slight corrosion to front brake discs (inner faces)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2016-11-03 14:14**MOT test number** 579846570368**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)**MOT #3** 2015-10-21 09:07**MOT test number** 840432610352**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



| | |
|-----------------|---|
| MOT #2 | 2014-10-27 15:36 |
| MOT test number | 379490004330 |
| Result | ✓ Passed |
| Notice | Nail in nearside rear tyre |
| Notice | Large flap on nearside front tyre sidewall, NOT down to cords |

| | |
|-------------------------|---|
| MOT #1 | 2014-10-27 15:36 |
| MOT test number | 978970104366 |
| Result | ✗ Failed |
| Pass with rectification | Offside Registration plate lamp not working (1.1.C.1d) |
| Notice | Large flap on nearside front tyre sidewall, NOT down to cords |
| Pass with rectification | Nearside Registration plate lamp not working (1.1.C.1d) |
| Notice | Nail in nearside rear tyre |



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
17 January 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 November |
| Days left | 186 |
| MOT expiry date | 17 January 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|----------------|
| Vehicle class | 49 |
| Band | C |
| Single payment (12 months) | £ 35,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 36,75,- |



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 10,000 |
| Auction value | £ 10,000 |
| Average private trade value | £ 10,000 |

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this CITROEN had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | AK61VEV |
| Plate since | 2019-03-28 |
| Current registration | AK61VEV |
| Plate since | 2019-03-28 |

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 14 |
| First mileage registration | 2011-11-17 |
| Last registration | 2024-01-18 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2011-11-17 | 16 mi |
| Registration #2 | 2014-10-27 | 59.324 mi |
| Registration #3 | 2015-10-21 | 74.232 mi |
| Registration #4 | 2016-11-03 | 91.202 mi |
| Registration #5 | 2017-11-09 | 104.495 mi |
| Registration #6 | 2017-11-10 | 104.495 mi |
| Registration #7 | 2018-11-03 | 110.890 mi |
| Registration #8 | 2019-05-29 | 121.277 mi |
| Registration #9 | 2019-05-29 | 121.277 mi |
| Registration #10 | 2019-05-29 | 121.277 mi |
| Registration #11 | 2019-05-29 | 121.277 mi |
| Registration #12 | 2019-05-29 | 121.277 mi |
| Registration #13 | 2019-05-29 | 121.277 mi |
| Registration #14 | 2019-05-29 | 121.277 mi |

More info >



Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 90% |
| Children | 80% |
| Pedestrian | 43% |
| Safety systems | 97% |
| Overall rating | 79% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1810 mm |
| Height | 1523 mm |
| Length | 4275 mm |
| Wheel base | 2612 mm |
| Kerb weight | 1320 kg |
| Max. allowed weight | 1815 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 60 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | JBEH3025004 |