



report date: 2024-03-28

General information

Make	FORD
Model	KUGA LX TDCI
Colour	Silver
Year of manufacture	2008
Top speed	122 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	52.3 mpg
Consumption combined	44.1 mpg
CO2 emission	169 g/km
CO2 label	H





Internet history

Entry 1	
Date	2021-01-31
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-06-08
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	19
Total items failed	6

MOT #16 2023-06-09 15:50

MOT test number 735802311301

Result ✓ Passed

Next expiry date 2024-06-08

Advice Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

MOT #15 2023-06-09 12:44

MOT test number 783506216473

Result ✗ Failed

Fail Windscreen washer not working (3.5 (a))

Advice Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

**MOT #14** 2022-05-13 14:00**MOT test number** 295871885362**Result** ✓ Passed**Advice** Both rear tyres worn badly on inner edges**Advice** Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))**Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))**MOT #13** 2022-05-13 12:47**MOT test number** 448602419051**Result** ✗ Failed**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))**Advice** Both rear tyres worn badly on inner edges**Fail** Windscreen washer not working (3.5 (a))**Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))**MOT #12** 2021-04-26 13:47**MOT test number** 727053217859**Result** ✓ Passed**MOT #11** 2021-04-26 09:52**MOT test number** 461492510792**Result** ✗ Failed**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #10** 2020-05-11 09:20**MOT test number** 286443407132**Result** ✓ Passed**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Plastic cover sills ,undertrays,engine covers.**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #9** 2019-05-02 11:07**MOT test number** 835896094745**Result** ✓ Passed**MOT #8** 2018-04-19 14:06**MOT test number** 112556752529**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Sub-frame corroded but not seriously weakened (2.4.G.1)**MOT #7** 2017-05-02 13:52**MOT test number** 726978692312**Result** ✓ Passed**Advice** Nearside Front Inner Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2016-05-03 12:08**MOT test number** 480239079888**Result** ✓ Passed



MOT #5	2015-05-01 11:42
MOT test number	807451425145
Result	✓ Passed
MOT #4	2014-05-14 16:57
MOT test number	258254434412
Result	✓ Passed
MOT #3	2013-07-05 09:09
MOT test number	436086283143
Result	✓ Passed
MOT #2	2012-07-04 08:47
MOT test number	695266782188
Result	✓ Passed
MOT #1	2011-07-04 12:39
MOT test number	175775081100
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
8 June 2024

Tax status	Valid until 1 April
Days left	338
MOT expiry date	8 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-28
Current registration	*****
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-07-18
Last registration	2023-06-09
Complete history	See info



Registration #1	2008-07-18	15 mi
Registration #2	2011-07-04	16.631 mi
Registration #3	2012-07-04	22.987 mi
Registration #4	2013-07-05	29.009 mi
Registration #5	2014-05-14	33.179 mi
Registration #6	2015-05-01	40.375 mi
Registration #7	2016-05-03	45.344 mi
Registration #8	2017-05-02	50.063 mi
Registration #9	2018-04-19	54.832 mi
Registration #10	2019-05-01	59.591 mi
Registration #11	2020-05-01	64.350 mi
Registration #12	2021-05-01	69.109 mi
Registration #13	2022-05-01	73.868 mi
Registration #14	2023-05-01	78.627 mi
Registration #15	2024-05-01	83.386 mi
Registration #16	2025-05-01	88.145 mi
Registration #17	2026-05-01	92.904 mi
Registration #18	2027-05-01	97.663 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1736 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	8R41969