



RENAULT

PKIUTU

report date: 2024-03-28

General information

Make	RENAULT
Model	TRAFIC SL27 DCI S/R P/V
Colour	Silver
Year of manufacture	2011
Top speed	96 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	290 Nm at 1.600 rpm
Engine capacity	1.996 cc
Cylinders	4
Fuel type	Diesel
Consumption city	33.2 mpg
Consumption extra urban	41.5 mpg
Consumption combined	38.1 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-11
Pictures	13
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-12-01
MOT pass rate	58 %
MOT passed	11
Failed MOT tests	8
Total advice items	20
Total items failed	27

MOT #19	2023-11-16 14:42
MOT test number	247000317202
Result	✓ Passed
Next expiry date	2024-12-01
Minor	Central Upper Stop lamp(s) lens defective which has no effect on emitted light (4.3.1 (b) (i))
Minor	Offside Rear Direction indicator lens defective which has no effect on emitted light (4.4.1 (b) (i))

**MOT #18**

2023-11-14 16:38

MOT test number

836208442795

Result

✗ Failed

- Fail** Front Brake disc significantly and obviously worn both (1.1.14 (a) (i))
- Fail** Offside Rear Brake lever not releasing correctly and functionality of brakes affected (1.1.2 (b) (ii))
- Fail** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Fail** Offside Rear Parking (secondary brake) on a single line braking system has no recorded effort at a wheel (1.3.1 (a) (ii))
- Minor** Offside Rear Direction indicator lens defective which has no effect on emitted light (4.4.1 (b) (i))
- Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
- Fail** Offside Rear Brake cable damaged (1.1.15 (a))
- Fail** Nearside Front Lower Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Fail** Front Sub-frame is so deformed it is likely to adversely affect braking or steering both bushes worn and affecting steering and braking (6.1.1 (a) (ii))
- Minor** Central Upper Stop lamp(s) lens defective which has no effect on emitted light (4.3.1 (b) (i))

MOT #17

2022-11-21 16:26

MOT test number

524281689935

Result

✓ Passed

- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Minor** Nearside Front Lower Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #16**

2022-11-18 16:15

MOT test number

371700230287

Result**✗ Failed**

- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Fail** Horn not working (7.7 (a))
- Fail** Offside Rear Axle swivel pins and bushes swivel pin and/or bush excessively worn (5.1.2 (b) (i))
- Minor** Nearside Front Lower Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Fail** Nearside Track rod end ball joint worn to the extent there is a serious risk of detachment (2.1.3 (b) (ii))
- Fail** Nearside Rear Axle swivel pins and bushes swivel pin and/or bush excessively worn (5.1.2 (b) (i))

MOT #15

2021-12-02 16:11

MOT test number

920258166483

Result**✓ Passed**

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #14

2021-12-02 08:48

MOT test number

760140738543

Result**✗ Failed**

- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Horn sound not in accordance with requirements (7.7 (c))

MOT #13

2021-09-24 14:05

MOT test number

835421995237

Result**✓ Passed**

**MOT #12** 2021-09-23 11:49**MOT test number** 667326619040**Result** ✗ Failed**Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #11** 2020-09-17 09:45**MOT test number** 221072087096**Result** ✓ Passed**MOT #10** 2020-09-16 14:31**MOT test number** 149252166062**Result** ✗ Failed**Fail** Offside Front Inner Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))**Fail** Nearside Front Outer Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MOT #9** 2019-09-16 15:21**MOT test number** 884801298334**Result** ✓ Passed**MOT #8** 2019-09-16 09:28**MOT test number** 977134100523**Result** ✗ Failed**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Fail** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))**Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))

**MOT #7** 2018-06-20 15:27**MOT test number** 858663682347**Result** ✓ Passed**MOT #6** 2018-06-18 15:06**MOT test number** 887492415376**Result** ✗ Failed**Fail** Horn not working (7.7 (a) (ii))**Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Fail** Upper Stop lamp(s) not working (4.3.1 (a) (ii))**Minor** Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**MOT #5** 2017-06-06 07:29**MOT test number** 874281226686**Result** ✓ Passed**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)**Advice** Offside Front fog lamp inoperative

**MOT #4** 2017-06-06 07:29**MOT test number** 605561255384**Result** ✗ Failed**Advice** Offside Front fog lamp inoperative**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Main beam 'tell-tale' not working (1.7.4c)**Advice** Nearside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)**MOT #3** 2016-06-14 07:54**MOT test number** 608952386364**Result** ✓ Passed**MOT #2** 2015-06-22 13:05**MOT test number** 137653475120**Result** ✓ Passed**MOT #1** 2014-07-03 08:45**MOT test number** 828914784117**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
1 December 2024

Tax status	Valid until 1 March
-------------------	---------------------

Days left	307
------------------	-----

MOT expiry date	1 December 2024
------------------------	-----------------

Full MOT history	See MOT history
-------------------------	---------------------------------



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	PK11UTU
Plate since	2019-09-28
Current registration	PK11UTU
Plate since	2019-09-28

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2011-06-15
Last registration	2023-11-16
Complete history	See info



Registration #1	2011-06-15	6 mi
Registration #2	2014-07-03	30.412 mi
Registration #3	2015-06-22	41.599 mi
Registration #4	2016-06-14	56.095 mi
Registration #5	2017-06-06	66.636 mi
Registration #6	2017-06-06	66.636 mi
Registration #7	2018-06-18	81.617 mi
Registration #8	2018-06-20	81.680 mi
Registration #9	2019-09-16	92.582 mi
Registration #10	2019-09-16	92.582 mi
Registration #11	2020-09-16	96.430 mi
Registration #12	2020-09-16	96.430 mi
Registration #13	2020-09-16	96.430 mi
Registration #14	2020-09-16	96.430 mi
Registration #15	2020-09-16	96.430 mi
Registration #16	2020-09-16	96.430 mi
Registration #17	2020-09-16	96.430 mi
Registration #18	2020-09-16	96.430 mi
Registration #19	2020-09-16	96.430 mi
Registration #20	2020-09-16	96.430 mi
Registration #21	2020-09-16	96.430 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1904 mm
Height	1955 mm
Length	4782 mm
Kerb weight	1660 kg
Max. allowed weight	2770 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	C175241