



report date: 2024-03-29

General information

| | |
|---------------------|----------------|
| Make | VAUXHALL |
| Model | CORSA GRIFFIN |
| Colour | Red |
| Year of manufacture | 2019 |
| Top speed | 104 mph |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|----------------------|---------------------|
| Power | 74 BHP |
| Max. torque | 130 Nm at 4.000 rpm |
| Engine capacity | 1.398 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption combined | 43.5 mpg |
| CO2 emission | 128 g/km |
| CO2 label | D |






Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-08-18 |
| Pictures | 10 |
| Listing price | View report |



source: autoonline.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-08-17 |
| MOT pass rate | 75 % |
| MOT passed | 3 |
| Failed MOT tests | 1 |
| Total advice items | 5 |
| Total items failed | 0 |

MOT #4 2023-08-15 15:26

MOT test number 105617235242

Result ✓ Passed

Next expiry date 2024-08-17

Advice Front Tyre worn close to legal limit/worn on edge Offside & Nearside worn on edges. (5.2.3 (e))**Advice** Nearside Rear Outer Tyre slightly damaged/cracking or perishing Sidewall perishing. (5.2.3 (d) (ii))

MOT #3 2023-08-15 12:50

MOT test number 162589299261

Result ✗ Failed**Advice** Front Tyre worn close to legal limit/worn on edge Offside & Nearside worn on edges. (5.2.3 (e))**MAJOR** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Rear Outer Tyre slightly damaged/cracking or perishing Sidewall perishing. (5.2.3 (d) (ii))

MOT #2 2022-08-11 13:16

MOT test number 713973879374

Result ✓ Passed

MOT #1 2021-08-18 14:39

MOT test number 952094156498

Result ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
17 August 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 August |
| Days left | 94 |
| MOT expiry date | 17 August 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--------------------------------------|------------|
| Vehicle class | 48 |
| Band | G |
| First licence fee (12 months) | £ 210,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

| | |
|----------------------|--|
| Number of plates | 1 |
| Current registration |  PE19VDC |
| Plate since | 2019-03-29 |
| Current registration |  PE19VDC |
| Plate since | 2019-03-29 |

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 6 |
| First mileage registration | 2019-03-29 |
| Last registration | 2023-08-15 |
| Complete history | See info |



| | | |
|-----------------|------------|-----------|
| Registration #1 | 2019-03-29 | 29 mi |
| Registration #2 | 2019-03-29 | 29,377 mi |
| Registration #3 | 2021-08-18 | 14,035 mi |
| Registration #4 | 2019-03-29 | 29,377 mi |
| Registration #5 | 2019-03-29 | 29,377 mi |
| Registration #6 | 2019-03-29 | 29,377 mi |

More info >



Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★☆ |
| Adult | 79% |
| Children | 77% |
| Pedestrian | 71% |
| Safety systems | 56% |
| Overall rating | 72% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1736 mm |
| Height | 1479 mm |
| Length | 4021 mm |
| Wheel base | 2510 mm |
| Kerb weight | 1066 kg |
| Max. allowed weight | 1600 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 45 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 3 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | B14XER -19UZ3825LDD |