





General information

Make	ΤΟΥΟΤΑ
Model	IQ VVT-I IQ
Colour	Black
Year of manufacture	2009
Top speed	93 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Max. torque 91 Nm at 4.800 rpm 101 - 120 Engine capacity 998 cc 121 - 140 Cylinders 3 141 - 165 Fuel type Petrol 166 - 185 Consumption city 57.7 mpg 186 - 225 Consumption extra urban 72.4 mpg 225+			
Max. torque 91 Nm at 4.800 rpm 101 - 120 Engine capacity 998 cc 121 - 140 Cylinders 3 141 - 165 Fuel type Petrol 166 - 185 Consumption city 57.7 mpg 186 - 225 Consumption combined 65.7 mpg 225+	Power	67 BHP	0 < 101 A
Engine capacity 998 cc 121 - 140 Cylinders 3 141 - 165 Fuel type Petrol 166 - 185 Consumption city 57.7 mpg 186 - 225 Consumption extra urban 72.4 mpg 225+	Max. torque	91 Nm at 4.800 rpm	
Cylinders 3 141 - 165 Fuel type Petrol 166 - 185 Consumption city 57.7 mpg 186 - 225 Consumption extra urban 72.4 mpg 225+ Consumption combined 65.7 mpg 186 - 225	Engine capacity	998 cc	
Consumption city57.7 mpg186 - 225Consumption extra urban72.4 mpg225+Consumption combined65.7 mpg	Cylinders	3	
Consumption extra urban72.4 mpg225+Consumption combined65.7 mpg	Fuel type	Petrol	166 - 185
Consumption combined 65.7 mpg	Consumption city	57.7 mpg	186 - 225
	Consumption extra urban	72.4 mpg	225+
CO2 emission 99 g/km	Consumption combined	65.7 mpg	
	CO2 emission	99 g/km	
CO2 label A	CO2 label	А	





Internet history

Entry 1

Date

2022-04-28

Pictures

Listing price

View report

8



source: cargurus.co.uk



MOT history

MOT expiry date	2025-04-04
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	10
Total items failed	9

MOT #14	2024-04-05 13:54
MOT test number	219744391473
Result	✓ Passed
Next expiry date	2025-04-04

MOT #13	2023-03-29 13:46
MOT test number	669581307700
Result	✓ Passed





MOT #12	2023-03-28 16:13
MOT test number	382713470225
Result	🗙 Failed
Fail Nearside Rear Outer Tyre has ply or cords exposed sidewall/tread 175/65/15 (5.2.3 (d) (ii))
Fail Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the (5.3.4 (b) (ii))	e ingress of dirt
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Fail Nearside Headlamp aim too high (4.1.2 (a))	
Fail (a) (i))Offside Front Lower Suspension component insecurely attached ball joint securing picture	n missing (5.3.3
Advice Offside Rear Outer Tyre slightly damaged/cracking or perishing tread sidewall (5.	2.3 (d) (ii))
Fail Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the (5.3.4 (b) (ii))	ingress of dirt
FailNearside Front Position lamp not working (4.2.1 (a) (ii))	
Fail Offside Headlamp aim too low (4.1.2 (a))	

MOT #11		2022-03-31 14:49
MOT test	number	689325858589
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #10	2021-03-31 16:18
MOT test number	910171814125
Result	✓ Passed



SY58VZ	. F
report date: 2024-0	03-29

MOT #9		2021-03-31 16:18
MOT test number		229868824124
Result		🗙 Failed
Pass with rectification	Offside Headlamp aim too low (4.1.2 (a))	
Pass with rectification	Nearside Headlamp aim too low (4.1.2 (a))	
MOT #8		2019-07-11 10:58
MOT test number		858078298797
Result		✓ Passed
MOT #7		2018-04-19 14:32
MOT test number		367270270657
Result		✓ Passed
МОТ #6		2017-03-31 12:43
MOT test number		565280160966

Result

2016-04-05 10:46
913991088064
✓ Passed

🗸 Passed





MOT #4		2015-03-30 13:13
MOT test	number	155349385070
Result		✓ Passed
Notice	N/s/r tyre is wearing on edges and cracking on edges.	
Notice	Chip in winscreen.	
Notice	Both front tyres are wearing on edges.	
MOT #3		2014-04-01 10:38
MOT test	number	108401094461
Result		✓ Passed

MOT #2	2013-03-26 15:01
MOT test number	185745083038
Result	✓ Passed

O/s winscreen wiper is starting to split.

MOT #1	2012-02-14 11:37
MOT test number	125955542453
Result	✓ Passed

Notice



Tax & MOT check

Tax due: 1 May 2025	✓ Taxed	Expires: 4 April 2025	✓ МОТ
Tax status			Valid until 1 May
Days left			366
MOT expiry date			4 April 2025
Full MOT history			See MOT history
Tax calculation			
Vehicle class		48	

Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date	F	ET
Category		LAMP
Туре		
Damage 2		AMPL
	F	A A A A A A A A A A A A A A A A A A A
Date		1º
Category		SMT.
Туре		

Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.700
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

ana	

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-01-08
Last registration	2024-04-05
Complete history	See info



Registration #1	2009-01-08	25 mi
Registration #2	2012-02-14	13.389 mi
Registration #3	2013-03-26	21.748 mi
Registration #4	2014-04-01	29.645 mi
Registration #5	2015-03-30	35.582 mi
Registration #6	2016-04-05	41.377 mi
Registration #7	2017-03-31	47.337 mi
Registration #8	2018-04-19	49.490 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.117 mi

More info >





Car features

S0225	Air conditioning
\$0295	
S0482	
\$0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	91%
Children	71%
Pedestrian	54%
Safety systems	86%
Overall rating	79%
Video	see crash video



Dimensions & weight	
Width	1680 mm
Height	1500 mm
Length	2985 mm
Wheel base	2000 mm
Kerb weight	845 kg
Max. allowed weight	1215 kg
Additional information	
Fuel tank capacity	32
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 13/13

Number of axles	2
Engine number	1KR0827053