



report date: 2024-03-29

General information

Make	KIA
Model	CARENS GS CRDI
Colour	Black
Year of manufacture	2009
Top speed	116 mph
0 - 60 mph	12.6 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	138 BHP
Max. torque	305 Nm at 2.500 rpm
Engine capacity	1.991 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.4 mpg
Consumption extra urban	49.6 mpg
Consumption combined	39.8 mpg
CO2 emission	189 g/km
CO2 label	J







Internet history

Entry 1

Date	2021-07-29
Pictures	24
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-08-10
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	35
Total items failed	14

MOT #16	2023-07-18 10:10
MOT test number	424824123761
Result	✓ Passed
Next expiry date	2024-08-10

MOT #15	2022-08-11 14:44
MOT test number	727640880275
Result	✓ Passed
Advice	Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14** 2022-08-08 10:01**MOT test number** 611180637326**Result** ✗ Failed

- Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Nearside Front Tyre has ply or cords exposed inner edge (5.2.3 (d) (ii))
- Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Wheel bearing has excessive play (5.1.3 (a) (i))

MOT #13 2021-08-10 10:59**MOT test number** 921841797310**Result** ✓ Passed

- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Front Exhaust mounting defective (6.1.2 (a))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #12 2019-09-03 16:19**MOT test number** 417644785008**Result** ✓ Passed

**MOT #11**

2019-09-02 10:56

MOT test number

944998448601

Result**✗ Failed****Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))**Advice** Front Brake pad(s) wearing thin close to limit (1.1.13 (a) (ii))**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Exhaust mounting defective (6.1.2 (a))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #10**

2018-08-31 14:01

MOT test number

862802678106

Result**✓ Passed****MOT #9**

2017-09-02 13:28

MOT test number

784255639584

Result**✓ Passed****Advice** N/s/f tyre wearing on inside edge**MOT #8**

2016-07-29 09:43

MOT test number

836304749165

Result**✓ Passed**

**MOT #7** 2016-07-27 09:09**MOT test number** 425473742273**Result** ✗ Failed**Advice** Nearside headlamp dip beam not tested**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**MOT #6** 2015-07-03 16:11**MOT test number** 279074085118**Result** ✓ Passed**Notice** Nearside front tyre worn inside edge**Notice** Front brake pads worn thin**MOT #5** 2015-07-02 10:40**MOT test number** 459423085118**Result** ✗ Failed**Fail** Nearside Headlamp aim not tested (1.8.A.1c)**Notice** Nearside front tyre worn inside edge**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**Notice** Front brake pads worn thin**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #4** 2014-07-08 15:33**MOT test number** 189159984154**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Engine covers fitted obscuring some components in the engine bay

**MOT #3** 2014-07-03 13:37**MOT test number** 235564684186**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #2** 2013-06-21 13:33**MOT test number** 858922673116**Result** ✓ Passed**Notice** Front brake discs worn thin**Notice** Offside front tyre worn bald on edges**Notice** Both rear tyres worn edges**Notice** Under-trays fitted obscuring some underside components**Notice** Front brake pads worn thin**Notice** Nearside front tyre worn edges**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #1** 2012-06-21 10:46**MOT test number** 209003872157**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
10 August 2024

Tax status	Valid until 1 August
Days left	93
MOT expiry date	10 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-06-25
Last registration	2023-07-18
Complete history	See info



Registration #1	2009-06-25	15 mi
Registration #2	2012-06-21	33.690 mi
Registration #3	2013-06-21	40.001 mi
Registration #4	2014-07-03	46.131 mi
Registration #5	2014-07-08	46.156 mi
Registration #6	2015-07-02	50.285 mi
Registration #7	2015-07-03	50.285 mi
Registration #8	2016-07-27	55.655 mi
Registration #9	2016-07-29	55.655 mi
Registration #10	2016-07-29	55.655 mi
Registration #11	2016-07-29	55.655 mi
Registration #12	2016-07-29	55.655 mi
Registration #13	2016-07-29	55.655 mi
Registration #14	2016-07-29	55.655 mi
Registration #15	2016-07-29	55.655 mi
Registration #16	2016-07-29	55.655 mi
Registration #17	2016-07-29	55.655 mi
Registration #18	2016-07-29	55.655 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1720 mm
Length	4545 mm
Wheel base	2700 mm
Kerb weight	1681 kg
Max. allowed weight	2275 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	D4EA8H370949