



report date: 2024-03-28

General information

| | |
|---------------------|-------------------|
| Make | FORD |
| Model | FUSION ZETEC TDCI |
| Colour | Silver |
| Year of manufacture | - |
| Top speed | 98 mph |
| 0 - 60 mph | 16.1 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 67 BHP |
| Max. torque | 160 Nm at 2.000 rpm |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 49.6 mpg |
| Consumption extra urban | 72.4 mpg |
| Consumption combined | 62.8 mpg |



LABEL UNKNOWN



Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-06-16 |
| Pictures | 0 |
| Listing price | View report |

source: [autotrader.co.uk](#)

**MOT history**

| | |
|-------------------------|---|
| MOT #15 | 2023-07-13 09:35 |
| MOT test number | 641059593891 |
| Result | ✓ Passed |
| Next expiry date | 2024-07-13 |
| Advice | Rear Brake pipe corroded, covered in grease or other material front to rear pipes greased (1.1.11 (c)) |
| Advice | Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i)) |
| Advice | Nearside Rear Brake pipe corroded, covered in grease or other material back plate pipe greased (1.1.11 (c)) |
| Minor | Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |

| | |
|------------------------|--|
| MOT #14 | 2022-07-11 09:14 |
| MOT test number | 144945549184 |
| Result | ✓ Passed |
| Advice | Rear Brake pipe corroded, covered in grease or other material rear back plate pipes greased (1.1.11 (c)) |

| | |
|------------------------|--|
| MOT #13 | 2021-07-14 15:04 |
| MOT test number | 451553352892 |
| Result | ✓ Passed |
| Advice | Nearside Rear Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i)) |
| Advice | Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| Advice | Nearside Rear Service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.2.2 (a) (i)) |

**MOT #12**

2021-07-13 16:03

MOT test number

657224104948

Result**✗ Failed****Fail** Nearside Front Service brake grabbing severely (1.2.1 (c))**Advice** Nearside Rear Service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.2.2 (a) (i))**Fail** Nearside Front Service brake grabbing severely (1.2.1 (c))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))**MOT #11**

2020-06-30 14:27

MOT test number

842663635744

Result**✓ Passed****MOT #10**

2020-06-29 09:30

MOT test number

591826346664

Result**✗ Failed****Fail** Offside Rear fog lamp not working (4.5.1 (a) (ii))**Advice** Tyre worn close to legal limit/worn on edge both front..... (5.2.3 (e))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #9**

2019-04-17 11:57

MOT test number

657387789646

Result**✓ Passed****Advice** Oil leak, but not excessive (8.4.1 (a) (i))



| | |
|------------------------|--|
| MOT #8 | 2018-04-18 07:58 |
| MOT test number | 928957031598 |
| Result | ✓ Passed |
| Advice | Offside Rear Brake pipe slightly corroded (3.6.B.2c) |

| | |
|------------------------|------------------|
| MOT #7 | 2017-05-19 10:08 |
| MOT test number | 370134647609 |
| Result | ✓ Passed |

| | |
|------------------------|--|
| MOT #6 | 2017-05-18 14:10 |
| MOT test number | 733671137316 |
| Result | ✗ Failed |
| Fail | Nearside Rear Registration plate lamp not working (1.1.C.1d) |
| Fail | Rear registration plate insecure (6.3.1b) |
| Advice | Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d) |
| Fail | Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2) |
| Fail | Central Rear Stop lamp not working (1.2.1b) |
| Fail | Offside Rear Direction indicator incorrect colour (1.4.A.2f) |
| Fail | Central Obligatory mirror missing (8.1.1) |
| Fail | Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2) |
| Fail | Offside Rear Stop lamp not working (1.2.1b) |

| | |
|------------------------|---|
| MOT #5 | 2015-12-09 10:03 |
| MOT test number | 460346282258 |
| Result | ✓ Passed |
| Advice | Nearside Rear Brake pipe slightly corroded across axle (3.6.B.2c) |
| Advice | Front Brake pipe slightly corroded to rear (3.6.B.2c) |

**MOT #4** 2014-12-08 11:21**MOT test number** 999252244356**Result** ✓ Passed**MOT #3** 2013-12-10 11:37**MOT test number** 219664843373**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #2** 2012-12-13 16:34**MOT test number** 436408542480**Result** ✓ Passed**MOT #1** 2012-12-13 12:01**MOT test number** 867078342306**Result** ✗ Failed**Fail** Rear brake application uneven (3.7.B.2)**Notice** Oil leak**Fail** Brakes imbalanced across an axle (3.7.B.5b)



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,299 |
| Auction value | £ 19,299 |
| Average private trade value | £ 19,299 |

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this FORD had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | |
| Plate since | 2024-03-28 |
| Current registration | |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 17 |
| First mileage registration | 2009-12-30 |
| Last registration | 2023-07-13 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2009-12-30 | 12 mi |
| Registration #2 | 2012-12-13 | 37.854 mi |
| Registration #3 | 2012-12-13 | 37.854 mi |
| Registration #4 | 2013-12-10 | 47.709 mi |
| Registration #5 | 2014-12-08 | 55.175 mi |
| Registration #6 | 2015-12-09 | 60.795 mi |
| Registration #7 | 2017-05-18 | 66.761 mi |
| Registration #8 | 2017-05-19 | 66.762 mi |
| Registration #9 | 2018-04-18 | 72.083 mi |
| Registration #10 | 2019-05-20 | 75.277 mi |
| Registration #11 | 2019-05-20 | 75.277 mi |
| Registration #12 | 2019-05-20 | 75.277 mi |
| Registration #13 | 2019-05-20 | 75.277 mi |
| Registration #14 | 2019-05-20 | 75.277 mi |
| Registration #15 | 2019-05-20 | 75.277 mi |
| Registration #16 | 2019-05-20 | 75.277 mi |
| Registration #17 | 2019-05-20 | 75.277 mi |

More info >



Car features

The FORD factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1963 mm |
| Height | 1543 mm |
| Length | 4013 mm |
| Wheel base | 2485 mm |
| Kerb weight | 1162 kg |
| Max. allowed weight | 1640 kg |

Additional information

| | |
|-----------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |

| | |
|---------------|---------|
| Engine number | 9R24266 |
|---------------|---------|