



report date: 2024-03-29

General information

Make	FORD
Model	S-MAX TITANIUM TDCI
Colour	Silver
Year of manufacture	2009
Top speed	112 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	52.3 mpg
Consumption combined	44.1 mpg
CO2 emission	169 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-07-04
Pictures	7
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-04-14
MOT pass rate	93 %
MOT passed	13
Failed MOT tests	1
Total advice items	48
Total items failed	5

MOT #14	2024-03-30 16:20
MOT test number	378613305655
Result	✓ Passed
Next expiry date	2025-04-14
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

MOT #13	2023-04-11 11:29
MOT test number	369048243959
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Central Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Rear Shock absorbers has a reduced damping effect (5.3.2 (d))

MOT #12	2022-04-12 11:38
MOT test number	896169960325
Result	✓ Passed

**MOT #11**

2021-03-31 08:41

MOT test number

472816121635

Result

✓ Passed

- Advice** Rear Shock absorbers light misting of oil or has limited damping effect Both sides (5.3.2 (b))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both sides (1.1.14 (a) (ii))
- Advice** Rear Coil spring corroded Both sides (5.3.1 (b) (i))
- Advice** Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users (8.2.2.2 (c))

MOT #10

2020-03-21 09:41

MOT test number

143748823631

Result

✓ Passed

- Advice** Rear Shock absorbers light misting of oil or has limited damping effect Both. (5.3.2 (b))
- Advice** Rear exhaust heavily corroded.
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Both. (1.1.14 (a) (ii))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Front wipers smear the screen.
- Advice** Rear Tyre worn close to legal limit/worn on edge Both sides. (5.2.3 (e))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #9** 2019-03-26 12:10**MOT test number** 831460601740**Result** ✓ Passed

Advice Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Front bushes both sides (5.3.4 (a) (i))

Advice Front Wipers smearing

Advice Rear Shock absorbers light misting of oil or has limited damping effect both sides (5.3.2 (b))

MOT #8 2018-04-11 08:52**MOT test number** 689377472009**Result** ✓ Passed

Advice Offside Rear Shock absorber has slight corrosion to the casing (2.7.2a)

Advice Child Seat fitted not allowing full inspection of adult belt Nearside and offside rear.

Advice Offside Rear coil spring corroded (2.4.C.1b)

Advice Front shocks weak.

Advice Offside Rear Shock absorber has a light misting of oil (2.7.3)

Advice Nearside Rear coil spring corroded (2.4.C.1b)

Advice Nearside Front Shock absorber has a light misting of oil (2.7.3)

**MOT #7**

2018-04-10 11:43

MOT test number

850499760297

Result

✗ Failed

- Fail** Offside Rear Trailing arm has excessive play in a pin/bush (2.4.G.2)
- Fail** Offside Registration plate lamp not working (1.1.C.1d)
- Fail** Nearside Rear Outer Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** Nearside Rear coil spring corroded (2.4.C.1b)
- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Offside Rear Shock absorber has slight corrosion to the casing (2.7.2a)
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Fail** Nearside Headlamp not working on dipped beam (1.7.5a)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear coil spring corroded (2.4.C.1b)
- Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)
- Advice** Front shocks weak.
- Advice** Child Seat fitted not allowing full inspection of adult belt Nearside and offside rear.

MOT #6

2017-04-15 10:13

MOT test number

600687213517

Result

✓ Passed

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2016-03-23 10:20**MOT test number** 743699157063**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2015-03-23 10:04**MOT test number** 536982485080**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #3** 2014-03-27 09:40**MOT test number** 409586284017**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2013-03-22 10:11**MOT test number** 927551983078**Result** ✓ Passed**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2012-03-29 14:14**MOT test number** 127209382055**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
14 April 2025

Tax status	Valid until 1 November
Days left	186
MOT expiry date	14 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-03-28
Last registration	2024-03-30
Complete history	See info



Registration #1	2009-03-28	18 mi
Registration #2	2012-03-29	23.920 mi
Registration #3	2013-03-22	30.106 mi
Registration #4	2014-03-27	39.225 mi
Registration #5	2015-03-23	46.511 mi
Registration #6	2016-03-23	54.225 mi
Registration #7	2017-04-15	62.611 mi
Registration #8	2018-04-10	73.380 mi
Registration #9	2019-05-20	85.277 mi
Registration #10	2020-05-20	95.277 mi
Registration #11	2021-05-20	105.277 mi
Registration #12	2022-05-20	115.277 mi
Registration #13	2023-05-20	125.277 mi
Registration #14	2024-05-20	135.277 mi
Registration #15	2025-05-20	145.277 mi
Registration #16	2026-05-20	155.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1842 mm
Height	1677 mm
Length	4443 mm
Kerb weight	1613 kg
Max. allowed weight	2130 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

9R89811