



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TOUAREG V6 TDI
Colour	Black
Year of manufacture	-
Top speed	125 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	221 BHP
Max. torque	500 Nm at 1.750 rpm
Cylinders	6
Fuel type	Diesel
Consumption city	19.9 mpg
Consumption extra urban	33.6 mpg
Consumption combined	26.9 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-15
Pictures	30
Listing price	View report



source: autotrader.co.uk



MOT history

MOT #16 2021-01-20 13:11

MOT test number 371638878386

Result ✓ Passed

Next expiry date 2022-01-19

Advice Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Nail in tyre

**MOT #15**

2021-01-04 14:10

MOT test number

553019367843

Result**✗ Failed**

MAJOR Nearside Front Seat belt anchorage prescribed area strength or continuity significantly reduced inner sill (7.1.1 (a) (i))

MAJOR Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MAJOR Rear Direction indicator incorrect colour both sides (4.4.3 (a))

MAJOR Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Nearside Rear Nail in tyre

MAJOR Offside Front Seat belt anchorage prescribed area strength or continuity significantly reduced inner sill (7.1.1 (a) (i))

Advice Rear Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security under side (6.2.2 (d) (i))

Advice Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MAJOR Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))

Advice Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR Central Rear Seat belt missing seat belt stuck (7.1.2 (a))

MOT #14

2019-07-10 15:23

MOT test number

475405817227

Result**✓ Passed**

Advice Front Brake hose slightly deteriorated both sides (1.1.12 (b) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Anti-roll bar pin or bush worn but not resulting in excessive movement D-bushes (5.3.4 (a) (i))

**MOT #13**

2019-07-05 12:48

MOT test number

557173359874

Result**✗ Failed**

Advice Front Anti-roll bar pin or bush worn but not resulting in excessive movement D-bushes (5.3.4 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR Parking brake lever defective so that it cannot be satisfactorily operated Release mechanism defective . (1.1.6 (d))

MAJOR Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

MAJOR Nearside Front Upper Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MAJOR Parking brake efficiency below requirements (1.4.2 (a) (i))

Advice Front Brake hose slightly deteriorated both sides (1.1.12 (b) (ii))

MAJOR Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #12

2018-07-11 10:13

MOT test number

786605100133

Result**✓ Passed**

Advice Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

Minor Offside Front Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

**MOT #11** 2018-07-07 13:36**MOT test number** 411589812791**Result** ✗ Failed**MAJOR** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**DANGEROUS** Rear Tyre tread depth below requirements of 1.6mm both sides (5.2.3 (e))**MAJOR** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**DANGEROUS** Rear Tyre tread depth below requirements of 1.6mm both (5.2.3 (e))**Minor** Offside Front Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))**MAJOR** Windscreen washer provides insufficient washer liquid (3.5 (a))**DANGEROUS** Front Brake disc in such a condition that it is seriously weakened both (1.1.14 (a) (ii))**MAJOR** Nearside Front Brake pad(s) wear indicator illuminated (1.1.13 (a) (i))**DANGEROUS** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**MOT #10** 2017-02-27 20:32**MOT test number** 128982795306**Result** ✓ Passed**MOT #9** 2017-02-27 20:32**MOT test number** 986330463200**Result** ✗ Failed**Pass with rectification** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Pass with rectification** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Pass with rectification** Nearside Front Headlamp not working on dipped beam (1.7.5a)



MOT #8	2015-12-16 13:45
MOT test number	506012969424
Result	✓ Passed
Advice	Nearside Front Outer sidewall has damage

MOT #7	2015-12-15 14:50
MOT test number	647299435858
Result	✗ Failed
Advice	Nearside Front Outer sidewall has damage
Fail	Offside Front coil spring broken (2.4.C.1a)
Fail	Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
Fail	Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

MOT #6	2015-10-28 10:02
MOT test number	543202515524
Result	✗ Failed
Fail	Offside Rear Tyre has ply or cords exposed (4.1.D.1b)
Fail	Nearside front brake binding (3.7.B.1)
Fail	Nearside Headlamp insecure (1.7.3)
Advice	Offside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)
Fail	Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)
Advice	Oil leak
Fail	Parking brake is not capable of being maintained in operation by direct mechanical action only (3.1.2)
Fail	Nearside Headlamp aim too high (1.8)
Fail	Offside Headlamp insecure (1.7.3)
Fail	Offside Front coil spring broken (2.4.C.1a)



MOT #5	2014-12-02 15:47
MOT test number	626016934397
Result	✓ Passed
Notice	Both front wipers smearing the screen
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #4	2014-12-02 15:47
MOT test number	956036834338
Result	✗ Failed
Pass with rectification	Nearside Front position lamp(s) not working (1.1.A.3b)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Pass with rectification	Offside Headlamp not working on dipped beam (1.7.5a)
Notice	Both front wipers smearing the screen

MOT #3	2013-07-10 12:24
MOT test number	605531393184
Result	✓ Passed
Advice	Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.C.1b)
Notice	EM light on



MOT #2	2012-07-30 11:15
MOT test number	765472212277
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.C.1b)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Notice	Child seat fitted not allowing full inspection of adult belt
Advice	Centre Rear Seat belt damaged but not affecting the operation of the belt (5.2.2a)

MOT #1	2011-08-08 09:47
MOT test number	285620521210
Result	✓ Passed
Notice	Child seat fitted not allowing full inspection of adult belt



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 YX11X
Plate since	2019-01-01
Current registration	 YX11X
Plate since	2019-01-01

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-04-10
Last registration	2021-01-20
Complete history	See info



Registration #1	2008-04-10	9 mi
Registration #2	2011-08-08	33.925 mi
Registration #3	2012-07-30	47.234 mi
Registration #4	2013-07-10	61.510 mi
Registration #5	2014-12-02	74.248 mi
Registration #6	2015-10-28	80.004 mi
Registration #7	2015-12-15	80.007 mi
Registration #8	2015-12-16	80.008 mi
Registration #9	2017-02-27	95.481 mi
Registration #10	2017-02-27	95.481 mi
Registration #11	2017-02-27	95.481 mi
Registration #12	2017-02-27	95.481 mi
Registration #13	2017-02-27	95.481 mi
Registration #14	2017-02-27	95.481 mi
Registration #15	2017-02-27	95.481 mi
Registration #16	2017-02-27	95.481 mi
Registration #17	2017-02-27	95.481 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1928 mm
Height	1726 mm
Length	4754 mm
Wheel base	2855 mm
Max. allowed weight	2945 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles

2

Engine number

BKS 081949