





#### General information

Make	FIAT
Model	500X POP
Colour	White
Year of manufacture	2016
Top speed	112 mph
0 - 60 mph	11.5 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	110 BHP	
Max. torque	152 Nm at 4.500 rpm	
Engine capacity	1.598 cc	
Cylinders	4	
Fuel type	Petrol	
Consumption city	32.5 mpg	
Consumption extra urban	56.5 mpg	
Consumption combined	44.1 mpg	
CO2 emission	147 g/km	
CO2 label	F	





## Internet history

Entry	1
Date	


Pictures

2021-07-22

12

Listing price

View report



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-07-23
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	12
Total items failed	4

MOT #7	2023-07-24 09:35
MOT test number	812319858227
Result	✓ Passed
Next expiry date	2024-07-23
Advice Sill trims fitted	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Under trays fitted	

МОТ #6	2023-07-21 09:10	
MOT test number	556190614058	
Result	🗙 Failed	
Advice Sill trims fitted		
<b>Fail</b> Nearside Track rod end ball joint dust cover excessively damaged or deteriorated s prevents the ingress of dirt (2.1.3 (g) (ii))	so that it no longer	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))		
<b>Fail</b> Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))		
Advice Under trays fitted		
<b>Fail</b> Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords on outer sidewall (5.2.3 (d) (i))		
Minor Offside Track rod end ball joint dust cover damaged or deteriorated, but prevent dirt (2.1.3 (g) (i))	ting the ingress of	





MOT #5	2022-07-21 15:48
MOT test number	694915442495
Result	✓ Passed
Advice Nearside Front Suspension arm pin or bush worn but not rest (a) (i))	ulting in excessive movement (5.3.4
Advice Offside Front Suspension arm pin or bush worn but not result (i))	ting in excessive movement (5.3.4 (a)

MOT #4	2022-07-21 14:51
MOT test number	521533342930
Result	🗙 Failed
Advice Nearside Front Suspension arm pin or bush worn but not resulting in e (a) (i))	xcessive movement (5.3.4
FailNearside Front Position lamp not working (4.2.1 (a) (ii))	
Advice Offside Front Suspension arm pin or bush worn but not resulting in exercise (i))	cessive movement (5.3.4 (a)

MOT #3	2021-07-20 09:03
MOT test number	642815459750
Result	Passed
Advice Sill trims fitted	
MOT #2	2020-09-04 07:30
MOT test number	639815421935
Result	✓ Passed
MOT #1	2019-06-24 15:57
MOT test number	744300175906

Result

✓ Passed



Tax & MOT check

Taxed Tax due: 1 February 2025	MOT Expires: 23 July 2024
Tax status	Valid until 1 February
Days left	278
MOT expiry date	23 July 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-





#### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Dumage 2	E E E E
Date	J.
Category	amer
Туре	

#### Extra FIAT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





#### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info  $\rightarrow$ 





### Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second s	
***********	
********	
*******	
***********	
********	
	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	
	More info >





#### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info  $\rightarrow$ 





## Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-06-29
Last registration	2023-07-24
Complete history	See info



Registration #1	2016-06-29	6 mi
Registration #2	2019-06-24	22.614 mi
Registration #3	2020-09-04	27.402 mi
Registration #4	2021-07-20	30.496 mi
Registration #5		11.117 esi
Registration #6		11.117 esi
Registration #7		11.777 esi
Registration #8		11.117 esi
Registration #9		11.777 esi

More info >





## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
\$0566	
\$0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	86%
Children	85%
Pedestrian	74%
Safety systems	64%
Overall rating	79%
Video	see crash video



Dimensions & weight	
Width	1796 mm
Height	1600 mm
Length	4248 mm
Wheel base	2570 mm
Kerb weight	1275 kg
Max. allowed weight	1875 kg
Additional information	
Fuel tank capacity	48
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles	2
Engine number	3035798