



R059FSK

report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	GOLF SE TDI
Colour	Black
Year of manufacture	-
Top speed	118 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	250 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	47.1 mpg
Consumption extra urban	76.4 mpg
Consumption combined	62.8 mpg



**MOT history**

MOT #14	2020-12-02 15:26
MOT test number	347115365359
Result	✓ Passed
Next expiry date	2021-12-01

MOT #13	2020-11-30 12:00
MOT test number	753168566715
Result	✗ Failed
<div><div>Fail</div> Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))</div> <div><div>Fail</div> Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))</div> <div><div>Advice</div> Offside Front tyre worn on inside</div> <div><div>Fail</div> Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))</div> <div><div>Advice</div> Nearside Front tyre worn on outside</div>	

MOT #12	2019-05-22 16:33
MOT test number	253463506802
Result	✓ Passed
<div><div>Advice</div> Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))</div>	

MOT #11	2019-05-21 17:17
MOT test number	215397311585
Result	✗ Failed
<div><div>Fail</div> Nearside Front Windscreen washer provides insufficient washer liquid (3.5 (a))</div> <div><div>Fail</div> Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))</div> <div><div>Fail</div> Offside Front Windscreen washer provides insufficient washer liquid (3.5 (a))</div> <div><div>Advice</div> Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))</div>	

**MOT #10** 2018-05-25 11:49**MOT test number** 333401386816**Result** ✓ Passed**MOT #9** 2018-05-25 09:28**MOT test number** 877371444186**Result** ✗ Failed**Fail** Offside Rear Direction indicator not working (4.4.1 (a) (ii))**MOT #8** 2017-05-30 11:35**MOT test number** 464935389733**Result** ✓ Passed**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #7** 2017-05-30 09:44**MOT test number** 617596681124**Result** ✗ Failed**Fail** Offside Stop lamp not working (1.2.1b)**Fail** Offside Rear Shock absorber has a serious fluid leak (2.7.3)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Offside Rear position lamp(s) not working (1.1.A.3b)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)

**MOT #6** 2016-05-28 08:06**MOT test number** 676196923571**Result** ✓ Passed**Advice** Front tyres low on tread**MOT #5** 2015-05-18 16:39**MOT test number** 788478335139**Result** ✓ Passed**MOT #4** 2014-05-23 10:20**MOT test number** 506723244180**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Under-trays fitted obscuring some underside components**Notice** Nail in offside rear tyre**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #3** 2013-05-23 12:45**MOT test number** 699553943164**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2013-05-23 10:35
MOT test number	945883043147
Result	✗ Failed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Fail	Offside Front Tyre has ply or cords exposed (4.1.D.1b)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2012-05-17 11:19
MOT test number	638418832131
Result	✓ Passed



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 RO59FSK
Plate since	2019-03-29
Current registration	 RO59FSK
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-09-14
Last registration	2020-12-02
Complete history	See info



Registration #1	2009-09-14	25 mi
Registration #2	2012-05-17	36.493 mi
Registration #3	2013-05-23	46.088 mi
Registration #4	2013-05-23	46.091 mi
Registration #5	2014-05-23	59.285 mi
Registration #6	2015-05-18	69.781 mi
Registration #7	2016-05-28	81.146 mi
Registration #8	2017-05-30	94.967 mi
Registration #9	2018-05-30	108.788 mi
Registration #10	2019-05-30	122.609 mi
Registration #11	2020-05-30	136.430 mi
Registration #12	2021-05-30	150.251 mi
Registration #13	2022-05-30	164.072 mi
Registration #14	2023-05-30	177.893 mi
Registration #15	2024-05-30	191.714 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1786 mm
Height	1479 mm
Length	4199 mm
Wheel base	2578 mm
Kerb weight	1266 kg
Max. allowed weight	1840 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	CBD 326058