





report date: 2024-01-16

General information

Make	VOLKSWAGEN
Model	TRANSPORTER T28 TDI P/V STARTLINE BMT
Colour	White
Year of manufacture	2016
Top speed	91 mph
0 - 100 km/h	15.4 seconds
0 - 60 mph	19.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 kW / 102 HP / 83 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.968 сс
Cylinders	4
Fuel type	Diesel
Consumption city	34.0 mpg
Consumption extra urban	48.7 mpg
Consumption combined	42.2 mpg
CO2 emission	176 g/km
CO2 label	1



CarCheck.co.uk page 1/11



report date: 2024-01-16

Internet history

Entry 1

Date 2021-10-10

Pictures 19

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-01-16

MOT history

MOT expiry date	2025-02-15
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	9
Total items failed	2

MOT #7	2024-02-08 16:01
MOT test number	141911722752
Result	✓ Passed
Next expiry date	2025-02-15
Advice Nearside Front Lower Suspension arm pin or bush worn but not result (5.3.4 (a) (i)) Advice Offside Front Lower Suspension arm pin or bush worn but not resulting (5.3.4 (a) (i))	-

MOT #6	2024-02-08 11:49
MOT test number	169028121491
Result	X Failed
Fail Electronic stability control warning lamp indicates a fault (7.12 (e))	
Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	
Fail Anti-lock braking system warning lamp indicates an ABS fault (1.6 (kg)	0))
Advice Nearside Front Lower Suspension arm pin or bush worn but not re (5.3.4 (a) (i))	esulting in excessive movement

MOT #5	2023-02-09 09:38
MOT test number	473752470001
Result	✓ Passed

CarCheck.co.uk page 3/11

Advice (i))

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)

Advice

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4

(a) (i))



report date: 2024-01-16

MOT #4 2022-02-16 09:55

MOT test number 175456143299

MOT #3 2021-05-26 11:48

MOT test number 519412609445

Result Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Low emissions no readings recorded

Advice Nearside Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2 2020-05-29 11:12

MOT test number 710386637047

MOT #1 2019-05-31 10:55

MOT test number 594174393045

CarCheck.co.uk page 4/11



report date: 2024-01-16

Tax & MOT check



Tax status	Valid until 1 February
Days left	329
MOT expiry date	15 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 5/11



report date: 2024-01-16

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1


Date	
Category	
Туре	
Damage 2	

Damage 2

Category

Type

Date



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-01-16

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-01-16

More info >

Owner history

, <u> </u>	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	UK UK
Flate since	
Current registration	NK SIN
Plate since	

CarCheck.co.uk page 8/11



report date: 2024-01-16

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >


CarCheck.co.uk page 9/11



report date: 2024-01-16

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-06-03
Last registration	2024-02-08
Complete history	See info



Registration #1	2016-06-03	27 mi
Registration #2	2019-05-31	27.932 mi
Registration #3	2020-05-29	32.532 mi
Registration #4	2021-05-26	35.872 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-01-16

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	79%
Children	74%
Pedestrian	32%
Safety systems	57%
Overall rating	66%
Video	see crash video



Dimensions & weight

Width	2283 mm
Height	1990 mm
Length	4892 mm
Wheel base	3400 mm
Kerb weight	1855 kg
Max. allowed weight	2800 kg

Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	5
CarChack co.uk	pago 11/11

CarCheck.co.uk page 11/11

Number of seats	3
Number of axles	2
Engine number	CAAA938089