



report date: 2024-03-28

General information

|                     |                         |
|---------------------|-------------------------|
| Make                | KIA                     |
| Model               | CEED CRDI 2 ECODYNAMICS |
| Colour              | Blue                    |
| Year of manufacture | 2012                    |
| Top speed           | 106 mph                 |
| 0 - 60 mph          | 13.5 seconds            |
| Gearbox             | 6 speed Manual          |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 89 BHP              |
| Max. torque             | 235 Nm at 2.500 rpm |
| Engine capacity         | 1.582 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 64.2 mpg            |
| Consumption extra urban | 78.5 mpg            |
| Consumption combined    | 72.4 mpg            |
| CO2 emission            | 103 g/km            |
| CO2 label               | B                   |






Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-01-31                  |
| Pictures      | 10                          |
| Listing price | <a href="#">View report</a> |



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2025-04-12 |
| MOT pass rate      | 59 %       |
| MOT passed         | 10         |
| Failed MOT tests   | 7          |
| Total advice items | 28         |
| Total items failed | 17         |

|                  |  |
|------------------|--|
| MOT #17          | 2024-04-13 07:29   |
| MOT test number  | 253022010706   |
| Result           | ✓ Passed   |
| Next expiry date | 2025-04-12   |
| Advice           | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |
| Advice           | Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))         |
| Advice           | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))       |
| Advice           | Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))        |
| Advice           | Front Brake pad(s) wearing thin (1.1.13 (a) (ii))                          |

**MOT #16** 2024-03-15 11:22**MOT test number** 491059672711**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Emissions unable to be completed Due to engine condition (8.2.2.2 (e))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**MOT #15** 2023-03-23 15:50**MOT test number** 315559098939**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #14** 2023-03-17 11:37**MOT test number** 224000535845**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

**MOT #13**

2022-03-17 15:00

**MOT test number**

477862101622

**Result**

✓ Passed

**Advice**

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4

(a) (i))

**Minor**

Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1

(b) (i))

**Advice**

Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))

**MOT #12**

2022-03-17 10:09

**MOT test number**

204201810242

**Result**

✗ Failed

**Minor**

Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1

(b) (i))

**Advice**

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4

(a) (i))

**Fail**

Windscreen washer provides insufficient washer liquid (3.5 (a))

**Advice**

Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))

**MOT #11**

2021-03-22 17:32

**MOT test number**

276976842982

**Result**

✓ Passed

**MOT #10**

2021-03-19 15:27

**MOT test number**

748394305645

**Result**

✗ Failed

**Fail**

Nearside Rear Parking brake inoperative on one side (1.4.1 (a))

**Fail**

Parking brake efficiency below requirements (1.4.2 (a) (i))

**Fail**

Rear Service brake excessively fluctuating (1.2.1 (e))

**Fail**

Offside Rear Service brake excessively binding (1.2.1 (f))

**MOT #9** 2020-01-10 15:52**MOT test number** 649524562984**Result** ✓ Passed**MOT #8** 2020-01-10 11:34**MOT test number** 674147482690**Result** ✗ Failed**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #7** 2019-01-19 14:15**MOT test number** 823436641793**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge PERISHED (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge PERISHED (5.2.3 (e))**MOT #6** 2019-01-19 12:06**MOT test number** 786576890105**Result** ✗ Failed**Fail** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Fail** Offside Front Inner Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge PERISHED (5.2.3 (e))**Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Fail** Front Brakes imbalanced across an axle (1.2.1 (b) (i))**Fail** Offside Front Service brake excessively binding (1.2.1 (f))**Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge PERISHED (5.2.3 (e))

**MOT #5** 2019-01-19 11:58**MOT test number** 793680036538**Result** ✓ Passed**MOT #4** 2017-03-16 16:32**MOT test number** 116272061598**Result** ✓ Passed**Advice** Both rear tyres treads split and seperating.(oe) 205/55/16**Advice** Nearside Front Tyre tread split and seperating.(oe) Also balding on inner and starting to twist.  
205/55/16**MOT #3** 2017-03-16 09:33**MOT test number** 173774837700**Result** ✗ Failed**Fail** Offside Front Tyre has a tear, caused by separation or partial failure of its structure Tread seperation, splitting and twisted. Bald on inner.205/55/16 (4.1.D.1b)**Fail** Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement Wishbone front bush. (2.4.G.2)**Advice** Both rear tyres treads split and seperating.(oe) 205/55/16**Fail** Offside Front Inner Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Nearside Front Tyre tread split and seperating.(oe) Also balding on inner and starting to twist.  
205/55/16**MOT #2** 2016-03-18 13:11**MOT test number** 454945243712**Result** ✓ Passed**MOT #1** 2015-03-26 11:35**MOT test number** 395605585062**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
12 April 2025

|                         |                                 |
|-------------------------|---------------------------------|
| <b>Tax status</b>       | Valid until 1 August            |
| <b>Days left</b>        | 95                              |
| <b>MOT expiry date</b>  | 12 April 2025                   |
| <b>Full MOT history</b> | <a href="#">See MOT history</a> |

Tax calculation

|  |                |
|--|----------------|
| <b>Vehicle class</b>                           | 49             |
| <b>Band</b>                                    | B              |
| <b>Single payment (12 months)</b>              | £ 20,00,-      |
| <b>Single six month payment</b>                | Not applicable |
| <b>Total payable by 12 monthly instalments</b> | £ 21,00,-      |





Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |       |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this KIA had different number plates.

|                      |            |
|----------------------|------------|
| Number of plates     | 1          |
| Current registration | *****      |
| Plate since          | 2019-09-29 |
| Current registration | *****      |
| Plate since          | 2019-09-29 |

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

|                   |          |      |
|-------------------|----------|------|
| Finance company   | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type    | XXXXXXXX | XXXX |
| Agreement term    | XXXXXXXX | XXXX |
| Agreement number  | XXXXXXXX | XXXX |
| Contact info      | XXXXXXXX | XXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 19                       |
| First mileage registration | 2012-03-29               |
| Last registration          | 2024-04-13               |
| Complete history           | <a href="#">See info</a> |



|                  |            |           |
|------------------|------------|-----------|
| Registration #1  | 2012-03-29 | 22 mi     |
| Registration #2  | 2015-03-26 | 24.927 mi |
| Registration #3  | 2016-03-18 | 32.305 mi |
| Registration #4  | 2017-03-16 | 39.478 mi |
| Registration #5  | 2017-03-16 | 39.478 mi |
| Registration #6  | 2019-01-19 | 53.269 mi |
| Registration #7  | 2019-01-19 | 53.269 mi |
| Registration #8  | 2019-01-19 | 53.269 mi |
| Registration #9  | 2020-01-10 | 60.042 mi |
| Registration #10 | 2020-01-10 | 60.042 mi |
| Registration #11 | 2020-01-10 | 60.042 mi |
| Registration #12 | 2020-01-10 | 60.042 mi |
| Registration #13 | 2020-01-10 | 60.042 mi |
| Registration #14 | 2020-01-10 | 60.042 mi |
| Registration #15 | 2020-01-10 | 60.042 mi |
| Registration #16 | 2020-01-10 | 60.042 mi |
| Registration #17 | 2020-01-10 | 60.042 mi |
| Registration #18 | 2020-01-10 | 60.042 mi |
| Registration #19 | 2020-01-10 | 60.042 mi |

More info >



Car features

The KIA factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1790 mm |
| Height              | 1480 mm |
| Length              | 4260 mm |
| Wheel base          | 2650 mm |
| Kerb weight         | 1468 kg |
| Max. allowed weight | 1780 kg |

Additional information

|                 |                  |
|-----------------|------------------|
| Fuel delivery   | Direct Injection |
| Number of doors | 5                |
| Number of seats | 5                |
| Number of axles | 2                |

|               |              |
|---------------|--------------|
| Engine number | D4FBCZ384825 |
|---------------|--------------|