




report date: 2024-03-28

General information

Make	SMART
Model	FORTWO COUPE PASSION MHD
Colour	White
Year of manufacture	2010
Top speed	90 mph
0 - 100 km/h	13.7 seconds
0 - 60 mph	13.7 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	52 kW / 71 HP / 71 BHP
Max. torque	92 Nm at 2.800 rpm
Engine capacity	999 cc
Cylinders	3
Fuel type	Petrol
Consumption city	61.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	65.7 mpg
CO2 emission	98 g/km
CO2 label	A





Internet history

Entry 2

Date	2021-02-04
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)

Entry 1

Date	2021-01-21
Pictures	11
Listing price	View report



source: [yesauto.com](#)



MOT history

MOT expiry date	2025-03-16
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	23
Total items failed	9
MOT #16	2024-03-12 09:16
MOT test number	390657385938
Result	✓ Passed
Next expiry date	2025-03-16
MOT #15	2023-03-09 08:50
MOT test number	202825164420
Result	✓ Passed
MOT #14	2022-03-08 08:46
MOT test number	976821017395
Result	✓ Passed
MOT #13	2021-03-17 10:00
MOT test number	584482656350
Result	✓ Passed
MOT #12	2020-09-03 14:39
MOT test number	204321992950
Result	✓ Passed

**MOT #11** 2019-10-17 16:23**MOT test number** 367291057897**Result** ✓ Passed**Advice** Offside Front Tyre slightly damaged/cracking or perishing outer sidewall (5.2.3 (d) (ii))**MOT #10** 2019-10-16 15:23**MOT test number** 461807892261**Result** ✗ Failed**Fail** Rear Exhaust system insecure (6.1.2 (a))**Fail** Nearside Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Advice** Offside Front Tyre slightly damaged/cracking or perishing outer sidewall (5.2.3 (d) (ii))**MOT #9** 2018-12-11 11:01**MOT test number** 809181350706**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge heavily perished + 3mm (5.2.3 (e))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge heavily perished and 3mm (5.2.3 (e))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #8**

2018-12-10 10:04

MOT test number

238126618272

Result

✗ Failed

- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge heavily perished and 3mm (5.2.3 (e))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Nearside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge heavily perished + 3mm (5.2.3 (e))
- Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #7

2017-12-05 09:11

MOT test number

260463820162

Result

✓ Passed

- Advice** Nearside Front Suspension arm has slight play in a pin/bush (2.4.G.2)
- Advice** Nearside Rear Tyre has deterioration
- Advice** Offside Front Suspension arm has slight play in a pin/bush (2.4.G.2)
- Advice** Offside Front Tyre has slight damage to the outer sidewall

MOT #6

2016-11-28 15:05

MOT test number

920703228825

Result

✓ Passed

- Advice** Nearside rear tyre slightly deteriorated
- Advice** Offside front tyre has multiple cuts on outer sidewall not revealing the ply/cords.

**MOT #5** 2016-11-28 09:38**MOT test number** 501880269276**Result** ✗ Failed**Fail** Registration plate lamp not working (1.1.C.1d)**Advice** Nearside rear tyre slightly deteriorated**Advice** Offside front tyre has multiple cuts on outer sidewall not revealing the ply/cords.**Fail** Central Stop lamp not working (1.2.1b)**MOT #4** 2015-11-30 17:25**MOT test number** 444169831299**Result** ✓ Passed**Advice** Nearside Rear Tyre has slight deterioration on the outer sidewall**Advice** Offside Front Suspension arm has slight play in a pin/bush (2.4.G.2)**MOT #3** 2015-11-30 09:12**MOT test number** 405209291918**Result** ✗ Failed**Fail** Offside Rear Rear position lamp(s) not working (1.1.A.3b)**Advice** Nearside Rear Tyre has slight deterioration on the outer sidewall**Fail** Nearside Windscreen wiper does not clear the windscreen effectively Aero blade 23 (8.2.2)**Advice** Offside Front Suspension arm has slight play in a pin/bush (2.4.G.2)**MOT #2** 2014-11-19 11:44**MOT test number** 748533424318**Result** ✓ Passed



MOT #1	2013-12-11 09:44
MOT test number	899665143371
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
16 March 2025

Tax status	Valid until 1 June
Days left	34
MOT expiry date	16 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this SMART. See if, where and when this SMART had damage and the car repair costs. We also check if this SMART was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SMART salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SMART in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SMART? How many owners did this SMART have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this SMART had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-28
Current registration	
Plate since	2019-09-28

More info >



Finance check

Check if this SMART is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SMART has been settled.

If not, and you buy this SMART then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SMART is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-12-14
Last registration	2024-03-12
Complete history	See info



Registration #1	2010-12-14	8 mi
Registration #2	2013-12-11	26.834 mi
Registration #3	2014-11-19	29.042 mi
Registration #4	2015-11-30	29.173 mi
Registration #5	2015-11-30	29.173 mi
Registration #6	2016-11-28	31.830 mi
Registration #7	2016-11-28	31.830 mi
Registration #8	2017-12-05	33.913 mi
Registration #9	2018-12-10	36.664 mi
Registration #10	2018-12-11	36.665 mi
Registration #11	2019-03-20	36.665 mi
Registration #12	2019-03-20	36.665 mi
Registration #13	2019-03-20	36.665 mi
Registration #14	2019-03-20	36.665 mi
Registration #15	2019-03-20	36.665 mi
Registration #16	2019-03-20	36.665 mi
Registration #17	2019-03-20	36.665 mi
Registration #18	2019-03-20	36.665 mi
Registration #19	2019-03-20	36.665 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1559 mm
Height	1542 mm
Length	2695 mm
Wheel base	1867 mm
Kerb weight	725 kg
Max. allowed weight	1020 kg

Additional information

Fuel tank capacity	99 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	3B21CM3838