





report date: 2024-03-29

General information

| Make | VAUXHALL |
|---------------------|----------------|
| Model | AGILA SE |
| Colour | Silver |
| Year of manufacture | 2014 |
| Top speed | 109 mph |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 93 BHP |
|-------------------------|---------------------|
| Max. torque | 118 Nm at 4.800 rpm |
| Engine capacity | 1.242 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 46.3 mpg |
| Consumption extra urban | 62.8 mpg |
| Consumption combined | 55.4 mpg |
| CO2 emission | 118 g/km |
| CO2 label | С |



CarCheck.co.uk page 1/11



Internet history

Entry 2

Date 2021-10-02

Pictures 27

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

| Dat | te | 2021-09-30 |
|-----|----|------------|
| | | |

Pictures 27

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



VK64CEY

✓ Passed

report date: 2024-03-29

| MOT | history |
|--------|---|
| 101()1 | nisiorv |
| | ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,, |

Result

| MOT expiry date | 2024-08-22 |
|--------------------|------------|
| MOT pass rate | 100 % |
| MOT passed | 7 |
| Failed MOT tests | 0 |
| Total advice items | 1 |
| Total items failed | 0 |

| MOT #7 | 2023-08-23 15:56 |
|---|------------------|
| MOT test number | 763458488513 |
| Result | ✓ Passed |
| Next expiry date | 2024-08-22 |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #6 | 2022-08-04 07:28 |
|-----------------|------------------|
| MOT test number | 244486052368 |
| Result | ✓ Passed |
| | |
| MOT #5 | 2021-08-18 12:17 |
| MOT test number | 150277126803 |
| Result | ✓ Passed |
| | |
| MOT #4 | 2020-09-23 10:24 |
| MOT test number | 396202932684 |
| Result | ✓ Passed |
| | |
| MOT #3 | 2019-09-19 10:22 |
| MOT test number | 773601372208 |

CarCheck.co.uk page 3/11



| MOT #2 | 2018-09-26 11:40 |
|------------------------|----------------------------------|
| MOT test number | 274616387145 |
| Result | ✓ Passed |
| | |
| | |
| MOT #1 | 2017-09-13 11:02 |
| MOT #1 MOT test number | 2017-09-13 11:02 214603940597 |

CarCheck.co.uk page 4/11



Tax & MOT check



| Tax status | Valid until 1 October |
|------------------|-----------------------|
| Days left | 154 |
| MOT expiry date | 22 August 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|---|----------------|
| Band | С |
| Single payment (12 months) | £ 35,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 36,75,- |

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date

Category

Type

Damage 2

Date

Category

Type



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



VK64CEY

report date: 2024-03-29

| Owner history | |
|---|-------------|
| For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downlo here. | |
| ********* | |
| | |
| *************************************** | |
| ********* | |
| *************************************** | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this VAUXHALL had different number plates. | |
| Number of plates | |
| Current registration | OK SING |
| Plate since | |
| Current registration | UK NE |
| Plate since | |
| | Mana info |
| | More info > |
| | |
| | |

CarCheck.co.uk page 8/11



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| 0.1.116 | |

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 10 |
| First mileage registration | 2014-09-30 |
| Last registration | 2023-08-23 |
| Complete history | See info |



| Registration #1 | 2014-09-30 | 9 mi |
|---------------------------------|------------|----------------------------------|
| Registration #2 | 2017-09-13 | 11.781 mi |
| Registration #3 | 2018-09-26 | 14.194 mi |
| Registration #4 | 2019-09-19 | 16.693 mi |
| Registration #5 | 2020-09-23 | 17.862 mi |
| | | |
| Registration #6 | | 11.777 es |
| Registration #6 Registration #7 | | 11.777 es |
| | | 11.777 ea 11.777 ea |
| Registration #7 | | 11.77 mi 11.77 mi 11.77 mi |

More info >

CarCheck.co.uk page 10/11



Safety ratings

| NCAP rating | **** |
|-------------|-----------------|
| Video | see crash video |



Dimensions & weight

| Width | 1932 mm |
|---------------------|---------|
| Height | 1590 mm |
| Length | 3740 mm |
| Wheel base | 2360 mm |
| Kerb weight | 1045 kg |
| Max. allowed weight | 1485 kg |

Additional information

| Fuel tank capacity | 45 I |
|--------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | K12B - 1828353LUY |

CarCheck.co.uk page 11/11