



AU52PYV

report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	BORA
Colour	Blue
Year of manufacture	2002
Gearbox	-

Engine & fuel consumption

Engine capacity	1.896 cc
Fuel type	Diesel
CO2 emission	146 g/km
CO2 label	F








Internet history

Entry 1

Date	2021-08-08
Pictures	6
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2025-03-28
MOT pass rate	76 %
MOT passed	16
Failed MOT tests	5
Total advice items	31
Total items failed	11

MOT #21	2024-03-29 14:38
MOT test number	162161648863
Result	✓ Passed
Next expiry date	2025-03-28
Advice	Exhaust noisy (8.1.1 (a))
Advice	Oil leak, but not excessive getting near limit (8.4.1 (a) (i))
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #20	2024-03-29 10:49
MOT test number	540916330786
Result	✗ Failed
Advice	Exhaust noisy (8.1.1 (a))
Advice	Oil leak, but not excessive getting near limit (8.4.1 (a) (i))
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
MAJOR	Offside Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #19	2023-03-08 12:09
MOT test number	190900823323
Result	✓ Passed

**MOT #18** 2022-03-29 07:19**MOT test number** 853482261432**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #17** 2020-10-06 16:14**MOT test number** 888504844689**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #16** 2017-11-27 10:32**MOT test number** 408422156444**Result** ✓ Passed**MOT #15** 2016-09-20 08:01**MOT test number** 172302261754**Result** ✓ Passed**MOT #14** 2015-08-27 11:25**MOT test number** 266550046220**Result** ✓ Passed**Advice** Rear registration plate faded but not likely to be misread (6.3.1d)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #13** 2014-09-08 15:25**MOT test number** 415591954263**Result** ✓ Passed**Advice** Nearside Inner Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Notice** Slightly distorted pattern to n/s dip beam**Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #12** 2014-09-04 10:31**MOT test number** 969037444204**Result** ✗ Failed**Advice** Nearside Inner Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Fail** Nearside Outer Front Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2)**Notice** Slightly distorted pattern to n/s dip beam**MOT #11** 2013-09-04 08:45**MOT test number** 199337543246**Result** ✓ Passed

**MOT #10** 2013-08-29 12:26**MOT test number** 708301343212**Result** ✗ Failed**Fail** Nearside Rear brake disc in such a condition that it is seriously weakened (3.5.1i)**Notice** O/s/r tyre is low on tread**Fail** Nearside rear brake binding (3.7.B.1)**Fail** Offside Outer Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Notice** N/s/f outer cv gaiter is not fully secure**Fail** Offside Rear brake disc in such a condition that it is seriously weakened (3.5.1i)**Fail** Offside rear brake binding (3.7.B.1)**MOT #9** 2012-08-31 16:21**MOT test number** 217734542254**Result** ✓ Passed**Notice** Rear discs corroded**Notice** Child seat fitted not allowing full inspection of adult belt

**MOT #8** 2012-08-28 10:48**MOT test number** 397581542486**Result** ✗ Failed**Fail** Nearside Rear Shock absorber has negligible damping effect (2.7.5)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Rear discs corroded**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Child seat fitted not allowing full inspection of adult belt**Fail** Nearside Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**MOT #7** 2011-08-30 13:57**MOT test number** 967352941264**Result** ✓ Passed**MOT #6** 2010-09-08 12:40**MOT test number** 610051150236**Result** ✓ Passed**MOT #5** 2009-08-14 12:18**MOT test number** 641176929298**Result** ✓ Passed**MOT #4** 2008-09-27 07:58**MOT test number** 700291078262**Result** ✓ Passed



MOT #3	2007-09-25 10:32
MOT test number	843878767217
Result	✗ Failed
Notice	O/S/R brake disc discoloured.
Pass with rectification	Offside Headlamp aim too high (1.8)
Pass with rectification	Nearside Headlamp aim too high (1.8)

MOT #2	2007-09-25 10:32
MOT test number	393668567258
Result	✓ Passed
Notice	O/S/R brake disc discoloured.

MOT #1	2006-08-30 10:26
MOT test number	394852846261
Result	✓ Passed





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
28 March 2025

Tax status		Valid until 1 September
Days left		125
MOT expiry date		28 March 2025
Full MOT history		<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2002-09-27
Last registration	2024-03-29
Complete history	<a href="#">See info</a>



Registration #1	2002-09-27	6 mi
Registration #2	2006-08-30	30.552 mi
Registration #3	2007-09-25	36.543 mi
Registration #4	2008-09-27	40.900 mi
Registration #5	2009-08-14	44.735 mi
Registration #6	2010-09-08	45.121 mi
Registration #7	2011-08-30	51.785 mi
Registration #8	2012-08-28	58.400 mi
Registration #9	2012-08-31	58.427 mi
Registration #10	2013-08-29	66.270 mi
Registration #11	2013-09-04	66.330 mi
Registration #12	2013-09-04	66.330 mi
Registration #13	2013-09-04	66.330 mi
Registration #14	2013-09-04	66.330 mi
Registration #15	2013-09-04	66.330 mi
Registration #16	2013-09-04	66.330 mi
Registration #17	2013-09-04	66.330 mi
Registration #18	2013-09-04	66.330 mi
Registration #19	2013-09-04	66.330 mi
Registration #20	2013-09-04	66.330 mi
Registration #21	2013-09-04	66.330 mi
Registration #22	2013-09-04	66.330 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Additional information

Engine number NOT KNOWN