



report date: 2024-03-28

General information

Make	VAUXHALL
Model	ANTARA SE NAV CDTI
Colour	White
Year of manufacture	2013
Top speed	119 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	182 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	26.9 mpg
Consumption extra urban	44.1 mpg
Consumption combined	35.8 mpg
CO2 emission	208 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-06-28
Pictures	15
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-09
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	32
Total items failed	0

MOT #12	2023-07-07 10:07
MOT test number	263005428828
Result	✓ Passed
Next expiry date	2024-07-09
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11	2022-07-01 14:56
MOT test number	824956061595
Result	✓ Passed
Advice	Stop lamp, non obligatory lamp dim
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #10**

2022-07-01 07:23

MOT test number

228305828545

Result**✗ Failed**

- MAJOR** Reversing lamp inoperative (4.6.1 (a))
- MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Stop lamp, non obligatory lamp dim
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #9

2021-07-05 14:52

MOT test number

216702547044

Result**✓ Passed**

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Oil leak, but not excessive slight drip on floor (8.4.1 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #8

2021-07-02 14:18

MOT test number

707522455593

Result**✗ Failed**

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Oil leak, but not excessive slight drip on floor (8.4.1 (a) (i))
- MAJOR** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #7** 2020-07-10 10:09**MOT test number** 807799229933**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2.5 mm and heavily cracked and perished 235/55/18 (5.2.3 (e))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Front Tyre worn close to legal limit/worn on edge 2.5 mm and heavily cracked and perished (5.2.3 (e))**MOT #6** 2020-07-10 09:32**MOT test number** 634948641191**Result** ✗ Failed**MAJOR** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge 2.5 mm and heavily cracked and perished (5.2.3 (e))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MAJOR** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2.5 mm and heavily cracked and perished 235/55/18 (5.2.3 (e))**MOT #5** 2019-07-11 09:11**MOT test number** 870444403721**Result** ✓ Passed**MOT #4** 2018-06-14 09:54**MOT test number** 930573429503**Result** ✓ Passed**Advice** EMISSIONS TOO CLEAN**MOT #3** 2017-07-10 09:30**MOT test number** 358077837639**Result** ✓ Passed



MOT #2	2016-07-14 08:49
MOT test number	935874007410
Result	✓ Passed

MOT #1	2016-01-25 15:12
MOT test number	941355649392
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Advice	Front under tray fitted not allowing full inspection



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
9 July 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	9 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2020-01-01
Current registration	 XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-03-01
Last registration	2023-07-07
Complete history	See info



Registration #1	2013-03-01	16 mi
Registration #2	2016-01-25	37.096 mi
Registration #3	2016-07-14	43.348 mi
Registration #4	2017-07-10	49.463 mi
Registration #5	2018-06-14	54.036 mi
Registration #6	2019-07-11	64.134 mi
Registration #7	2020-07-10	71.286 mi
Registration #8	2021-06-29	75.277 mi
Registration #9	2022-06-29	75.277 mi
Registration #10	2023-06-29	75.277 mi
Registration #11	2023-06-29	75.277 mi
Registration #12	2023-06-29	75.277 mi
Registration #13	2023-06-29	75.277 mi
Registration #14	2023-06-29	75.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2085 mm
Height	1717 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1921 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	227236K