



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	BEETLE T
Colour	Silver
Year of manufacture	2002
Top speed	126 mph
0 - 60 mph	9.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	150 BHP
Max. torque	298 Nm at 2.000 rpm
Engine capacity	1.781 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.4 mpg
Consumption extra urban	43.5 mpg
Consumption combined	34.4 mpg
CO2 emission	194 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-10-06
Pictures	3
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2022-12-08
MOT pass rate	80 %
MOT passed	16
Failed MOT tests	4
Total advice items	43
Total items failed	8

MOT #20	2021-12-09 12:18
MOT test number	794558321987
Result	✓ Passed
Next expiry date	2022-12-08

MOT #19	2020-10-16 11:20
MOT test number	719392104349
Result	✓ Passed

MOT #18	2019-07-10 12:21
MOT test number	749634990478
Result	✓ Passed

MOT #17	2018-07-23 14:19
MOT test number	499429722888
Result	✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive inner sill (5.3.6 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #16	2017-07-25 08:45
MOT test number	164142301064
Result	✓ Passed
Advice	O/s steering rack gaiter twisted

MOT #15	2016-07-26 14:56
MOT test number	202963173021
Result	✓ Passed
Advice	Centre exhaust mount broken off
Advice	Items removed from driver's view prior to test
Advice	Stone chip in windscreen
Advice	General corrosion on underside of vehicle

MOT #14	2016-07-26 13:50
MOT test number	720974112669
Result	✗ Failed
Advice	Items removed from driver's view prior to test
Advice	Stone chip in windscreen
Fail	Nearside Rear wheel bearing rough when rotated (2.6.1)
Advice	General corrosion on underside of vehicle
Fail	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Fail	Nearside Front position lamp(s) not working (1.1.A.3b)
Advice	Centre exhaust mount broken off
Fail	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)



MOT #13	2015-07-22 09:52
MOT test number	625503905229
Result	✓ Passed

MOT #12	2014-07-15 16:28
MOT test number	209906794442
Result	✓ Passed

- Notice** Management light on
- Advice** Nearside Rear Rear wheel bearing has slight play (2.6.2)
- Notice** Tank straps corroded
- Notice** Rear axel ans shocks corroded
- Advice** Rear Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)
- Notice** Centre exhaust and mount deteiorated
- Notice** Rear tyres close to wear bars

**MOT #11**

2014-07-15 11:56

MOT test number

717096694157

Result

✗ Failed

- Notice** Rear axel ans shocks corroded
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Nearside Rear Rear wheel bearing has slight play (2.6.2)
- Notice** Centre exhaust and mount deteiorated
- Notice** Rear tyres close to wear bars
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Rear Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)
- Notice** Management light on
- Notice** Tank straps corroded

MOT #10

2013-07-19 10:15

MOT test number

947690803259

Result

✓ Passed

- Notice** Engine management light on.
- Advice** Front Steering system has slight free play detected at steering wheel (2.2.A.1b)

MOT #9

2012-07-25 09:49

MOT test number

158347302236

Result

✓ Passed

MOT #8

2012-07-23 16:47

MOT test number

527305402279

Result

✗ Failed

- Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)

**MOT #7** 2011-06-28 11:29**MOT test number** 525669071188**Result** ✓ Passed**MOT #6** 2010-06-24 12:48**MOT test number** 653055770149**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** N/s/r wheel bearing slightly rough**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Center exhaust mount broken**MOT #5** 2008-10-22 11:52**MOT test number** 130136798264**Result** ✓ Passed**Advice** Offside Front brake disc slightly pitted (3.5.1h)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front brake disc slightly pitted (3.5.1h)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #4** 2008-10-22 11:52**MOT test number** 894246598229**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front brake disc slightly pitted (3.5.1h)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Headlamp aim too far to the right (1.8)**Advice** Offside Front brake disc slightly pitted (3.5.1h)**MOT #3** 2007-03-15 16:56**MOT test number** 873384777006**Result** ✓ Passed**MOT #2** 2006-04-12 13:32**MOT test number** 932262006185**Result** ✓ Passed**MOT #1** 2005-10-22 10:26**MOT test number** 592815095204**Result** ✓ Passed**Advice** Front brake disc slightly scored (3.5.1h)**Advice** Front Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 NJ52WTT
Plate since	2019-06-29
Current registration	 NJ52WTT
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2002-09-24
Last registration	2021-12-09
Complete history	See info



Registration #1	2002-09-24	19 mi
Registration #2	2005-10-22	14.414 mi
Registration #3	2006-04-12	16.389 mi
Registration #4	2007-03-15	21.661 mi
Registration #5	2008-10-22	31.202 mi
Registration #6	2010-06-24	38.915 mi
Registration #7	2011-06-28	42.288 mi
Registration #8	2012-07-23	45.251 mi
Registration #9	2012-07-25	45.251 mi
Registration #10	2013-07-19	51.198 mi
Registration #11	2014-07-15	53.344 mi
Registration #12	2015-07-15	55.490 mi
Registration #13	2016-07-15	57.636 mi
Registration #14	2017-07-15	59.782 mi
Registration #15	2018-07-15	61.928 mi
Registration #16	2019-07-15	64.074 mi
Registration #17	2020-07-15	66.220 mi
Registration #18	2021-07-15	68.366 mi
Registration #19	2022-07-15	70.512 mi
Registration #20	2023-07-15	72.658 mi
Registration #21	2024-03-28	74.804 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1724 mm
Height	1498 mm
Length	4081 mm
Wheel base	2508 mm
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of axles	2

Engine number

AWU703717