




report date: 2024-03-28

General information

Make	VOLVO
Model	XC90 D5 SE AWD
Colour	Black
Year of manufacture	2009
Top speed	118 mph
0 - 60 mph	11.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	185 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	25.5 mpg
Consumption extra urban	40.4 mpg
Consumption combined	33.2 mpg
CO2 emission	224 g/km
CO2 label	K





Internet history

Entry 2

Date 2021-09-02

Pictures 21

Listing price [View report](#)





source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 1

Date 2021-05-23

Pictures 15

Listing price [View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2023-09-06
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	46
Total items failed	18

MOT #16	2022-09-07 14:04
MOT test number	954258842427
Result	✓ Passed
Next expiry date	2023-09-06
Advice	Suspension corroded



MOT #15

2022-09-06 10:02

MOT test number

507079575227

Result

✗ Failed

- Advice** Items removed from driver's view prior to test
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Wishbone rear bush (5.3.4 (a) (i))
- Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))
- Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Seat belt webbing slightly damaged or frayed Middle row (7.1.2 (b) (ii))
- Advice** Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement D-bush (5.3.4 (a) (i))
- Fail** Offside Rear Position lamp with a multiple light source more than 1/2 not functioning (4.2.1 (a) (ii))
- Minor** Offside Direction indicator flashing more than 120 times a minute (4.4.4 (a))
- Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
- Advice** Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement Inner bush, front of two (5.3.4 (a) (i))
- Fail** Offside Headlamp aim too low (4.1.2 (a))
- Advice** Offside Rear Upper Suspension arm pin or bush worn but not resulting in excessive movement Inner bush, front of two (5.3.4 (a) (i))
- Advice** Offside rear light unit damaged, not showing white light to rear
- Fail** Nearside Front Suspension arm pin or bush excessively worn Wishbone rear bush (5.3.4 (a) (i))
- Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm bush (5.3.4 (a) (i))
- Advice** Offside Rear Nail in tyre x3 nails in tread
- Advice** Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement D-bush (5.3.4 (a) (i))
- Advice** Nearside Side repeater slightly discoloured (4.4.3 (a))
- Fail** Parking brake lever has excessive movement indicating incorrect adjustment Foot pedal (1.1.6 (c))
- Advice** Tyre slightly damaged/cracking or perishing All 4 tyres (5.2.3 (d) (ii))
- Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

Fail Nearside Rear Position lamp with a multiple light source more than 1/2 not functioning (4.2.1 (a) (ii))

Advice Nearside Rear Upper Suspension arm pin or bush worn but not resulting in excessive movement
Inner bush, front of two (5.3.4 (a) (i))

Fail Nearside Headlamp aim too high (4.1.2 (a))

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing
arm bush (5.3.4 (a) (i))

Advice General underside surface corrosion

**MOT #14** 2020-12-14 16:23**MOT test number** 259496300994**Result** ✓ Passed**MOT #13** 2019-06-24 14:56**MOT test number** 875055989905**Result** ✓ Passed**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #12** 2019-06-24 14:56**MOT test number** 336625580361**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #11** 2018-07-02 16:55**MOT test number** 878796442508**Result** ✓ Passed**MOT #10** 2017-06-30 08:55**MOT test number** 887873736238**Result** ✓ Passed**MOT #9** 2016-07-08 11:11**MOT test number** 152577136045**Result** ✓ Passed**MOT #8** 2016-07-08 08:01**MOT test number** 959689007456**Result** ✓ Passed

**MOT #7**

2015-06-25 10:34

MOT test number

386076375160

Result

✓ Passed

- Notice** Offside rear lens cracked
- Notice** Under-trays fitted obscuring some underside components
- Notice** Nearside rear tyre wearing on outer edge
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Notice** Oil leak
- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #6

2015-06-25 10:34

MOT test number

567716475170

Result

✗ Failed

- Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)
- Pass with rectification** Offside Rear position lamp(s) not working (1.1.A.3b)
- Notice** Offside rear lens cracked
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Notice** Under-trays fitted obscuring some underside components
- Notice** Nearside rear tyre wearing on outer edge
- Pass with rectification** Nearside Front position lamp(s) has less than 50% of the light sources illuminating (1.1.A.3b)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Oil leak
- Notice** Engine covers fitted obscuring some components in the engine bay

**MOT #5** 2014-06-30 16:16**MOT test number** 996551284135**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Oil leak**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #4** 2014-06-27 09:15**MOT test number** 727668774172**Result** ✗ Failed**Notice** Under-trays fitted obscuring some underside components**Notice** Oil leak**Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #3** 2013-06-28 11:11**MOT test number** 145849473113**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #2** 2012-06-14 15:14**MOT test number** 105926462199**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)



MOT #1	2012-06-14 15:14
MOT test number	286246862183
Result	✗ Failed
Pass with rectification	Offside Front position lamp(s) not working (1.1.A.3b)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Pass with rectification	Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)



Tax & MOT check

✕
Untaxed

Tax expired:
18 April 2023

✕
MOT

Expired:
6 September 2023

Tax status	Expired at 18 April 2023
Days left	377 days too late
MOT expiry date	6 September 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history


Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 YF09VHL
Plate since	2019-09-28
Current registration	 YF09VHL
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-06-30
Last registration	2022-09-07
Complete history	See info



Registration #1	2009-06-30	26 mi
Registration #2	2012-06-14	71.543 mi
Registration #3	2013-06-28	101.156 mi
Registration #4	2014-06-27	130.953 mi
Registration #5	2014-06-30	130.953 mi
Registration #6	2015-06-25	162.021 mi
Registration #7	2016-07-08	174.238 mi
Registration #8	2017-06-30	179.751 mi
Registration #9	2018-06-30	185.264 mi
Registration #10	2019-06-30	190.777 mi
Registration #11	2020-06-30	196.290 mi
Registration #12	2021-06-30	201.803 mi
Registration #13	2022-06-30	207.316 mi
Registration #14	2023-06-30	212.829 mi
Registration #15	2024-06-30	218.342 mi
Registration #16	2025-06-30	223.855 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1898 mm
Height	1743 mm
Length	4798 mm
Wheel base	2857 mm
Kerb weight	2148 kg
Max. allowed weight	2750 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	741691