



report date: 2024-03-29

General information

Make	FIAT
Model	DOBLO 16V ACTIVE MULTIJET COMBI
Colour	Black
Year of manufacture	2015
Top speed	111 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	135 BHP
Max. torque	320 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	49.6 mpg
CO2 emission	145 g/km
CO2 label	F





Internet history

Entry 2

Date	2023-01-06
Pictures	20
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 1

Date	2022-07-05
Pictures	28
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](#)



## MOT history

MOT expiry date	2025-02-13
MOT pass rate	60 %
MOT passed	6
Failed MOT tests	4
Total advice items	11
Total items failed	8

MOT #10	2024-02-14 17:07
MOT test number	153370201569
Result	✓ Passed
Next expiry date	2025-02-13
Advice	Nearside Play in steering rack inner joint(s) has a lot of movement
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9	2024-02-05 10:34
MOT test number	812881464572
Result	✗ Failed
Fail	Offside Front Lower Suspension component ball joint excessively worn (5.3.4 (a) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Play in steering rack inner joint(s) has a lot of movement
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8	2023-01-18 16:52
MOT test number	698663417044
Result	✓ Passed

**MOT #7** 2023-01-12 16:17**MOT test number** 180771644169**Result** ✗ Failed

- Fail** Nearside Side repeater not working (4.4.1 (a) (ii))
- Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))
- Fail** Nearside Rear Service brake lagging in operation (1.2.1 (d))
- Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**MOT #6** 2022-03-09 09:19**MOT test number** 211977033788**Result** ✓ Passed**MOT #5** 2021-03-30 16:13**MOT test number** 865704371410**Result** ✓ Passed

- Minor** Nearside Front Lower Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #4** 2019-11-26 10:27**MOT test number** 885948671200**Result** ✓ Passed

- Minor** Offside Side repeater insecure (4.4.1 (c) (i))

**MOT #3** 2019-11-26 10:27**MOT test number** 101325827980**Result** ✗ Failed

- Pass with rectification** Nearside Side repeater not working (4.4.1 (a) (ii))
- Minor** Offside Side repeater insecure (4.4.1 (c) (i))
- Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))



MOT #2	2018-11-14 11:23
MOT test number	454667573531
Result	✓ Passed
Advice	Nearside Rear Nail in tyre

MOT #1	2018-11-14 11:23
MOT test number	644684588038
Result	✗ Failed
Pass with rectification	Offside Side repeater not working (4.4.1 (a) (ii))
Advice	Nearside Rear Nail in tyre



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
13 February 2025

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	94
<b>MOT expiry date</b>	13 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2015-11-30
Last registration	2024-02-14
Complete history	<a href="#">See info</a>



Registration #1	2015-11-30	16 mi
Registration #2	2018-11-14	50.754 mi
Registration #3	2018-11-14	50.754 mi
Registration #4	2019-11-26	69.455 mi
Registration #5	2019-11-26	69.455 mi
Registration #6	2021-03-30	86.520 mi
Registration #7	2022-03-09	94.658 mi
Registration #8	2023-03-29	101.277 mi
Registration #9	2023-03-29	101.277 mi
Registration #10	2023-03-29	101.277 mi
Registration #11	2023-03-29	101.277 mi
Registration #12	2023-03-29	101.277 mi
Registration #13	2024-02-14	101.277 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1832 mm
Height	1845 mm
Length	4390 mm
Wheel base	3105 mm
Kerb weight	1545 kg
Max. allowed weight	2270 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of seats	5
Number of axles	2

Engine number

7437356