






report date: 2024-03-28

General information

Make	VOLVO
Model	XC70 D5 AUTHORITIES
Colour	White
Year of manufacture	2012
Top speed	137 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	212 BHP
Max. torque	440 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	33.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	45.6 mpg



CarCheck.co.uk page 1/12



CU62ANV report date: 2024-03-28

Internet history

Εı	n	tı	'V	,	1

Life y 1	
Date	2021-12-20
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2025-03-20
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	11
Total items failed	0

MOT #12	2024-03-21 16:08
MOT test number	120059166921
Result	✓ Passed
Next expiry date	2025-03-20
Advice Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))	

MOT #11	2023-04-22 11:53
MOT test number	557773416823
Result	✓ Passed
Advice Front Play in steering rack inner joint(s)	
Advice Rear Coil spring corroded (5.3.1 (b) (i))	

MOT #10	2021-12-06 16:24
MOT test number	363991497177
Result	✓ Passed
Advice Play in steering rack inner joint(s)	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #9 2021-12-06 11:02

MOT test number 156893691422

Result X Failed

MAJOR Nearside Side repeater not working (4.4.1 (a) (ii))

MAJOR Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Play in steering rack inner joint(s)

MOT #8 2020-12-22 08:12

MOT test number 829139823021

Result ✓ Passed

MOT #7 2020-12-21 11:51

MOT test number 469948907125

Result X Failed

DANGEROUS Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #6 2020-01-14 11:44

MOT test number 653745354149

Result \rightarrow Passed

MOT #5 2020-01-13 15:16

MOT test number 608338951823

Result X Failed

DANGEROUS Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MAJOR Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))

MOT #4 2019-01-10 10:17

MOT test number 502975531160

Result
✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #3	2017-11-24 10:34
MOT test number	356431034939
Result	✓ Passed
MOT #2	2016-11-10 17:15
MOT test number	857347545431
Result	✓ Passed
Advice Rear Brake pad(s) wearing thin (3.5.1g)	

MOT #1	2015-12-03 10:25
MOT test number	824997135451
Result	✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

20 March 2025

Tax & MOT check

MOT expiry date



Full MOT history See MOT history

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	

	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	,
Current registration	NK SIE
Plate since	
Current registration	NK SIN
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-12-01
Last registration	2024-03-21
Complete history	See info



Registration #1	2012-12-01	6 mi
Registration #2	2015-12-03	74.479 mi
Registration #3	2016-11-10	92.571 mi
Registration #4	2017-11-24	113.257 mi
Registration #5	2019-01-10	124.022 mi
Registration #6	2020-01-13	129.803 mi
Registration #7	2020-01-14	129.803 mi
Registration #8		71.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.177 es
Registration #12		11.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
60501	
60566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	88%
Children	84%
Pedestrian	43%
Safety systems	71%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	1861 mm
Height	1547 mm
Length	4823 mm

Additional information

Number of seats	5
Number of axles	2
Engine number	1091388

CarCheck.co.uk page 12/12