



**AEI7RWN**

report date: 2024-03-28

General information

Make	MINI
Model	ONE
Colour	Black
Year of manufacture	2017
Top speed	119 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	102 BHP
Max. torque	180 Nm at 1.400 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	47.9 mpg
Consumption extra urban	67.3 mpg
Consumption combined	58.9 mpg
CO2 emission	112 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-08-09
Pictures	5
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2025-04-26
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	14
Total items failed	2

MOT #7	2024-04-16 13:14
MOT test number	675889274039
Result	✓ Passed
Next expiry date	2025-04-26
Advice	Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Offside front, offside rear and nearside rear tyres heavily cracking

MOT #6	2024-04-10 09:49
MOT test number	600539085189
Result	✗ Failed
Fail	Nearside Front Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))
Advice	Offside front, offside rear and nearside rear tyres heavily cracking
Minor	Brake fluid warning lamp illuminated (1.1.10 (f))
Fail	Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Advice	Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #5** 2023-03-29 11:09**MOT test number** 704209842136**Result** ✓ Passed**Advice** Brakes require further inspection**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Engine covers and under trays fitted obscuring some components**Advice** Coil springs corroded**Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))**MOT #4** 2022-04-11 13:43**MOT test number** 195346398105**Result** ✓ Passed**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Nail in tyre**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (iii))**MOT #3** 2021-04-27 20:22**MOT test number** 398762319280**Result** ✓ Passed**MOT #2** 2021-02-15 14:15**MOT test number** 572202185774**Result** ✓ Passed**MOT #1** 2020-02-13 11:42**MOT test number** 241077952928**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
26 April 2025

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	95
<b>MOT expiry date</b>	26 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >





Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-03-02
Last registration	2024-04-16
Complete history	<a href="#">See info</a>



Registration #1	2017-03-02	29 mi
Registration #2	2020-02-13	17.353 mi
Registration #3	2021-02-15	20.058 mi
Registration #4	2021-04-27	20.569 mi
Registration #5	2022-05-20	20.277 mi
Registration #6	2023-05-20	20.277 mi
Registration #7	2023-05-20	20.277 mi
Registration #8	2023-05-20	20.277 mi
Registration #9	2023-05-20	20.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1727 mm
Height	1425 mm
Length	3982 mm
Wheel base	2567 mm
Kerb weight	1225 kg
Max. allowed weight	1680 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number	F011H523
---------------	----------