






report date: 2024-03-28

## General information

Make	NISSAN
Model	NAVARA DCI TEKNA 4X4 DCB
Colour	Black
Year of manufacture	2011
Top speed	112 mph
0 - 60 mph	10.7 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	188 BHP
Max. torque	450 Nm at 2.000 rpm
Engine capacity	2.488 cc
Cylinders	4
Fuel type	Diesel
Consumption city	24.1 mpg
Consumption extra urban	37.7 mpg



CarCheck.co.uk page 1/15



report date: 2024-03-28

# Internet history

## Entry 2

Date 2021-08-11

Pictures 31

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/15



GF11BXX report date: 2024-03-28

MOT history

MOT expiry date	2024-07-05
MOT pass rate	69 %
	11
MOT passed	11
Failed MOT tests	5
Total advice items	39
Total items failed	18

MOT #16		2023-06-30 13:07
MOT test	number	785889010224
Result		✓ Passed
Next expi	ry date	2024-07-05
Advice	Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))	
<b>Advice</b> system re	Nearside Rear Brakes imbalanced requirements only just met. It would appea quires adjustment or repair. (1.2.1 (b) (i))	ar that the braking
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Front Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))	

MOT #15		2022-06-24 10:54
MOT test	number	874684731839
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/15



report date: 2024-03-28

**MOT #14** 2022-06-17 15:11 819999063196 **MOT** test number Result × Failed **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Fail Service brake efficiency below requirements (1.2.2 (a) (i)) **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Fail Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i)) **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i)) **Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Fail Parking brake efficiency below requirements (1.4.2 (a) (i)) Fail Offside Front Lower Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))

MOT #13	2021-07-06 08:31
MOT test number	713748059976
Result	<b>✓</b> Passed
MOT #12	2020-12-16 13:29
MOT test number	189151098031
Result	<b>✓</b> Passed
Advice Nearside Rear Brake drum damp with oil	

CarCheck.co.uk page 4/15



report date: 2024-03-28

**MOT #11** 2020-12-10 11:32 **MOT** test number 209880801774 Result × Failed **Advice** Nearside Rear Brake drum damp with oil Fail Nearside Side repeater not working (4.4.1 (a) (ii)) Fail Nearside Rear Parking brake inoperative on one side (1.4.1 (a)) Advice Rear Tyre worn close to legal limit/worn on edge Both sides 2mm (5.2.3 (e)) Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i)) Fail Rear Exhaust mounting defective (6.1.2 (a)) **Advice** Fail Parking brake efficiency below requirements (1.4.2 (a) (i)) Nearside Rear Service brake has no recorded effort at a wheel (1.2.1 (a) (ii)) Fail

 MOT #10
 2019-12-28 13:30

 MOT test number
 993928131111

 Result
 ✓ Passed

**MOT #9** 2019-07-10 12:10 554782369713 **MOT** test number Result Passed **Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i)) **Advice** Nearside Front Brake pipe corroded, covered in grease or other material tip slightly corroded (1.1.11(c))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge bold on outer edge (5.2.3 (e)) Advice Exhaust mounting defective front back box mount (6.1.2 (a)) Advice Nearside Front Outer CV boot inner clip missing but prevents dirt ingress **Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

CarCheck.co.uk page 5/15



Fail

**GF11BXX** 

report date: 2024-03-28

**MOT #8** 2019-07-05 08:05 **MOT** test number 730037342993 Result × Failed **Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i)) Fail Emissions not tested exhaust leak (8.2.2.2 (e)) Nearside Rear Tyre worn close to legal limit/worn on edge bold on outer edge (5.2.3 (e)) **Advice** Fail Nearside Rear Hydraulic brake cylinder leaking hydraulic fluid drum covered in brake fluid (1.1.16 (b) (i)) Fail Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i)) **Advice** Exhaust mounting defective front back box mount (6.1.2 (a)) Advice Nearside Front Outer CV boot inner clip missing but prevents dirt ingress Advice Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i)) Advice Nearside Front Brake pipe corroded, covered in grease or other material tip slightly corroded (1.1.11(c))Fail Parking brake efficiency below requirements (1.4.2 (a) (i)) Fail Exhaust has a major leak of exhaust gases flexible section (6.1.2 (a))

MOT #7	2018-06-29 11:13
MOT test number	352846212995

Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

Result

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))

Advice Nearside Rear light unit damaged but lights not affected

CarCheck.co.uk page 6/15



**Advice** 

**GF11BXX** report date: 2024-03-28

**MOT #6** 2018-06-29 11:13 933016961660 **MOT** test number Result × Failed **Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Pass with rectification Offside Front Position lamp not working (4.2.1 (a)) Nearside Rear light unit damaged but lights not affected

**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))

**MOT #5** 2017-07-03 10:18 **MOT** test number 567725537487

Result Passed

**MOT #4** 2017-06-19 14:37

**MOT** test number 758235749486

Result × Failed

**Advice** Nearside Rear Half Shaft Seal Leaking

Fail Rear Brakes imbalanced across an axle Axle 2 (3.7.B.5b)

Fail Nearside rear brake recording little or no effort (3.7.B.5a)

**MOT** #3 2016-06-27 10:25

**MOT** test number 713467810852

Result ✓ Passed

MOT #2 2015-06-06 09:22

**MOT** test number 717047955153

Result Passed

**Notice** Front and centre exhaust rubber support bondings weak but exhaust still supported

CarCheck.co.uk page 7/15



MOT #1

GF11BXX
report date: 2024-03-28

2014-06-13 13:44

**MOT test number** 217914664150

**Result** ✓ Passed

CarCheck.co.uk page 8/15




**GF11BXX** report date: 2024-03-28

5 July 2024

### Tax & MOT check

**MOT** expiry date



**Full MOT history** See MOT history

CarCheck.co.uk page 9/15



report date: 2024-03-28

### Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



GF11BXX report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 11/15



report date: 2024-03-28

## Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owner have? Check it in the premium report and see all owner registrations. Download the full	
***************************************	
	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	
Current registration	NK WE WAS
Plate since	
Current registration	NK SIK
Plate since	
	More info >

CarCheck.co.uk page 12/15



**GF11BXX** report date: 2024-03-28

Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >


CarCheck.co.uk page 13/15



**GF11BXX** report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-05-19
Last registration	2023-06-30
Complete history	See info



Registration #1	2011-05-19	25 mi
Registration #2	2014-06-13	30.282 mi
Registration #3	2015-06-06	39.369 mi
Registration #4	2016-06-27	50.500 mi
Registration #5	2017-06-19	60.383 mi
Registration #6	2017-07-03	60.617 mi
Registration #7	2018-06-29	69.348 mi
Registration #8	2018-06-29	69.348 mi
Registration #9	2019-07-05	78.334 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		71.777 es
Registration #13		11.777 es
Registration #14		71.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		0.00 44

More info >

CarCheck.co.uk page 14/15



report date: 2024-03-28

## Car features

50225	Air conditionin
50295	
50482	
50501	
50566	
50567	
50569	

## Safety ratings

NCAP rating	*****
Video	see crash video



## Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Engine number	10672B

CarCheck.co.uk page 15/15