



report date: 2024-03-29

General information

Make	FIAT
Model	TIPO MULTIJET EASY
Colour	Grey
Year of manufacture	2018
Top speed	112 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	94 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	62.8 mpg
Consumption extra urban	85.6 mpg
Consumption combined	76.4 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-07-24
Pictures	12
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-08
MOT pass rate	44 %
MOT passed	4
Failed MOT tests	5
Total advice items	24
Total items failed	17

MOT #9	2024-02-09 12:01
MOT test number	570497239486
Result	✓ Passed
Next expiry date	2025-02-08
Advice	Central Rear Standard fitment seat belt missing
Advice	Nearside Rear exhaust shield insecure

MOT #8	2024-02-02 11:58
MOT test number	234215321580
Result	✗ Failed
Advice	Nearside Rear exhaust shield insecure
Fail	Nearside Rear Seat belt buckle not functioning as intended (7.1.2 (d))
Fail	Offside Rear Seat belt buckle not functioning as intended (7.1.2 (d))
Fail	Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
Fail	Central Rear Seat belt buckle not functioning as intended (7.1.2 (d))

**MOT #7**

2023-02-07 08:09

MOT test number

828066818908

Result

✓ Passed

- Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Front Inner Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

MOT #6

2022-03-21 15:36

MOT test number

366601635448

Result

✓ Passed

- Advice** Engine and under covers fitted obscuring some components
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #5

2022-03-21 11:05

MOT test number

457418035078

Result

✗ Failed

- Advice** Engine and under covers fitted obscuring some components
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Front Anti-roll bar ball joint excessively worn both side (5.3.4 (a) (i))
- Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #4**

2022-03-10 14:52

MOT test number

924607247902

Result**✗ Failed**

- Fail** Offside Rear Seat belt buckle not functioning as intended (7.1.2 (d))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Offside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))
- Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Fail** Nearside Rear Seat belt buckle not functioning as intended (7.1.2 (d))
- Fail** Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Offside Rear Nail in tyre

MOT #3

2022-03-10 12:55

MOT test number

701585293989

Result**✗ Failed**

- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Offside Rear Seat belt buckle not functioning as intended (7.1.2 (d))
- Fail** Offside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))
- Advice** Offside Rear Nail in tyre
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Nearside Rear Seat belt buckle not functioning as intended (7.1.2 (d))
- Fail** Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))



MOT #2	2021-03-03 14:53
MOT test number	984894577607
Result	✓ Passed
Advice	Both front brake discs worn

MOT #1	2021-03-01 12:54
MOT test number	470841042129
Result	✗ Failed
Advice	Both front brake discs worn
Fail	Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
Fail	Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))



Tax & MOT check

✓
Taxed

Tax due:
1 April 2025

✓
MOT

Expires:
8 February 2025

Tax status	Valid until 1 April
Days left	336
MOT expiry date	8 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
First licence fee (12 months)	£ 165,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 185,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	PK180EU
Plate since	2019-03-29
Current registration	PK180EU
Plate since	2019-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2018-03-29
Last registration	2024-02-09
Complete history	See info



Registration #1	2018-03-29	12 mi
Registration #2	2021-03-01	18.321 mi
Registration #3	2021-03-03	18.322 mi
Registration #4	2022-03-10	32.070 mi
Registration #5	2022-03-10	32.070 mi
Registration #6	2022-03-10	32.070 mi
Registration #7	2022-03-10	32.070 mi
Registration #8	2022-03-10	32.070 mi
Registration #9	2022-03-10	32.070 mi
Registration #10	2022-03-10	32.070 mi
Registration #11	2022-03-10	32.070 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	82%
Children	60%
Pedestrian	62%
Safety systems	57%
Overall rating	68%
Video	see crash video



Copyright © 2016 Euro NCAP

Dimensions & weight

Width	1792 mm
Height	1495 mm
Length	4368 mm
Wheel base	2638 mm
Kerb weight	1365 kg
Max. allowed weight	1790 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	6204117