





report date: 2024-03-29

General information

Make	HONDA
Model	CR-Z I-VTEC IMA SPORT
Colour	Black
Year of manufacture	-
Top speed	124 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP	
Max. torque	145 Nm at 4.800 rpm	
Cylinders	4	
Fuel type	Petrol	
Consumption city	46.3 mpg	
Consumption extra urban	64.2 mpg	
Consumption combined	56.5 mpg	



CarCheck.co.uk page 1/10



Internet history

Entry 3

Date 2022-04-04

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 2

Date 2021-09-23

Pictures 35

Listing price <u>View report</u>









source: yesauto.com

Entry 1

Date 2021-09-19


Pictures 36

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/10



2023-04-08 08:55

✓ Passed

MOT history

MOT #13

Result

MOT test number	529947767275
Result	✓ Passed
Next expiry date	2024-04-07
MOT #12	2022-04-07 10:07
MOT test number	565530425416
Result	✓ Passed
MOT #11	2021-09-24 09:43
MOT test number	608256942433
Result	✓ Passed
MOT #10	2021-03-02 15:30
MOT test number	793772371697

MOT #9	2020-02-05 10:10
MOT test number	567506425619
Result	✓ Passed

MOT #8	2019-01-11 12:24
MOT test number	101710166665
Result	✓ Passed

MOT #7	2019-01-11 12:24
MOT test number	515210607922

Result × Failed

Pass with rectification Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

CarCheck.co.uk page 3/10



MOT #6 2018-01-11 16:03

MOT test number 864075277123

MOT #5 2016-12-15 09:53

MOT test number 705489545771

Result

✓ Passed

MOT #4 2016-12-15 09:53

MOT test number 141445051474

Result X Failed

Pass with rectification Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Pass with rectification Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Pass with rectification Offside Front Body has a sharp edge caused by damage wing mirror (6.1.C.1)

MOT #3 2015-12-23 12:53

MOT test number 624294345588

Result \(\sqrt{Passed} \)

MOT #2 2015-01-07 12:59

MOT test number 845607205027

Notice Slight damage to offside rear tyre outor wall tyre been run flat

Notice Vehicle's internal headlight adjuster altered to recheck lights

MOT #1 2014-01-14 15:40

MOT test number 798254214053

Result ✓ Passed

Notice Under-trays fitted obscuring some underside components

CarCheck.co.uk page 4/10



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



OV11EEM

report date: 2024-03-29

Owner	history
OWITCE	THISCOLY

e when mistery	
For how long did the current and previous owner(s) have this HONDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full is	
STREET, STREET	

	More info >
Plate changes	
See in this check if this HONDA had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 7/10



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 8/10



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-03-25
Last registration	2023-04-08
Complete history	See info



Registration #1	2011-03-25	26 mi
Registration #2	2014-01-14	15.714 mi
Registration #3	2015-01-07	24.013 mi
Registration #4	2015-12-23	32.292 mi
Registration #5	2016-12-15	40.779 mi
Registration #6	2016-12-15	40.779 mi
Registration #7	2018-01-11	47.786 mi
Registration #8	2019-01-11	54.053 mi
Registration #9	2019-01-11	54.053 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		71.777 66
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		

More info >

CarCheck.co.uk page 9/10



Safety ratings

NCAP rating	****
Adult	93%
Children	80%
Pedestrian	71%
Safety systems	86%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	2014 mm
Height	1395 mm
Length	4080 mm
Wheel base	2425 mm
Kerb weight	1198 kg

Additional information

Fuel tank capacity	40 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	LEA1 1004814

CarCheck.co.uk page 10/10