



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	SCIROCCO GT
Colour	Red
Year of manufacture	2009
Top speed	145 mph
0 - 60 mph	7.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	200 BHP
Max. torque	280 Nm at 1.700 rpm
Engine capacity	1.984 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.7 mpg
Consumption extra urban	47.9 mpg
Consumption combined	37.2 mpg
CO2 emission	179 g/km
CO2 label	I







Internet history

Entry 2

Date	2022-07-16
Pictures	50
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-09-11
Pictures	47
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-10
MOT pass rate	57 %
MOT passed	12
Failed MOT tests	9
Total advice items	44
Total items failed	19

MOT #21	2023-10-02 15:50
---------	------------------

MOT test number	550268753386
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-10-10
------------------	------------

- AdviceOffside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- AdviceOffside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- AdviceNearside Front Coil spring corroded (5.3.1 (b) (i))
- AdviceNearside Rear Coil spring corroded (5.3.1 (b) (i))
- AdviceNearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- AdviceNearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- AdviceOil leak, but not excessive (8.4.1 (a) (i))
- AdviceOffside Front Coil spring corroded (5.3.1 (b) (i))
- AdviceOffside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #20**

2023-10-02 10:24

MOT test number

682371364286

Result**✗ Failed**

- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Fail** Offside Front Service brake excessively binding (1.2.1 (f))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))

MOT #19

2022-10-11 10:47

MOT test number

180904961392

Result**✓ Passed**

- Advice** Covers fitted masking testable items

**MOT #18**

2022-06-04 10:59

MOT test number

418740395324

Result

✓ Passed

Advice

Oil leak, but not excessive (8.4.1 (a) (i))

Advice

Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice

Rear Lower Suspension arm corroded but not seriously weakened both (5.3.3 (b) (i))

Advice

Nearside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #17

2021-06-18 08:22

MOT test number

920477429659

Result

✓ Passed

MOT #16

2021-05-18 14:04

MOT test number

165087429299

Result

✗ Failed

Advice

Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice

Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail

Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Advice

Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail

Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MOT #15

2020-07-14 12:17

MOT test number

799421489665

Result

✓ Passed

Advice

Rear Coil spring corroded Both (5.3.1 (b) (i))

**MOT #14** 2020-07-14 12:17**MOT test number** 112575274572**Result** ✗ Failed**Advice** Rear Coil spring corroded Both (5.3.1 (b) (i))**Pass with rectification** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #13** 2019-03-22 13:33**MOT test number** 607650981118**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12** 2019-03-20 09:27**MOT test number** 380614269601**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Nearside Front Headlamp aim too high (4.1.2 (a))**Fail** Offside Front Headlamp aim too low (4.1.2 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11** 2018-04-17 13:02**MOT test number** 932642157249**Result** ✓ Passed

**MOT #10** 2018-04-16 14:51**MOT test number** 823732388879**Result** ✗ Failed**Fail** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)**Fail** Exhaust has a major leak of exhaust gases joining/ clamp (7.1.2)**Fail** Offside Headlamp aim too low (1.8)**Fail** Emissions not tested (7.3.A.1)**MOT #9** 2017-03-28 10:52**MOT test number** 888393027695**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit 2mm (4.1.E.1)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #8** 2017-03-27 10:32**MOT test number** 458998950700**Result** ✗ Failed**Fail** Nearside Headlamp aim too low (1.8)**Fail** Nearside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Offside Front Tyre worn close to the legal limit 2mm (4.1.E.1)**MOT #7** 2016-04-05 11:59**MOT test number** 969536956516**Result** ✓ Passed

**MOT #6** 2016-03-25 15:47**MOT test number** 269592003646**Result** ✗ Failed**Fail** Nearside Rear coil spring broken (2.4.C.1a)**MOT #5** 2015-04-20 14:21**MOT test number** 576990815190**Result** ✓ Passed**Notice** Sump pan corroded**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #4** 2015-04-17 12:26**MOT test number** 885367305159**Result** ✗ Failed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Rear Mechanical brake component has restricted free movement (3.5.1k)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Sump pan corroded**MOT #3** 2014-03-21 14:30**MOT test number** 806630384057**Result** ✓ Passed**MOT #2** 2012-11-16 11:50**MOT test number** 737301722363**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)



MOT #1	2012-11-16 10:53
MOT test number	279241422382
Result	✗ Failed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
Fail	Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
10 October 2024

Tax status	Valid until 1 April
Days left	337
MOT expiry date	10 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 SK59GBX
Plate since	2019-06-29
Current registration	 SK59GBX
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2009-11-20
Last registration	2023-10-02
Complete history	See info



Registration #1	2009-11-20	22 mi
Registration #2	2012-11-16	45.923 mi
Registration #3	2012-11-16	45.923 mi
Registration #4	2014-03-21	59.839 mi
Registration #5	2015-04-17	69.028 mi
Registration #6	2015-04-20	69.028 mi
Registration #7	2016-03-25	75.391 mi
Registration #8	2016-04-05	75.565 mi
Registration #9	2017-03-27	82.247 mi
Registration #10	2017-03-28	82.247 mi
Registration #11	2018-04-16	88.040 mi
Registration #12	2018-04-17	88.043 mi
Registration #13	2019-05-20	95.277 mi
Registration #14	2019-05-20	95.277 mi
Registration #15	2019-05-20	95.277 mi
Registration #16	2019-05-20	95.277 mi
Registration #17	2019-05-20	95.277 mi
Registration #18	2019-05-20	95.277 mi
Registration #19	2019-05-20	95.277 mi
Registration #20	2019-05-20	95.277 mi
Registration #21	2019-05-20	95.277 mi
Registration #22	2019-05-20	95.277 mi
Registration #23	2019-05-20	95.277 mi
Registration #24	2019-05-20	95.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	73%
Pedestrian	53%
Safety systems	71%
Overall rating	76%
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1404 mm
Length	4256 mm
Wheel base	2578 mm
Kerb weight	1318 kg
Max. allowed weight	1740 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	2

Number of seats	4
Number of axles	2
Engine number	CAW 031599