





report date: 2024-03-29

## General information

| Make                | VOLKSWAGEN                            |
|---------------------|---------------------------------------|
| Model               | TRANSPORTER T28 TDI P/V TRENDLINE BMT |
| Colour              | White                                 |
| Year of manufacture | 2019                                  |
| Top speed           | 98 mph                                |
| 0 - 100 km/h        | 11.6 seconds                          |
| Gearbox             | 5 speed Manual                        |

## Engine & fuel consumption

| Power                   | 110 kW / 150 HP / 101 BHP |
|-------------------------|---------------------------|
| Max. torque             | 340 Nm at 1.500 rpm       |
| Engine capacity         | 1.968 cc                  |
| Cylinders               | 4                         |
| Fuel type               | Diesel                    |
| Consumption city        | 40.4 mpg                  |
| Consumption extra urban | 54.3 mpg                  |
| Consumption combined    | 47.9 mpg                  |
| CO2 emission            | 156 g/km                  |
| CO2 label               | G                         |



CarCheck.co.uk page 1/11



report date: 2024-03-29

## Internet history

## Entry 1

Date 2022-05-16

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

# MOT history

| MOT expiry date    | 2025-04-12 |
|--------------------|------------|
| MOT pass rate      | 60 %       |
| MOT passed         | 3          |
| Failed MOT tests   | 2          |
| Total advice items | 4          |
| Total items failed | 2          |

| MOT #5    |  | 2024-04-08 16:39 |
|-----------|--|------------------|
| MOT test  | number   | 199796071137     |
| Result    |  | ✓ Passed         |
| Next expi | ry date  | 2025-04-12       |
| Advice    | Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b)) |                  |
| Advice    | Bulb fail warning lamp on dash                                     |                  |

| MOT #4   | 2024-04-08 11:54 |
|--|------------------|
| MOT test number  | 230779783785     |
| Result   | <b>X</b> Failed  |
| Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))      |                  |
| Advice Bulb fail warning lamp on dash  |                  |
| Fail Headlamp aim projected beam image is obviously incorrect both (4.1.2 (c)) |                  |

| MOT #3          | 2023-04-13 13:26 |
|-----------------|------------------|
| MOT test number | 416896540531     |
| Result          | <b>✓</b> Passed  |

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #2 2023-04-13 08:13

**MOT test number** 880382166507

Result

**X** Failed

**Fail** Driver's view of the road through the swept area of the windscreen significantly affected by an obstruction Sun strip too wide (3.1 (a) (ii))

MOT #1 2022-04-05 12:25

**MOT test number** 429742604242

Result \( \sqrt{Passed} \)

CarCheck.co.uk page 4/11



GF19TNE report date: 2024-03-29

Tax & MOT check



| Tax status       | Valid until 1 July |
|------------------|--------------------|
| Days left        | 62                 |
| MOT expiry date  | 12 April 2025      |
| Full MOT history | See MOT history    |

### Tax calculation

| Vehicle class             | 39         |
|---------------------------|------------|
| Standard rate (12 months) | £ 320,00,- |
| Standard rate (6 months)  | £ 176,00,- |

CarCheck.co.uk page 5/11



report date: 2024-03-29

### Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <a href="here">here</a> for the results.


#### Damage 1

| Date     |  |
|----------|--|
| Category |  |
| Туре     |  |
| Damage 2 |  |

Damage 2

**Category** 

**Type** 



#### Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

### Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

| Owner history  |             |
|--|-------------|
| For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here. |             |
| ********   |             |
|  |             |
| ************   |             |
| *********  |             |
| ***************************************  |             |
| ************   |             |
|  | More info > |
| Plate changes  |             |
| See in this check if this VOLKSWAGEN had different number plates.  |             |
| Number of plates   |             |
| Current registration   | SIPS<br>UK  |
| Plate since  | mm.m.a      |
| Current registration   | UK UK       |
| Plate since  |             |
|  | More info > |

CarCheck.co.uk page 8/11



GF19TNE report date: 2024-03-29

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Combact info      |  |

**Contact info** 

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 7          |
| First mileage registration | 2019-03-28 |
| Last registration          | 2024-04-08 |
| Complete history           | See info   |



| Registration #1 | 2019-03-28 | 24 mi     |
|-----------------|------------|-----------|
| Registration #2 | 2022-04-05 | 56.612 mi |
| Registration #3 |            | 11.777 es |
| Registration #4 | 2023-04-13 | 64.382 mi |
| Registration #5 |            | 11.777 es |
| Registration #6 |            | 11.777 es |
| Registration #7 |            | 11.777 au |

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

## Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

# Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 79%             |
| Children       | 74%             |
| Pedestrian     | 32%             |
| Safety systems | 57%             |
| Overall rating | 66%             |
| Video          | see crash video |



## Dimensions & weight

| Width               | 1904 mm |
|---------------------|---------|
| Height              | 1990 mm |
| Length              | 4892 mm |
| Wheel base          | 3000 mm |
| Kerb weight         | 1914 kg |
| Max. allowed weight | 2800 kg |

## Additional information

| Fuel tank capacity | 70 I             |
|--------------------|------------------|
| Fuel delivery      | Direct Injection |
| Number of seats    | 3                |
| CarChack co.uk     | pago 11/11       |

CarCheck.co.uk page 11/11

| Number of axles | 2          |
|-----------------|------------|
| Engine number   | CXGB134569 |