



report date: 2024-03-29

General information

Make	KIA
Model	CEED CRDI VR-7
Colour	White
Year of manufacture	2011
Top speed	107 mph
0 - 60 mph	11.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	235 Nm at 2.500 rpm
Engine capacity	1.582 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	70.6 mpg
Consumption combined	65.7 mpg
CO2 emission	113 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-01-31
Pictures	1
Listing price	<a href="#">View report</a>



source: autoonline.co.uk



MOT history

MOT expiry date	2025-04-18
MOT pass rate	55 %
MOT passed	11
Failed MOT tests	9
Total advice items	30
Total items failed	17

MOT #20	2024-04-18 15:25
MOT test number	803236303747
Result	✓ Passed
Next expiry date	2025-04-18
Advice	Nearside Front Tyre worn close to legal limit/worn on edge Bald inner edge (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Front Brake disc worn, but not excessively Both (1.1.14 (a) (i))

**MOT #19**

2024-04-18 09:11

**MOT test number**

220372156433

**Result****✗ Failed**

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Front Brake disc worn, but not excessively Both (1.1.14 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge Bald inner edge (5.2.3 (e))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Windscreen washer not working (3.5 (a))
- Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

**MOT #18**

2023-04-17 10:00

**MOT test number**

493908990414

**Result****✓ Passed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #17**

2023-04-17 10:00

**MOT test number**

466985742247

**Result****✗ Failed**

- Pass with rectification** Reversing lamp inoperative (4.6.1 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #16** 2022-03-28 11:52**MOT test number** 636122969653**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #15** 2022-03-28 11:52**MOT test number** 551065965389**Result** ✗ Failed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Pass with rectification** Front Position lamp not working both (4.2.1 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #14** 2021-04-19 08:30**MOT test number** 787761596796**Result** ✓ Passed**MOT #13** 2020-01-06 13:01**MOT test number** 803472451309**Result** ✓ Passed**MOT #12** 2020-01-06 13:01**MOT test number** 940374666124**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #11** 2019-01-11 12:15**MOT test number** 936172958105**Result** ✓ Passed



MOT #10 2018-01-15 13:26

MOT test number 698109286674

Result ✓ Passed

MOT #9 2018-01-15 13:26

MOT test number 917813491241

Result ✗ Failed

**Pass with rectification** Offside Headlamp aim too low (1.8)

**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)

MOT #8 2017-01-20 12:37

MOT test number 301818753767

Result ✓ Passed

**Advice** Child Seat fitted not allowing full inspection of adult belt

MOT #7 2017-01-20 12:37

MOT test number 796122799637

Result ✗ Failed

**Pass with rectification** Nearside Headlamp aim too high (1.8)

**Advice** Child Seat fitted not allowing full inspection of adult belt

**Pass with rectification** Offside Headlamp aim too high (1.8)

**MOT #6** 2016-02-02 14:05**MOT test number** 766365712623**Result** ✓ Passed**Advice** Nearside Rear tyre cracking**Advice** Nearside Front Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt seepage of grease (2.5.C.1a)**Advice** Offside Rear tyre cracking**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #5** 2016-01-23 10:30**MOT test number** 715427001265**Result** ✗ Failed**Advice** Nearside Rear tyre cracking**Fail** Offside Front Headlamp aim too low adjusted (1.8)**Fail** Offside Front Front suspension ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Nearside Front Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt seepage of grease (2.5.C.1a)**Advice** Offside Rear tyre cracking**Fail** Nearside Front Front suspension ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #4** 2015-01-10 09:19**MOT test number** 578920715026**Result** ✓ Passed

**MOT #3** 2015-01-10 09:19**MOT test number** 349220315098**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**Pass with rectification** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**MOT #2** 2014-01-11 15:33**MOT test number** 549941414036**Result** ✓ Passed**Notice** Offside front bumper and headlamp have minor damage**MOT #1** 2014-01-11 11:13**MOT test number** 467681314008**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Suspension arm ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Notice** Offside front bumper and headlamp have minor damage**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
18 April 2025

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	337
<b>MOT expiry date</b>	18 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	<b>HN60HVW</b>
Plate since	2019-03-29
Current registration	<b>HN60HVW</b>
Plate since	2019-03-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2011-02-04
Last registration	2024-04-18
Complete history	<a href="#">See info</a>



Registration #1	2011-02-04	21 mi
Registration #2	2014-01-11	23.488 mi
Registration #3	2014-01-11	23.488 mi
Registration #4	2015-01-10	29.856 mi
Registration #5	2016-01-23	37.956 mi
Registration #6	2016-02-02	38.040 mi
Registration #7	2017-01-20	46.838 mi
Registration #8	2017-01-20	46.838 mi
Registration #9	2018-01-15	56.148 mi
Registration #10	2018-01-15	56.148 mi
Registration #11	2019-01-11	66.992 mi
Registration #12	2019-01-11	66.992 mi
Registration #13	2019-01-11	66.992 mi
Registration #14	2019-01-11	66.992 mi
Registration #15	2019-01-11	66.992 mi
Registration #16	2019-01-11	66.992 mi
Registration #17	2019-01-11	66.992 mi
Registration #18	2019-01-11	66.992 mi
Registration #19	2019-01-11	66.992 mi
Registration #20	2019-01-11	66.992 mi
Registration #21	2019-01-11	66.992 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1790 mm
Height	1480 mm
Length	4260 mm
Wheel base	2650 mm
Kerb weight	1468 kg
Max. allowed weight	1820 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number	D4FBBZ297252
---------------	--------------