



report date: 2024-03-29

General information

Make	AUDI
Model	A3 TDI SE
Colour	Black
Year of manufacture	2008
Top speed	117 mph
0 - 60 mph	11.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	104 BHP
Max. torque	320 Nm at 2.500 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.9 mpg
Consumption extra urban	64.2 mpg
Consumption combined	53.3 mpg
CO2 emission	135 g/km
CO2 label	E





MOT history

MOT expiry date	2025-03-23
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	31
Total items failed	2

MOT #17	2024-03-21 11:57
MOT test number	919050864963
Result	✓ Passed
Next expiry date	2025-03-23
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Minor	Offside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))
Minor	Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #16**

2023-03-24 17:11

**MOT test number**

834837451106

**Result**

✓ Passed

- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Central Rear Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- Advice** Offside Front Suspension rod pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #15**

2021-10-20 15:00

**MOT test number**

735473234514

**Result**

✓ Passed

**MOT #14**

2020-10-24 13:00

**MOT test number**

475540595099

**Result**

✓ Passed

- Advice** Nearside Front 50% of side repeater not working
- Advice** Nearside Rear arch liner damaged

**MOT #13** 2020-10-24 11:05**MOT test number** 780861436089**Result** ✗ Failed**Advice** Nearside Front 50% of side repeater not working**MAJOR** Nearside Headlamp aim projected beam image is obviously incorrect bulb fitted wrong (4.1.2 (c))**Advice** Nearside Rear arch liner damaged**MOT #12** 2019-10-30 15:45**MOT test number** 130930347015**Result** ✓ Passed**Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**MOT #11** 2019-10-30 10:18**MOT test number** 814197938752**Result** ✗ Failed**Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**DANGEROUS** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**DANGEROUS** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #10** 2018-11-28 14:34**MOT test number** 983410883574**Result** ✓ Passed**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #9** 2017-11-03 15:40**MOT test number** 311012830643**Result** ✓ Passed**MOT #8** 2016-11-30 12:45**MOT test number** 231165121552**Result** ✓ Passed**Advice** Nearside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)**MOT #7** 2015-11-30 15:45**MOT test number** 208205201709**Result** ✓ Passed**Advice** Offside Rear tyre slightly perished**MOT #6** 2014-11-20 13:36**MOT test number** 379914524365**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #5** 2014-11-20 09:36**MOT test number** 538384724327**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Child seat fitted not allowing full inspection of adult belt**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



<b>MOT #4</b>	2013-11-30 10:37
<b>MOT test number</b>	757844433359
<b>Result</b>	✓ Passed
<div><b>Notice</b> Child seat fitted not allowing full inspection of adult belt</div>	
<b>MOT #3</b>	2012-11-14 13:35
<b>MOT test number</b>	818179312369
<b>Result</b>	✓ Passed
<b>MOT #2</b>	2011-12-01 10:23
<b>MOT test number</b>	948075231362
<b>Result</b>	✓ Passed
<b>MOT #1</b>	2011-10-24 15:19
<b>MOT test number</b>	748347391257
<b>Result</b>	✓ Passed
<div><b>Advice</b> Offside Front Tyre worn close to the legal limit (4.1.E.1)</div> <div><b>Advice</b> Nearside Front Tyre worn close to the legal limit (4.1.E.1)</div>	



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
23 March 2025

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	32
<b>MOT expiry date</b>	23 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-11-07
Last registration	2024-03-21
Complete history	<a href="#">See info</a>



Registration #1	2008-11-07	8 mi
Registration #2	2011-10-24	37.752 mi
Registration #3	2011-12-01	38.149 mi
Registration #4	2012-11-14	43.325 mi
Registration #5	2013-11-30	50.996 mi
Registration #6	2014-11-20	58.499 mi
Registration #7	2014-11-20	58.499 mi
Registration #8	2015-11-30	66.327 mi
Registration #9	2016-11-30	75.398 mi
Registration #10	2017-11-30	84.469 mi
Registration #11	2018-11-30	93.540 mi
Registration #12	2019-11-30	102.611 mi
Registration #13	2020-11-30	111.682 mi
Registration #14	2021-11-30	120.753 mi
Registration #15	2022-11-30	129.824 mi
Registration #16	2023-11-30	138.895 mi
Registration #17	2024-03-21	147.966 mi
Registration #18	2024-03-21	147.966 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1765 mm
Height	1423 mm
Length	4286 mm
Wheel base	2578 mm
Kerb weight	1295 kg
Max. allowed weight	1880 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number	BXE 979560
---------------	------------