



report date: 2024-03-28

General information

Make	FORD
Model	KA ZETEC
Colour	Silver
Year of manufacture	2010
Top speed	99 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	44.8 mpg
Consumption extra urban	64.2 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	C






Internet history

Entry 2

Date	2023-06-12
Pictures	25
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-01-30
Pictures	10
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2024-06-01
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	21
Total items failed	17

MOT #19	2023-06-02 13:25
MOT test number	872915680026
Result	✓ Passed
Next expiry date	2024-06-01

MOT #18	2023-05-18 15:30
MOT test number	293318552387
Result	✓ Passed
Advice	All 4 tyres have slight cracking
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #17	2022-05-26 12:34
MOT test number	554696482641
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge Slight cracking/perishing (5.2.3 (e))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge Slight cracking/perishing (5.2.3 (e))

**MOT #16** 2021-05-20 10:54**MOT test number** 647685732637**Result** ✓ Passed**MOT #15** 2020-02-08 14:31**MOT test number** 340983241978**Result** ✓ Passed**MOT #14** 2020-02-06 09:42**MOT test number** 932131442531**Result** ✗ Failed**Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))**Fail** Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Coil spring corroded Both rears (5.3.1 (b) (i))**Fail** Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Nearside Rear Upper Shock absorbers has an excessively worn bush Also shock absorber corroded (5.3.2 (c))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #13** 2018-11-24 10:32**MOT test number** 845502514857**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #12** 2018-11-24 10:32**MOT test number** 788904550552**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a))**Pass with rectification** Nearside Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Pass with rectification** Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))**Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))**MOT #11** 2017-12-12 10:36**MOT test number** 557261381592**Result** ✓ Passed**MOT #10** 2017-09-21 13:00**MOT test number** 472261910729**Result** ✓ Passed**MOT #9** 2017-09-21 11:36**MOT test number** 842873866839**Result** ✗ Failed**Fail** Offside Rear Tyre not fitted in accordance with side wall instructions (4.1.D.1f)**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #8** 2016-12-08 11:58**MOT test number** 489856963161**Result** ✓ Passed

**MOT #7** 2016-03-30 10:13**MOT test number** 940756021938**Result** ✓ Passed**MOT #6** 2015-03-31 11:39**MOT test number** 208840695046**Result** ✓ Passed**Notice** Exhaust back box slightly corroded**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2015-03-31 11:39**MOT test number** 438190095072**Result** ✗ Failed**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Exhaust back box slightly corroded**MOT #4** 2014-03-14 15:31**MOT test number** 168463874061**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Exhaust system corroded outer skin on rear silencer peeling

**MOT #3** 2014-03-14 15:31**MOT test number** 406253574077**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too high (1.8)**Notice** Exhaust system corroded outer skin on rear silencer peeling**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2013-03-05 15:41**MOT test number** 186754163087**Result** ✓ Passed**MOT #1** 2013-03-04 14:57**MOT test number** 989513463080**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside Front brake disc in such a condition that it is seriously weakened (3.5.1i)**Fail** Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
1 June 2024

Tax status	Valid until 1 June
Days left	34
MOT expiry date	1 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	YR10MZJ
Plate since	2020-03-28
Current registration	YR10MZJ
Plate since	2020-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-03-30
Last registration	2023-06-02
Complete history	See info



Registration #1	2010-03-30	13 mi
Registration #2	2013-03-04	27.571 mi
Registration #3	2013-03-05	27.571 mi
Registration #4	2014-03-14	31.543 mi
Registration #5	2015-03-31	35.549 mi
Registration #6	2016-03-30	44.951 mi
Registration #7	2016-12-08	51.038 mi
Registration #8	2017-09-21	53.374 mi
Registration #9	2017-09-21	53.374 mi
Registration #10	2017-12-12	53.392 mi
Registration #11	2018-03-20	55.377 mi
Registration #12	2018-03-20	55.377 mi
Registration #13	2018-03-20	55.377 mi
Registration #14	2018-03-20	55.377 mi
Registration #15	2018-03-20	55.377 mi
Registration #16	2018-03-20	55.377 mi
Registration #17	2018-03-20	55.377 mi
Registration #18	2018-03-20	55.377 mi
Registration #19	2018-03-20	55.377 mi
Registration #20	2018-03-20	55.377 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1702 mm
Height	1505 mm
Length	3620 mm
Wheel base	2300 mm
Kerb weight	940 kg
Max. allowed weight	1320 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	5653452