




report date: 2024-03-28

General information

Make	MAZDA
Model	MX-5 I ROADSTER SPORT BLACK
Colour	Grey
Year of manufacture	2012
Top speed	136 mph
0 - 60 mph	7.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	158 BHP
Max. torque	188 Nm at 5.000 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.9 mpg
Consumption extra urban	47.9 mpg
Consumption combined	37.2 mpg
CO2 emission	181 g/km
CO2 label	I






Internet history

Entry 3

Date	2021-07-27
Pictures	18
Listing price	View report



source: yesauto.com

Entry 2

Date	2021-07-15
Pictures	1
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-05-29
Pictures	19
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-13
MOT pass rate	90 %
MOT passed	9
Failed MOT tests	1
Total advice items	21
Total items failed	2

MOT #10	2023-06-24 11:34
MOT test number	488797226689
Result	✓ Passed
Next expiry date	2024-07-13

MOT #9	2022-07-02 11:29
MOT test number	169346742330
Result	✓ Passed

MOT #8	2021-07-14 14:24
MOT test number	167436267752
Result	✓ Passed

MOT #7	2020-06-17 13:57
MOT test number	636106220570
Result	✓ Passed

MOT #6	2019-06-18 13:42
MOT test number	441028527081
Result	✓ Passed



MOT #5	2018-06-20 15:46
MOT test number	179869402127
Result	✓ Passed

MOT #4	2017-06-09 09:46
MOT test number	758517587722
Result	✓ Passed

- Advice** Offside Rear tyre starting to crack in treads & sidewalls
- Advice** Vehicles internal headlight adjuster altered to recheck lights
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front tyre starting to crack in treads & sidewalls
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear tyre starting to crack in treads & sidewalls
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front tyre starting to crack in treads & sidewalls



MOT #3	2017-06-09 08:36
MOT test number	809820118436
Result	✗ Failed
Advice	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Nearside Front tyre starting to crack in treads & sidewalls
Fail	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Advice	Nearside Rear tyre starting to crack in treads & sidewalls
Fail	Offside Headlamp aim too high (1.8)
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Offside Front tyre starting to crack in treads & sidewalls
Advice	Vehicles internal headlight adjuster altered to recheck lights
Advice	Offside Rear tyre starting to crack in treads & sidewalls
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #2	2016-06-09 14:28
MOT test number	370779698772
Result	✓ Passed
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Undertray fitted
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #1	2015-06-18 14:49
MOT test number	307109765158
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 January 2025

✓
MOT

Expires:
13 July 2024

Tax status Valid until 1 January

Days left 248

MOT expiry date 13 July 2024

Full MOT history [See MOT history](#)

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	YX12 FCL
Plate since	2024-03-28
Current registration	YX12 FCL
Plate since	2024-03-28

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled. If not, and you buy this MAZDA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this MAZDA is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-06-21
Last registration	2023-06-24
Complete history	See info



Registration #1	2012-06-21	13 mi
Registration #2	2015-06-18	16.470 mi
Registration #3	2016-06-09	20.185 mi
Registration #4	2017-06-09	24.130 mi
Registration #5	2017-06-09	24.130 mi
Registration #6	2018-06-20	26.840 mi
Registration #7	2019-06-18	28.824 mi
Registration #8	2019-06-18	28.824 mi
Registration #9	2019-06-18	28.824 mi
Registration #10	2019-06-18	28.824 mi
Registration #11	2019-06-18	28.824 mi
Registration #12	2019-06-18	28.824 mi
Registration #13	2019-06-18	28.824 mi
Registration #14	2019-06-18	28.824 mi

[More info >](#)



Safety ratings

NCAP rating ★★★★☆
Video [see crash video](#)



Dimensions & weight

Width	1720 mm
Height	1245 mm
Length	4020 mm
Wheel base	2330 mm
Kerb weight	1173 kg
Max. allowed weight	1375 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	LF 20410082