





report date: 2024-03-28

General information

Make	VOLVO
Model	XC60 D4 SE NAV
Colour	Grey
Year of manufacture	2017
Top speed	130 mph
0 - 60 mph	7.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	188 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.969 сс
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	67.3 mpg
Consumption combined	62.8 mpg
CO2 emission	117 g/km
CO2 label	С



CarCheck.co.uk page 1/11



Internet history

Entry 1

Date	2021-02-06	
Pictures	1	
Listing price	<u>View report</u>	



source: autoonline.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2025-02-27
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	9
Total items failed	1

MOT #7	2024-02-21 10:27
MOT test number	607301282380
Result	✓ Passed
Next expiry date	2025-02-27
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #6	2023-02-28 14:32
MOT test number	249431198711
Result	✓ Passed

MOT #5	2023-02-27 14:36
--------	------------------

MOT test number 812055187618

Result X Failed

DANGEROUS Offside Front Outer Tyre has a tear, caused by separation or partial failure of its structure this tyre is also worn on the inner edge close to exposing cords (5.2.3 (d) (ii))

DANGEROUS Offside Rear Outer Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

DANGEROUS Nearside Rear Outer Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

DANGEROUS Nearside Front Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #4	2022-02-25 09:30
MOT test number	595435492026
Result	✓ Passed

CarCheck.co.uk page 3/11



AV67BXU

report date: 2024-03-28

MOT #3 2021-02-26 11:08

MOT test number 741484449108

Result
✓ Passed

MOT #2 2020-07-30 08:41

MOT test number 797300360285

Result ✓ Passed

Advice Vehicles internal headlight adjuster altered to recheck lights

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #1 2020-07-30 08:41

MOT test number 217170521820

Result X Failed

Advice Vehicles internal headlight adjuster altered to recheck lights

Pass with rectification Offside Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 4/11



AV67BXU

report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	27 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
First licence fee (12 months)	£ 210,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



AV67BXU

report date: 2024-03-28

Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.)

	More info	>
Plate changes		
See in this check if this VOLVO had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info


More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-09-08
Last registration	2024-02-21
Complete history	See info



Registration #1	2017-09-08	9 mi
Registration #2	2020-07-30	37.749 mi
Registration #3	2020-07-30	37.749 mi
Registration #4		11.777 es
Registration #5	2021-02-26	38.510 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es

More info >

CarCheck.co.uk page 10/11



Car features

50225	Air conditionin
50295	
50482	
50501	
60566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2120 mm
Height	1713 mm
Length	4644 mm
Wheel base	2774 mm
Kerb weight	1750 kg
Max. allowed weight	2485 kg

Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/1

Number of axles 2
Engine number 2112011