





General information

Make	VOLKSWAGEN
Model	POLO MATCH (70BHP)
Colour	Red
Year of manufacture	2009
Top speed	104 mph
0 - 60 mph	14.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	70 BHP
Max. torque	112 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	37.2 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	138 g/km
CO2 label	E





Internet history	
Entry 1	
Date	2021-02-06
Pictures	1
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2025-03-26
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	5
Total items failed	3

MOT #15	2024-03-20 15:58
MOT test number	341180535723
Result	✓ Passed
Next expiry date	2025-03-26
Advice Rear hand brake travel	

MOT #14		2024-03-20 15:58
MOT test number		806303294733
Result		🗙 Failed
Advice Rear hand brake	e travel	
Pass with rectification (4.1.2 (c))	Nearside Front Headlamp aim projected beam image	e is obviously incorrect

MOT #13	2023-03-27 19:52
MOT test number	703748010053
Result	✓ Passed
Advice Rear exhaust box outer skin corroded	

MOT #12	2022-03-24 13:25
MOT test number	883484884502
Result	✓ Passed
Advice Suspension arm pin or bush worn but not resulting in excessive (5.3.4 (a) (i))	movement both console bushes





MOT #11	2021-03-22 11:34
MOT test number	483324282026
Result	✓ Passed
MOT #10	2020-06-23 11:40
MOT test number	687630591195
Result	✓ Passed
MOT #9	2019-06-19 09:42
MOT test number	390471283388
Result	✓ Passed
MOT #8	2018-06-20 10:07
MOT test number	492864003468
Result	✓ Passed
MOT #7	2017-06-21 11:41
MOT test number	816744886848
Result	✓ Passed
МОТ #6	2016-06-22 10:33
MOT test number	690414605678
Result	✓ Passed
MOT #5	2015-06-10 10:54
MOT test number	895521565105
Result	✓ Passed
MOT #4	2014-06-12 12:52
MOT #4 MOT test number	
	319703564141
Result	Passed





MOT #3	3 2014-06-11 13:06
MOT te	st number 775982664176
Result	× Failed
Fail	Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)
Fail	Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

MOT #2	2013-06-07 11:37
MOT test number	909578053172
Result	✓ Passed
Notice H'brake long	
MOT #1	2012-06-27 13:15

MOT test number	898159472100
Result	✓ Passed



Tax & MOT check

Tax due: 1 March 2025	✓ Taxed	✓ MOT Expires: 26 March 2025
Tax status		Valid until 1 March
Days left		305
MOT expiry date		26 March 2025
Full MOT history		See MOT history
Tax calculation		

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEED ON
Category	Lamp
Туре	
Damage 2	AMPLE
Date	
Date	OLE I
Category	AM
Туре	

Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.700
Auction value	4 10.000
Average private trade value	4 10 700

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Rumber of plates	,
Rumber of plates Carrent registration	
Rumber of plates Carrent registration Fals since	
Rumber of protes Current registration Current registration	
Rumber of plates Carrent registration Fate since Fate since Fate since	1000-20-20





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-07-03
Last registration	2024-03-20
Complete history	<u>See info</u>



Registration #1	2009-07-03	24 mi
Registration #2	2012-06-27	9.111 mi
Registration #3	2013-06-07	11.739 mi
Registration #4	2014-06-11	14.654 mi
Registration #5	2014-06-12	14.654 mi
Registration #6	2015-06-10	16.588 mi
Registration #7	2016-06-22	18.340 mi
Registration #8	2017-06-21	19.819 mi
Registration #9	2018-06-20	20.874 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 est
Registration #17		11.777 mi

More info \rightarrow





Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating

Video

**** see crash video



Dimensions & weight

Width	1650 mm
Height	1467 mm
Length	3916 mm
Wheel base	2466 mm
Max. allowed weight	1570 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
CarCheck.co.uk	page 12/12

Engine number

BZG258667