



R70JHB

report date: 2024-03-29

General information

Make	FIAT
Model	500 C C LOUNGE
Colour	Red
Year of manufacture	2009
Top speed	99 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 6.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	44.1 mpg
Consumption extra urban	65.7 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2022-02-18
Pictures	7
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-01-27
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	13
Total items failed	13

MOT #17	2023-01-09 09:52
MOT test number	496876741466
Result	✓ Passed
Next expiry date	2024-01-27

MOT #16	2023-01-04 15:13
MOT test number	794846084190
Result	✗ Failed
Fail	Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #15	2022-01-28 12:40
MOT test number	831613907309
Result	✓ Passed

MOT #14	2020-12-11 12:21
MOT test number	202599880564
Result	✓ Passed

MOT #13	2019-11-28 11:56
MOT test number	850577462679
Result	✓ Passed

**MOT #12** 2019-11-25 14:52**MOT test number** 149745403216**Result** ✗ Failed**Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))**MOT #11** 2018-11-12 12:04**MOT test number** 597296960205**Result** ✓ Passed**MOT #10** 2017-11-13 09:29**MOT test number** 810190211814**Result** ✓ Passed**Advice** Nearside washer jet**Advice** Offside rear tyre cracking**MOT #9** 2017-11-06 15:33**MOT test number** 919475200858**Result** ✗ Failed**Advice** Nearside washer jet**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Offside rear tyre cracking**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #8** 2016-11-08 15:21**MOT test number** 956371560172**Result** ✓ Passed**Advice** Both front tyres slightly cracking

**MOT #7** 2016-11-08 15:21**MOT test number** 733917276119**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low (1.8)**Advice** Both front tyres slightly cracking**MOT #6** 2015-09-10 12:58**MOT test number** 274015429994**Result** ✓ Passed**MOT #5** 2015-09-07 16:15**MOT test number** 550364517358**Result** ✗ Failed**Fail** Offside Headlamp aim too low and too far to the right. (1.8)**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**Fail** Front registration plate missing (6.3.1a)**Fail** Front Exhaust has a major leak of exhaust gases (7.1.2)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #4** 2014-07-31 10:49**MOT test number** 749982714241**Result** ✓ Passed**Notice** Thin breather hose split**MOT #3** 2013-08-02 16:38**MOT test number** 846144213256**Result** ✓ Passed**Notice** Rear exhaust silencer outer skin corriding

**MOT #2** 2013-08-02 12:25**MOT test number** 386864913419**Result** ✗ Failed**Fail** Nearside Front brake disc in such a condition that it is seriously weakened (3.5.1i)**Notice** Rear exhaust silencer outer skin corriding**Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**Fail** Offside Front brake disc in such a condition that it is seriously weakened (3.5.1i)**MOT #1** 2012-08-09 12:31**MOT test number** 747032622287**Result** ✓ Passed**Notice** Exhaust back box outer skin starting to corrode**Notice** Front brake discs lipped**Notice** Nail in o/s/r tyre



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✗  
**MOT**  
**Expired:**  
27 January 2024

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	247
<b>MOT expiry date</b>	27 January 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-09-19
Last registration	2023-01-09
Complete history	<a href="#">See info</a>



Registration #1	2009-09-19	12 mi
Registration #2	2012-08-09	21.787 mi
Registration #3	2013-08-02	25.247 mi
Registration #4	2013-08-02	25.247 mi
Registration #5	2014-07-31	30.691 mi
Registration #6	2015-09-07	35.515 mi
Registration #7	2015-09-10	35.517 mi
Registration #8	2016-11-08	40.108 mi
Registration #9	2016-11-08	40.108 mi
Registration #10	2017-11-06	52.388 mi
Registration #11	2019-05-29	55.377 mi
Registration #12	2019-05-29	55.377 mi
Registration #13	2019-05-29	55.377 mi
Registration #14	2019-05-29	55.377 mi
Registration #15	2019-05-29	55.377 mi
Registration #16	2019-05-29	55.377 mi
Registration #17	2019-05-29	55.377 mi
Registration #18	2019-05-29	55.377 mi
Registration #19	2019-05-29	55.377 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	905 kg
Max. allowed weight	1320 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	5167321