




General information

Make	FORD
Model	GRAND C-MAX SPORT
Colour	Silver
Year of manufacture	2011
Top speed	109 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.2 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-12-04
Pictures	21
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-23
MOT pass rate	61 %
MOT passed	11
Failed MOT tests	7
Total advice items	23
Total items failed	11

MOT #18	2023-11-22 14:52
MOT test number	244251353333
Result	✓ Passed
Next expiry date	2024-11-23

MOT #17	2023-11-22 14:52
MOT test number	119078058555
Result	✗ Failed
Pass with rectification	Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #16	2022-11-17 15:14
MOT test number	254153562544
Result	✓ Passed
Advice	Nearside Front Play in steering rack inner joint(s)

**MOT #15** 2022-11-17 11:18**MOT test number** 992895325006**Result** ✗ Failed**Fail** Offside Front Steering linkage ball joint has excessive play excessive play inner ball joint (2.1.3 (b) (i))**Fail** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Nearside Front Play in steering rack inner joint(s)**Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #14** 2021-11-24 17:31**MOT test number** 361003162651**Result** ✓ Passed**MOT #13** 2021-02-24 12:06**MOT test number** 175041574893**Result** ✓ Passed**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Offside Rear Seat belt slightly damaged (7.1.2 (b) (i))**MOT #12** 2021-02-24 11:10**MOT test number** 770439660424**Result** ✗ Failed**Advice** Offside Rear Seat belt slightly damaged (7.1.2 (b) (i))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**MOT #11** 2020-02-25 13:52**MOT test number** 693112069429**Result** ✓ Passed



MOT #10	2019-02-21 16:13
MOT test number	826120284997
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9	2019-02-21 16:13
MOT test number	844412555897
Result	✗ Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Pass with rectification	Offside Front Steering arm modified such that the steering is adversely affected (2.1.3 (f) (ii))

MOT #8	2018-02-19 12:08
MOT test number	685266738559
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin replaced at time of test (3.5.1g)

MOT #7	2018-02-19 12:08
MOT test number	372951431380
Result	✗ Failed
Pass with rectification	Offside Front Steering arm has relative movement at its fixings (2.2.B.1h)
Advice	Front Brake pad(s) wearing thin replaced at time of test (3.5.1g)

MOT #6	2017-02-23 15:11
MOT test number	805341805660
Result	✓ Passed
Advice	CAM BELT HISTORY?

**MOT #5** 2017-02-23 15:10**MOT test number** 547594253307**Result** ✗ Failed**Pass with rectification** Central Rear Seat belt affected by a damaged seat frame (5.2.1b)**Advice** CAM BELT HISTORY?**Pass with rectification** Brake pedal anti-slip provision missing (3.3.A.1b)**MOT #4** 2016-02-22 16:33**MOT test number** 870427600509**Result** ✓ Passed**Advice** Clutch heavy**MOT #3** 2016-02-22 11:51**MOT test number** 222470010972**Result** ✗ Failed**Fail** Nearside Rear Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Clutch heavy**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nail through side wall of near side rear tyre**MOT #2** 2015-02-25 11:21**MOT test number** 696656055008**Result** ✓ Passed**Notice** Exhaust heat shields damaged and ripped from floor due to vehicle hitting the ground.**Notice** Near side sill trim is missing



MOT #1	2014-02-26 11:23
MOT test number	407977154057
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
23 November 2024

Tax status	Valid until 1 December
Days left	216
MOT expiry date	23 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	PO11FLG
Plate since	2019-03-28
Current registration	PO11FLG
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2011-03-01
Last registration	2023-11-22
Complete history	See info



Registration #1	2011-03-01	27 mi
Registration #2	2014-02-26	41.256 mi
Registration #3	2015-02-25	55.727 mi
Registration #4	2016-02-22	66.998 mi
Registration #5	2016-02-22	66.998 mi
Registration #6	2017-02-23	74.961 mi
Registration #7	2017-02-23	74.961 mi
Registration #8	2018-02-19	85.010 mi
Registration #9	2018-02-19	85.010 mi
Registration #10	2019-02-21	94.605 mi
Registration #11	2019-02-21	94.605 mi
Registration #12	2019-02-21	94.605 mi
Registration #13	2019-02-21	94.605 mi
Registration #14	2019-02-21	94.605 mi
Registration #15	2019-02-21	94.605 mi
Registration #16	2019-02-21	94.605 mi
Registration #17	2019-02-21	94.605 mi
Registration #18	2019-02-21	94.605 mi
Registration #19	2019-02-21	94.605 mi
Registration #20	2019-02-21	94.605 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1840 mm
Height	1497 mm
Length	4342 mm
Max. allowed weight	1820 kg

Additional information

Number of seats	5
Number of axles	2
Engine number	BD15357