



report date: 2024-03-29

General information

Make	CITROEN
Model	C5 HDI VTR PLUS
Colour	Grey
Year of manufacture	2013
Top speed	130 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	160 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	65.7 mpg
Consumption combined	55.4 mpg
CO2 emission	133 g/km
CO2 label	E





Internet history

Entry 1

Date	2022-02-27
Pictures	1
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

<b>MOT expiry date</b>	2024-11-03
<b>MOT pass rate</b>	80 %
<b>MOT passed</b>	8
<b>Failed MOT tests</b>	2
<b>Total advice items</b>	19
<b>Total items failed</b>	6

<b>MOT #10</b>	2023-11-04 17:49
<b>MOT test number</b>	898822910995
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2024-11-03

<b>MOT #9</b>	2022-08-17 15:42
<b>MOT test number</b>	870436770525
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
<b>Advice</b>	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

<b>MOT #8</b>	2021-07-15 13:42
<b>MOT test number</b>	284001236417
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Engine covers fitted obscuring testable components
<b>Advice</b>	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Minor</b>	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
<b>Advice</b>	Under trays fitted obscuring testable components

**MOT #7** 2021-07-15 12:18**MOT test number** 680410042115**Result** ✗ Failed**Advice** Engine covers fitted obscuring testable components**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Under trays fitted obscuring testable components**Fail** Nearside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2020-07-14 18:07**MOT test number** 587356758884**Result** ✓ Passed**MOT #5** 2019-07-12 08:47**MOT test number** 261551234270**Result** ✓ Passed**MOT #4** 2019-07-10 11:05**MOT test number** 433159100947**Result** ✗ Failed**Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Nearside Headlamp aim not tested (4.1.2 (b))**Fail** Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))**Fail** Offside Headlamp aim too high (4.1.2 (a))**Fail** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

**MOT #3** 2018-03-06 14:36**MOT test number** 267809301644**Result** ✓ Passed**Advice** Engine covers and under shields fitted covering some items**MOT #2** 2017-03-08 16:02**MOT test number** 778682077419**Result** ✓ Passed**Advice** Engine cover and undertray fitted obscuring some components**MOT #1** 2016-03-07 09:35**MOT test number** 537335466565**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Undertrays fitted**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
3 November 2024

<b>Tax status</b>	Valid until 1 December
<b>Days left</b>	216
<b>MOT expiry date</b>	3 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-03-28
Last registration	2023-11-04
Complete history	<a href="#">See info</a>



Registration #1	2013-03-28	7 mi
Registration #2	2016-03-07	35.071 mi
Registration #3	2017-03-08	49.402 mi
Registration #4	2018-03-06	62.715 mi
Registration #5	2019-07-10	78.341 mi
Registration #6	2019-07-12	78.341 mi
Registration #7	2019-07-12	78.341 mi
Registration #8	2019-07-12	78.341 mi
Registration #9	2019-07-12	78.341 mi
Registration #10	2019-07-12	78.341 mi
Registration #11	2019-07-12	78.341 mi
Registration #12	2019-07-12	78.341 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	83%
Pedestrian	40%
Safety systems	97%
Overall rating	79%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1860 mm
Height	1512 mm
Length	4289 mm
Wheel base	2815 mm
Kerb weight	1595 kg
Max. allowed weight	2238 kg

Additional information

Fuel tank capacity	71 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	DYZE4057041