





General information

| Make | VOLVO |
|---------------------|--------------------------|
| Model | V40 D3 MOMENTUM NAV PLUS |
| Colour | Grey |
| Year of manufacture | 2019 |
| Top speed | 127 mph |
| 0 - 60 mph | 8.0 seconds |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| Power | 150 BHP |
|----------------------|---------------------|
| Max. torque | 320 Nm at 3.000 rpm |
| Engine capacity | 1.969 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption combined | 61.4 mpg |
| CO2 emission | 118 g/km |
| CO2 label | С |





Internet history

Entry 1

Date

2022-03-20

7

Pictures

Listing price

View report









source: cargurus.co.uk



MOT history

| MOT expiry date | 2025-01-27 |
|--------------------|------------|
| MOT pass rate | 100 % |
| MOT passed | 3 |
| Failed MOT tests | 0 |
| Total advice items | 2 |
| Total items failed | 0 |

| MOT #3 | 2024-01-22 08:54 |
|------------------|------------------|
| MOT test number | 921206636344 |
| Result | ✓ Passed |
| Next expiry date | 2025-01-27 |

| MOT #2 | | 2023-01-26 09:23 |
|------------|--|------------------|
| MOT test r | number | 819355614170 |
| Result | | ✓ Passed |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #1 | 2022-01-28 11:40 |
|-----------------|------------------|
| MOT test number | 926537524597 |
| Result | ✓ Passed |





Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|-------------|
| Date | FER I |
| Category | A PLANE |
| Туре | |
| Damage 2 | AMPLE |
| Damage 2 | E Stand |
| Date | * |
| Category | ante. |
| Туре | |

Extra VOLVO salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4.00.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second s | |
|---|-------------|
| ********** | |
| ******** | |
| ******* | |
| ********* | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this VOLVO had different number plates. | |
| Number of plates | , |
| Carrent registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | More info > |





Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.


| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 5 |
| First mileage registration | 2019-03-06 |
| Last registration | 2024-01-22 |
| Complete history | See info |



| Registration #1 | 2019-03-06 | 6 mi |
|-----------------|------------|------------|
| Registration #2 | 2022-01-28 | 7.549 mi |
| Registration #3 | | 11.777 est |
| Registration #4 | | 11.777 est |
| Registration #5 | | 11.777 mi |





Car features

| S0225 | Air conditioning |
|--------|------------------|
| \$0295 | |
| S0482 | |
| \$0501 | |
| \$0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 98% |
| Children | 75% |
| Pedestrian | 88% |
| Safety systems | 100% |
| Overall rating | 92% |
| Video | see crash video |



| Dimensions & weight | |
|------------------------|------------------|
| Width | 2041 mm |
| Height | 1439 mm |
| Length | 4369 mm |
| Wheel base | 2647 mm |
| Max. allowed weight | 1995 kg |
| Additional information | |
| Fuel tank capacity | 62 I |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| | |

Engine number

2933731