



report date: 2024-03-29

General information

Make	FORD
Model	FOCUS C-MAX GHIA TDCI
Colour	Silver
Year of manufacture	-
Top speed	124 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	48.7 mpg





LABEL UNKNOWN



## Internet history

### Entry 3

Date	2022-12-10
Pictures	20
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

### Entry 2


Date	2022-01-25
Pictures	16
Listing price	<a href="#">View report</a>



source: [yesauto.com](https://www.yesauto.com)

### Entry 1

Date	2021-09-28
Pictures	17
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)



## MOT history

MOT #19	2022-12-06 12:54
MOT test number	491841453885
Result	✓ Passed
Next expiry date	2023-12-05
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
Minor	Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #18	2022-12-01 14:28
MOT test number	385138824305
Result	✗ Failed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Minor	Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Fail	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Fail	Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
Pass with rectification	Offside Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #17	2020-09-23 11:02
MOT test number	554729576169
Result	✓ Passed

**Advice**

Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

**Advice**

Nearside Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))

**MOT #16** 2020-09-23 11:02**MOT test number** 122735909648**Result** ✗ Failed

**Advice** Nearside Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))

**Pass with rectification** Offside Rear Position lamp not working (4.2.1 (a) (ii))

**Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

**MOT #15** 2019-10-08 11:31**MOT test number** 328962750132**Result** ✓ Passed**MOT #14** 2019-10-05 10:43**MOT test number** 518626616199**Result** ✗ Failed

**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))

**Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

**Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

**Fail** Offside Rear Position lamp not working (4.2.1 (a) (ii))

**MOT #13** 2018-10-08 10:34**MOT test number** 102331693611**Result** ✓ Passed

**Advice** Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))

**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**Minor** Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))

**MOT #12** 2018-10-05 11:42**MOT test number** 700870729651**Result** ✗ Failed**Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Minor** Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))**MOT #11** 2017-09-21 10:38**MOT test number** 800115699634**Result** ✓ Passed**MOT #10** 2016-09-28 10:24**MOT test number** 310182492406**Result** ✓ Passed**MOT #9** 2015-09-29 13:52**MOT test number** 530867626317**Result** ✓ Passed**MOT #8** 2014-09-30 11:35**MOT test number** 199833074284**Result** ✓ Passed

**MOT #7** 2013-09-21 15:24**MOT test number** 555644663242**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2012-09-22 15:32**MOT test number** 236426062229**Result** ✓ Passed**MOT #5** 2011-09-16 14:38**MOT test number** 316629951462**Result** ✓ Passed**Notice** N/s/rear wheel bearing slightly noisy**MOT #4** 2010-09-23 12:59**MOT test number** 393736160453**Result** ✓ Passed**MOT #3** 2009-09-17 14:44**MOT test number** 921210969272**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2008-09-16 15:25**MOT test number** 311550368235**Result** ✓ Passed



MOT #1	2007-09-13 15:05
MOT test number	370936457288
Result	✓ Passed





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	EK54PPF
Plate since	2019-03-29
Current registration	EK54PPF
Plate since	2019-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2004-09-25
Last registration	2022-12-06
Complete history	<a href="#">See info</a>



Registration #1	2004-09-25	9 mi
Registration #2	2007-09-13	26.361 mi
Registration #3	2008-09-16	33.165 mi
Registration #4	2009-09-17	38.715 mi
Registration #5	2010-09-23	47.552 mi
Registration #6	2011-09-16	56.024 mi
Registration #7	2012-09-22	64.098 mi
Registration #8	2013-09-21	70.370 mi
Registration #9	2014-09-30	74.687 mi
Registration #10	2015-09-29	77.996 mi
Registration #11	2016-09-28	82.194 mi
Registration #12	2017-09-21	86.587 mi
Registration #13	2018-09-20	91.077 mi
Registration #14	2019-09-19	95.767 mi
Registration #15	2020-09-18	100.657 mi
Registration #16	2021-09-17	105.747 mi
Registration #17	2022-09-16	111.037 mi
Registration #18	2023-09-15	116.527 mi
Registration #19	2024-09-14	122.217 mi
Registration #20	2025-09-13	128.107 mi
Registration #21	2026-09-12	134.197 mi
Registration #22	2027-09-11	140.487 mi
Registration #23	2028-09-10	146.977 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1783 mm
Height	1558 mm
Length	4333 mm
Wheel base	2640 mm
Kerb weight	1523 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number	4A71795