



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	EOS TDI SE
Colour	Red
Year of manufacture	2008
Top speed	127 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	156 g/km
CO2 label	G







Internet history

Entry 2

Date	2023-12-13
Pictures	8



source: g3remarketing.co.uk

Entry 1

Date	2021-02-06
Pictures	6
Listing price	<a href="#">View report</a>



source: autoonline.co.uk



MOT history

MOT expiry date	2025-01-04
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	16
Total items failed	6

MOT #12	2024-01-05 14:04
MOT test number	384857041318
Result	✓ Passed
Next expiry date	2025-01-04
Advice	Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
Advice	Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #11	2022-09-13 12:43
MOT test number	840576007823
Result	✓ Passed

MOT #10	2022-09-10 08:34
MOT test number	276478358459
Result	✗ Failed
Fail	Rear Service brake excessively binding both sides (1.2.1 (f))
Fail	Electronic stability control warning lamp indicates a fault (7.12 (e))

**MOT #9** 2017-10-07 12:00**MOT test number** 882641918788**Result** ✓ Passed

- Advice** Brake disc worn, pitted or scored, but not seriously weakened Both front (3.5.1i)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement Rear bush (2.4.G.2)
- Advice** Nearside Front Brake hose slightly chafed (3.6.B.4d)

**MOT #8** 2016-09-17 08:14**MOT test number** 336856515291**Result** ✓ Passed

- Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Brake disc worn, pitted or scored, but not seriously weakened both front (3.5.1i)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)
- Advice** Nearside Rear Nail in tyre
- Advice** Brake disc worn, pitted or scored, but not seriously weakened both rear (3.5.1i)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

**MOT #7** 2015-10-07 13:39**MOT test number** 429719759441**Result** ✓ Passed**MOT #6** 2015-10-05 14:26**MOT test number** 765676677597**Result** ✗ Failed

- Fail** Offside Rear Stop lamp not working (1.2.1b)

**MOT #5** 2013-10-04 12:24**MOT test number** 389907973221**Result** ✓ Passed**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Headlamp damaged but light output not reduced (1.7.5a)**MOT #4** 2013-10-03 13:20**MOT test number** 626076573262**Result** ✗ Failed**Fail** Offside Rear Mechanical brake component has restricted free movement (3.5.1k)**Advice** Offside Front Headlamp damaged but light output not reduced (1.7.5a)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2012-01-26 13:25**MOT test number** 806556922009**Result** ✓ Passed**MOT #2** 2012-01-26 10:26**MOT test number** 379766922092**Result** ✗ Failed**Fail** Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**MOT #1** 2011-03-03 10:18**MOT test number** 225432761099**Result** ✓ Passed



Tax & MOT check

✗  
**Untaxed**

**Tax expired:**  
14 October 2022

✓  
**MOT**

**Expires:**  
4 January 2025

Tax status

Expired at 14 October 2022

Days left

564 days too late

MOT expiry date

4 January 2025

Full MOT history

[See MOT history](#)

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>SA08CWP</b>
Plate since	2024-03-29
Current registration	 <b>SA08CWP</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2008-03-05
Last registration	2024-01-05
Complete history	<a href="#">See info</a>



Registration #1	2008-03-05	11 mi
Registration #2	2011-03-03	44.093 mi
Registration #3	2012-01-26	59.295 mi
Registration #4	2012-01-26	59.296 mi
Registration #5	2013-10-03	71.446 mi
Registration #6	2013-10-04	71.446 mi
Registration #7	2015-10-05	80.124 mi
Registration #8	2019-05-20	95.277 mi
Registration #9	2019-05-20	95.277 mi
Registration #10	2019-05-20	95.277 mi
Registration #11	2019-05-20	95.277 mi
Registration #12	2019-05-20	95.277 mi
Registration #13	2019-05-20	95.277 mi
Registration #14	2019-05-20	95.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1517 mm
Length	4774 mm
Wheel base	2709 mm
Kerb weight	1715 kg
Max. allowed weight	2140 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	BKP 293807