



PEUGEOT

OE63GVP


report date: 2024-03-29

General information

Make	PEUGEOT
Model	PARTNER HDI S L1 850
Colour	White
Year of manufacture	2013
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
CO2 emission	138 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-02-03
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://autoonline.co.uk)



MOT history

MOT expiry date	2023-12-01
MOT pass rate	58 %
MOT passed	7
Failed MOT tests	5
Total advice items	18
Total items failed	17

MOT #122024-01-04 16:18

MOT test number463692569585

ResultX Failed

- AdviceFront Brake disc worn, but not excessively (1.1.14 (a) (i))
- AdviceVehicle has corrosion underneath
- FailExhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
- FailOffside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- FailExhaust on a vehicle fitted with a diesel particulate filter emits visible smoke of any colour (8.2.2.2 (d))

MOT #112022-11-15 13:46

MOT test number760309093409

Result✓ Passed

**MOT #10**

2022-11-14 13:45

**MOT test number**

330169321954

**Result****✗ Failed**

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Brake pedal anti-slip provision missing (1.1.2 (c))
- Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #9**

2021-12-02 16:58

**MOT test number**

869492546748

**Result****✓ Passed****MOT #8**

2020-10-14 11:58

**MOT test number**

664285930883

**Result****✓ Passed**

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Hydraulic leak, but not excessive power steering pipe (8.4.1 (a) (i))

**MOT #7**

2020-10-14 08:45

**MOT test number**

569828110242

**Result****✗ Failed****Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Horn not working (7.7 (a) (ii))**Advice** Offside Front Hydraulic leak, but not excessive power steering pipe (8.4.1 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #6**

2019-11-21 14:40

**MOT test number**

842190587541

**Result****✓ Passed****Advice** Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #5**

2019-11-21 11:09

**MOT test number**

440811085388

**Result****✗ Failed****Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))**Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #4** 2018-11-26 11:06**MOT test number** 845262335682**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #3** 2017-11-28 16:33**MOT test number** 269111528322**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit both (4.1.E.1)**MOT #2** 2016-12-07 13:32**MOT test number** 374164478912**Result** ✓ Passed**MOT #1** 2016-12-07 11:11**MOT test number** 821369959756**Result** ✗ Failed**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)



Tax & MOT check

X

Untaxed

Tax expired:  
6 April 2023

X

MOT

Expired:  
1 December 2023

Tax status	Expired at 6 April 2023
Days left	390 days too late
MOT expiry date	1 December 2023
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-12-31
Last registration	2024-01-04
Complete history	<a href="#">See info</a>



Registration #1	2013-12-31	19 mi
Registration #2	2016-12-07	36.168 mi
Registration #3	2016-12-07	36.168 mi
Registration #4	2017-11-28	48.947 mi
Registration #5	2018-11-26	57.552 mi
Registration #6	2019-11-21	70.553 mi
Registration #7	2019-11-21	70.555 mi
Registration #8	2019-11-21	70.555 mi
Registration #9	2019-11-21	70.555 mi
Registration #10	2019-11-21	70.555 mi
Registration #11	2019-11-21	70.555 mi
Registration #12	2019-11-21	70.555 mi
Registration #13	2019-11-21	70.555 mi
Registration #14	2019-11-21	70.555 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Engine number	JBEM0211217