



PEUGEOT

KVIIIEJO


report date: 2024-03-29

General information

Make	PEUGEOT
Model	107 URBAN
Colour	Black
Year of manufacture	2011
Top speed	98 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	52.3 mpg
Consumption extra urban	70.6 mpg
Consumption combined	62.8 mpg
CO2 emission	103 g/km
CO2 label	B





MOT history

MOT expiry date	2025-02-07
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	20
Total items failed	15

MOT #13 2024-01-24 09:23

MOT test number 501978728283

Result ✓ Passed

Next expiry date 2025-02-07

- Advice** Offside Rear Outer Integral body structure is corroded but structural rigidity is not significantly reduced sill (6.1.1 (c) (i))
- Advice** Nearside side repeater lens missing
- Advice** Nearside Front Road wheel slightly distorted inner rim (5.2.2 (c) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #12 2024-01-23 12:35

MOT test number 441448103249

Result ✗ Failed

- Advice** Nearside Front Road wheel slightly distorted inner rim (5.2.2 (c) (i))
- Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Offside Rear Outer Integral body structure is corroded but structural rigidity is not significantly reduced sill (6.1.1 (c) (i))
- Advice** Nearside side repeater lens missing
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #11**

2023-02-08 13:52

MOT test number

352508772748

Result

✓ Passed

Advice Electric power steering malfunction lamp on at start of test extinguished at end of test**Advice** Nearside Front Road wheel slightly distorted inside rim (5.2.2 (c) (i))**Advice** Nearside side repeater lens missing**MOT #10**

2023-02-01 11:54

MOT test number

661297649271

Result

✗ Failed

Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Electric power steering malfunction lamp on at start of test extinguished at end of test**Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))**Fail** Exhaust carbon monoxide content at idle exceeds manufacturer's specified limits (8.2.1.2 (b))**Fail** Nearside Front Headlamp levelling device inoperative (4.1.5 (a))**Advice** Nearside Front Road wheel slightly distorted inside rim (5.2.2 (c) (i))**Advice** Nearside side repeater lens missing**Fail** Exhaust hydrocarbon content after 2nd fast idle exceeds default limits (8.2.1.2 (b))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**MOT #9**

2022-02-03 12:12

MOT test number

313492924920

Result

✓ Passed

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #8** 2022-02-02 16:42**MOT test number** 549349651204**Result** ✗ Failed

- Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))
- Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Fail** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Electronic power steering warning lamp indicates a system malfunction (2.6 (a))
- Fail** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

MOT #7 2021-01-27 18:53**MOT test number** 240955578803**Result** ✓ Passed**MOT #6** 2019-04-11 08:38**MOT test number** 521205107355**Result** ✓ Passed**MOT #5** 2018-04-03 08:33**MOT test number** 310796884020**Result** ✓ Passed**MOT #4** 2017-04-06 15:56**MOT test number** 868162639265**Result** ✓ Passed

**MOT #3** 2016-03-18 16:06**MOT test number** 892364845746**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #2 2015-03-20 10:35**MOT test number** 119589375017**Result** ✓ Passed**MOT #1** 2014-03-27 12:38**MOT test number** 818366584089**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
7 February 2025

Tax status	Valid until 1 February
Days left	277
MOT expiry date	7 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-03-28
Last registration	2024-01-24
Complete history	See info



Registration #1	2011-03-28	29 mi
Registration #2	2014-03-27	28.148 mi
Registration #3	2015-03-20	32.643 mi
Registration #4	2016-03-18	37.912 mi
Registration #5	2017-04-06	42.029 mi
Registration #6	2018-04-03	44.779 mi
Registration #7	2019-04-11	47.959 mi
Registration #8	2020-05-20	51.277 mi
Registration #9	2021-05-20	55.277 mi
Registration #10	2022-05-20	59.277 mi
Registration #11	2023-05-20	63.277 mi
Registration #12	2024-01-24	67.277 mi
Registration #13	2024-01-24	71.277 mi
Registration #14	2024-01-24	75.277 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1630 mm
Height	1470 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	905 kg
Max. allowed weight	1190 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	6795922