



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	BEETLE T
Colour	Blue
Year of manufacture	2004
Top speed	125 mph
0 - 60 mph	9.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	150 BHP
Max. torque	220 Nm at 2.000 rpm
Engine capacity	1.781 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.2 mpg
Consumption extra urban	42.8 mpg
Consumption combined	34.0 mpg
CO2 emission	197 g/km
CO2 label	J








Internet history

Entry 1

Date	2021-08-10
Pictures	7
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-19
MOT pass rate	75 %
MOT passed	18
Failed MOT tests	6
Total advice items	33
Total items failed	14

MOT #24	2023-08-15 10:16
MOT test number	799303057681
Result	✓ Passed
Next expiry date	2024-08-19
Advice	Light corrosion across underside of vehicle
Advice	Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
Advice	Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

MOT #23	2023-08-15 10:16
MOT test number	161199755659
Result	✗ Failed
Pass with rectification	Offside Headlamp not working on main beam (4.1.1 (a) (ii))
Advice	Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
Pass with rectification	Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
Advice	Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
Advice	Light corrosion across underside of vehicle

MOT #22	2022-08-20 14:38
MOT test number	576735726644
Result	✓ Passed

**MOT #21** 2021-08-06 15:37**MOT test number** 148949586615**Result** ✓ Passed**MOT #20** 2021-08-04 15:55**MOT test number** 547242756158**Result** ✗ Failed**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**MOT #19** 2020-08-13 13:45**MOT test number** 699887462942**Result** ✓ Passed**Advice** Central Front Exhaust mounting defective (6.1.2 (a))**Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #18** 2019-08-19 12:36**MOT test number** 982729153374**Result** ✓ Passed

**MOT #17**

2019-07-23 08:50

MOT test number

131731982106

Result**✗ Failed**

- Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Exhaust carbon monoxide content at idle exceeds default limits (8.2.1.2 (b))
- Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))
- Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

MOT #16

2018-04-25 09:12

MOT test number

331510812172

Result**✓ Passed****MOT #15**

2017-04-25 10:23

MOT test number

621513112349

Result**✓ Passed**

- Advice** Advise rear axle beam bushes worn
- Advice** Advise o/s/f tyre low on tread
- Advice** Advise front brake discs lipped
- Advice** Advise n/s/f tyre worn smooth on inner edge and has sidewall damage

**MOT #14** 2017-01-23 09:11**MOT test number** 687847806473**Result** ✓ Passed

- Advice** Nearside Rear tyre inner edge out of shape
- Advice** Oil leak
- Advice** Central exhaust shield insecure
- Advice** Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Rear both rear tyres perished on sidewalls
- Advice** Nearside Rear has cut to outer sidewall
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Central exhaust bracket broken

MOT #13 2016-01-25 10:59**MOT test number** 763041942596**Result** ✓ Passed**MOT #12** 2016-01-25 10:59**MOT test number** 730963395083**Result** ✗ Failed

- Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)
- Pass with rectification** Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #11 2015-01-21 13:45**MOT test number** 636591925059**Result** ✓ Passed

- Notice** Slight damage to front wheel rims

**MOT #10** 2015-01-21 12:13**MOT test number** 578321925048**Result** ✗ Failed**Advice** Offside Front Lower Ball joint has slight play (2.2.B.1f)**Notice** Slight damage to front wheel rims**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**MOT #9** 2014-01-14 10:31**MOT test number** 728384914057**Result** ✓ Passed**Notice** Slight damage to both front tyres (outer sidewalls)**MOT #8** 2013-01-03 12:33**MOT test number** 988533703004**Result** ✓ Passed**Notice** O/s/r tyre inner tread uneven and worn low**MOT #7** 2012-09-26 08:14**MOT test number** 825030372220**Result** ✓ Passed**Notice** Kerb damage to alloys**Notice** Engine under tray fitted**Notice** O s r tyre wearing low

**MOT #6** 2011-08-24 13:28**MOT test number** 777956731246**Result** ✓ Passed**Notice** Screen is damaged in o/s bottom corner**Notice** Rear pads low**Notice** N/s/f tyre worn very close to legal limit**MOT #5** 2011-01-13 13:09**MOT test number** 485793511005**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #4** 2010-01-14 14:52**MOT test number** 961904510052**Result** ✓ Passed**MOT #3** 2009-01-13 14:27**MOT test number** 174453819475**Result** ✗ Failed**Pass with rectification** Nearside Rear Direction indicators not working (1.4.A.2c)**Pass with rectification** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #2** 2009-01-13 14:27**MOT test number** 490513119089**Result** ✓ Passed**MOT #1** 2008-01-15 16:05**MOT test number** 223705918043**Result** ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
19 August 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	19 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 VN54WSK
Plate since	2019-06-29
Current registration	 VN54WSK
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2004-11-12
Last registration	2023-08-15
Complete history	See info



Registration #1	2004-11-12	12 mi
Registration #2	2008-01-15	14.358 mi
Registration #3	2009-01-13	18.013 mi
Registration #4	2010-01-14	22.458 mi
Registration #5	2011-01-13	29.076 mi
Registration #6	2011-08-24	33.854 mi
Registration #7	2012-09-26	38.507 mi
Registration #8	2013-01-03	39.483 mi
Registration #9	2014-01-14	43.673 mi
Registration #10	2015-01-21	47.238 mi
Registration #11	2015-01-21	47.240 mi
Registration #12	2016-01-25	51.304 mi
Registration #13	2016-01-25	51.304 mi
Registration #14	2016-01-25	51.304 mi
Registration #15	2016-01-25	51.304 mi
Registration #16	2016-01-25	51.304 mi
Registration #17	2016-01-25	51.304 mi
Registration #18	2016-01-25	51.304 mi
Registration #19	2016-01-25	51.304 mi
Registration #20	2016-01-25	51.304 mi
Registration #21	2016-01-25	51.304 mi
Registration #22	2016-01-25	51.304 mi
Registration #23	2016-01-25	51.304 mi
Registration #24	2016-01-25	51.304 mi
Registration #25	2016-01-25	51.304 mi



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1724 mm
Height	1502 mm
Length	4081 mm
Wheel base	2516 mm
Kerb weight	1481 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2

Engine number

AWU 711395