






report date: 2024-03-28

General information

Make	FORD
Model	TRANSIT 270 LIMITED LR P/V
Colour	Blue
Year of manufacture	2014
Top speed	98 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	92 kW / 125 HP / 123 BHP
Max. torque	330 Nm at 1.500 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	44.1 mpg
Consumption combined	40.4 mpg
CO2 emission	186 g/km
CO2 label	J



CarCheck.co.uk page 1/11



Internet history

Ei	n	tı	r	,	1

Life y 1	
Date	2021-11-17
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2023-10-27
MOT pass rate	100 %
MOT passed	6
Failed MOT tests	0
Total advice items	16
Total items failed	0

MOT #6		2022-10-24 16:48
MOT test number		571935817415
Result		✓ Passed
Next expiry date		2023-10-27
Advice Offside Front Lower rear (5.3.4 (a) (i))	Suspension arm pin or bush worr	boot severely deteriorated (6.1.7 (g) (i)) n but not resulting in excessive movement damaged or deteriorated, but preventing the
ingress of dirt (2.1.3 (g) (i))		

MOT #5	2021-10-28 12:03
MOT test	number 879858033933
Result	✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Advice (d) (ii))	Nearside Front Tyre slightly damaged/cracking or perishing nail in tyre. internal damaged. (5.2.3
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice (5.3.4 (a)	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (i))
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Minor	Nearside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 3/11



 MOT #4
 2020-10-08 07:58

 MOT test number
 226967364836

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3 2019-10-07 08:13

MOT test number 941275963648

Result ✓ Passed

MOT #2 2018-10-06 07:50

MOT test number 414854569789

Result Passed

Advice Front Tyre slightly damaged/cracking or perishing offside and nearside sidewalls (5.2.3 (d) (ii))

MOT #1 2017-10-07 07:56

MOT test number 184637214846

Result ✓ Passed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 4/11



See MOT history

Tax & MOT check

Tax expired: 1 January 2024



Expired: 27 October 2023

X MOT

Tax statusExpired at 1 January 2024Days left119 days too lateMOT expiry date27 October 2023

Tax calculation

Full MOT history

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner	hictor,
UWNEI	nisioiv
OWINCE	THISCOLY

•		
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report I		ave?

	More info	>
Plate changes		
See in this check if this FORD had different number plates.		
Number of plates		,
Current registration	UK NE	
Plate since		
Current registration	UK NE	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2014-08-20
Last registration	2022-10-24
Complete history	See info



Registration #1	2014-08-20	6 mi
Registration #2	2017-10-07	36.348 mi
Registration #3	2018-10-06	48.026 mi
Registration #4	2019-10-07	62.285 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	84%
Children	90%
Pedestrian	48%
Safety systems	71%
Overall rating	76%
Video	see crash video



Dimensions & weight

Width	2272 mm
Height	2020 mm
Length	4972 mm
Wheel base	2933 mm
Kerb weight	1817 kg
Max. allowed weight	2700 kg

Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	3 page 11/1

Number of axles 2

Engine number EP67550