




report date: 2024-03-29

General information

Make	NISSAN
Model	PATHFINDER DCI TEKNA
Colour	Grey
Year of manufacture	2011
Top speed	115 mph
0 - 60 mph	11.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	188 BHP
Max. torque	450 Nm at 2.000 rpm
Engine capacity	2.488 cc
Cylinders	4
Fuel type	Diesel
Consumption city	26.2 mpg
Consumption extra urban	39.2 mpg
Consumption combined	33.2 mpg
CO2 emission	224 g/km
CO2 label	K






Internet history

Entry 1

Date	2022-03-05
Pictures	9
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-03-01
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	24
Total items failed	7

MOT #15	2023-03-02 17:00
MOT test number	834177529532
Result	✓ Passed
Next expiry date	2024-03-01
Minor	Central Rear Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))
Advice	Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
Advice	Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #14**

2023-03-01 10:04

MOT test number

174451651668

Result**✗ Failed****DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner and outer edges (5.2.3 (e))**Minor** Central Rear Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))**MAJOR** Reversing lamp inoperative (4.6.1 (a))**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))**MAJOR** Offside Front Service brake excessively binding (1.2.1 (f))**Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #13**

2022-02-10 08:30

MOT test number

662038998548

Result**✓ Passed****MOT #12**

2022-02-03 09:26

MOT test number

669133160939

Result**✗ Failed****MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Rear door cannot be opened from outside**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MAJOR** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #11** 2021-01-29 09:48**MOT test number** 229734696770**Result** ✓ Passed**MOT #10** 2020-01-24 10:40**MOT test number** 503286349914**Result** ✓ Passed**MOT #9** 2019-02-13 12:42**MOT test number** 123605131062**Result** ✓ Passed**MOT #8** 2018-02-16 11:24**MOT test number** 459386870936**Result** ✓ Passed**MOT #7** 2017-02-13 15:38**MOT test number** 798916424312**Result** ✓ Passed**MOT #6** 2017-02-09 12:04**MOT test number** 418400733879**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim too low (1.8)**Pass with rectification** Nearside Front Headlamp aim too low (1.8)**Fail** Offside Rear coil spring broken (2.4.C.1a)**MOT #5** 2016-01-29 12:31**MOT test number** 994495531401**Result** ✓ Passed

**MOT #4** 2015-02-21 12:05**MOT test number** 879012755013**Result** ✓ Passed**MOT #3** 2015-02-21 09:47**MOT test number** 738312955034**Result** ✗ Failed**Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**MOT #2** 2014-04-09 09:29**MOT test number** 239149494038**Result** ✓ Passed**Notice** Rear wiper torn**MOT #1** 2014-03-25 09:31**MOT test number** 297794184032**Result** ✗ Failed**Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Notice** Front bumper skirt loose**Notice** Nail in o/s/r tyre**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**Notice** N/s washer jet low**Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Notice** Rear wiper split



Tax & MOT check

✓
Taxed

Tax due:
1 March 2025

✗
MOT

Expired:
1 March 2024

Tax status	Valid until 1 March
Days left	305
MOT expiry date	1 March 2024
Full MOT history	See MOT history

Tax calculation


Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-03-31
Last registration	2023-03-02
Complete history	See info



Registration #1	2011-03-31	25 mi
Registration #2	2014-03-25	29.319 mi
Registration #3	2014-04-09	29.638 mi
Registration #4	2015-02-21	35.088 mi
Registration #5	2015-02-21	35.088 mi
Registration #6	2016-01-29	44.215 mi
Registration #7	2017-02-09	53.622 mi
Registration #8	2017-02-13	53.633 mi
Registration #9	2018-02-16	61.371 mi
Registration #10	2019-03-20	70.377 mi
Registration #11	2019-03-20	70.377 mi
Registration #12	2019-03-20	70.377 mi
Registration #13	2019-03-20	70.377 mi
Registration #14	2019-03-20	70.377 mi
Registration #15	2019-03-20	70.377 mi
Registration #16	2019-03-20	70.377 mi
Registration #17	2019-03-20	70.377 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1848 mm
Height	1785 mm
Length	4813 mm
Wheel base	2853 mm
Kerb weight	2090 kg
Max. allowed weight	2880 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	711479