





report date: 2024-03-28

General information

| Make | ТОУОТА |
|---------------------|----------------|
| Model | RAV-4 VVTI XT4 |
| Colour | Black |
| Year of manufacture | 2007 |
| Top speed | 115 mph |
| 0 - 60 mph | 10.6 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 150 BHP |
|-------------------------|---------------------|
| Max. torque | 194 Nm at 4.000 rpm |
| Engine capacity | 1.998 сс |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 25.7 mpg |
| Consumption extra urban | 39.2 mpg |
| Consumption combined | 32.8 mpg |
| CO2 emission | 202 g/km |
| CO2 label | K |



CarCheck.co.uk page 1/14



ACO7DAA report date: 2024-03-28

Internet history

Entry 1

Date 2021-12-09

Pictures 22

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-28

MOT history

| MOT expiry date | 2023-11-17 |
|--------------------|------------|
| MOT pass rate | 76 % |
| MOT passed | 13 |
| Failed MOT tests | 4 |
| Total advice items | 34 |
| Total items failed | 9 |

| MOT #17 | | 2022-11-16 12:12 |
|------------|--|------------------|
| MOT test r | number | 320661487289 |
| Result | | ✓ Passed |
| Next expir | y date | 2023-11-17 |
| Advice | Offside Rear Coil spring corroded (5.3.1 (b) (i)) | |
| Advice | Nearside Rear Coil spring corroded (5.3.1 (b) (i)) | |

| MOT #16 | 2022-11-15 16:30 |
|--|---------------------|
| MOT test number | 261006270639 |
| Result | X Failed |
| Fail Offside Registration plate lamp inoperative in the case of a single lamp or all lamp | os (4.7.1 (b) (ii)) |
| Advice Offside Rear Coil spring corroded (5.3.1 (b) (i)) | |
| Fail Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii)) | |
| Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i)) | |

| MOT #15 | 2021-11-18 10:19 |
|--|------------------|
| MOT test number | 122455701984 |
| Result | ✓ Passed |
| Advice Rear Shock absorbers has light misting of oil (5.3.2 (b)) | |

CarCheck.co.uk page 3/14



Result

AC07DAA

report date: 2024-03-28

✓ Passed

MOT #14 2020-12-21 14:08

MOT test number 227868980592

Result
✓ Passed

MOT #13 2019-06-07 08:16

MOT test number 808886708399

Advice Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #12 2018-06-14 14:00

MOT test number 264014228267

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Front brake discs corroded on inner faces

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Front both front wipers leave slight smear

CarCheck.co.uk page 4/14



report date: 2024-03-28

MOT #11 2018-06-13 10:20 365878421480 **MOT** test number Result × Failed Fail Nearside Rear Service brake excessively binding (1.2.1 (f)) Offside Rear Child Seat fitted not allowing full inspection of adult belt **Advice** Fail Nearside Rear Outer Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) Advice Front brake discs corroded on inner faces Advice Offside Rear Coil spring corroded (5.3.1 (b) (i)) Fail Nearside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii)) Front both front wipers leave slight smear **Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i)) **Advice**

| MOT #10 | | 2017-06-15 11:50 |
|----------|---|------------------|
| MOT test | number | 592980652198 |
| Result | | ✓ Passed |
| Advice | Nearside Rear coil spring corroded (2.4.C.1b) | |
| Advice | Rear Exhaust has a minor leak of exhaust gases (7.1.2) | |
| Advice | Offside Rear coil spring corroded (2.4.C.1b) | |
| Advice | Offside Rear Child Seat fitted not allowing full inspection of adult belt | |

CarCheck.co.uk page 5/14



report date: 2024-03-28

MOT #9 2017-06-12 15:44 551766348805 **MOT test number** Result × Failed **Advice** Nearside Rear coil spring corroded (2.4.C.1b) Fail Nearside Rear Anti-roll bar linkage has excessive play in a ball joint broken (2.4.G.2) Fail Nearside Rear Shock absorber has a serious fluid leak (2.7.3) Advice Rear Exhaust has a minor leak of exhaust gases (7.1.2) Offside Rear coil spring corroded (2.4.C.1b) **Advice** Fail Offside Rear Anti-roll bar linkage has excessive play in a ball joint broken (2.4.G.2) Offside Rear Child Seat fitted not allowing full inspection of adult belt **Advice**

| MOT #8 | | 2016-06-15 11:03 |
|----------|---|------------------|
| MOT test | number | 663534722895 |
| Result | | ✓ Passed |
| Advice | Offside Rear coil spring worn (2.4.C.1b) | |
| Advice | Nearside Rear coil spring worn (2.4.C.1b) | |

| Advice Nearside Rear coil spring worn (2.4.C.1b) | |
|--|------------------|
| NOT #7 | 2015 05 01 14.40 |
| MOT #7 | 2015-05-01 14:48 |
| MOT test number | 546971925109 |
| Result | ✓ Passed |
| | |
| MOT #6 | 2014-04-29 16:37 |
| MOT test number | 735709514142 |
| Result | ✓ Passed |
| | |
| MOT #5 | 2013-04-05 12:34 |
| MOT test number | 998665693018 |
| Result | ✓ Passed |

CarCheck.co.uk page 6/14



Fail

AC07DAA

report date: 2024-03-28

MOT #4

MOT test number

216845672195

Result

Notice Fast idle emissions test, slight fluctuation.

Notice Front brake discs slightly corroded and scored.

MOT test number 555363791130

Result ✓ Passed

Advice Offside Rear Shock absorber has a light misting of oil (2.7.3)

Notice Front and rear brake discs slightly corroded, worn, scored, and pitted.

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

 MOT #2
 2010-07-03 14:11

 MOT test number
 920454180133

 Result
 ✓ Passed

MOT #1 2010-07-03 12:52

MOT test number 753044480131

Result X Failed

Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)

CarCheck.co.uk page 7/14



AC07DAA report date: 2024-03-28

Tax & MOT check

Tax expired: 21 October 2023



X **MOT**

Expired: 17 November 2023

Expired at 21 October 2023 **Tax status Days left** 191 days too late **MOT** expiry date 17 November 2023 **Full MOT history** See MOT history

Tax calculation

| Vehicle class | 48 |
|---|------------|
| Band | K |
| Single payment (12 months) | £ 395,00,- |
| Single six month payment | £ 217,25,- |
| Total payable by 12 monthly instalments | £ 414,75,- |

CarCheck.co.uk page 8/14



report date: 2024-03-28

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|--|
| Date | |
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |
| Туре | |



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



ACO7DAA report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-28

Owner history

| For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full | |
|---|-------------|
| | |
| manus . | |
| *************************************** | |
| *************************************** | |
| | |
| manus . | |
| *************************************** | |
| *************************************** | |
| | |
| | More info > |
| | |
| Plate changes | |
| Coo in this shock if this TOVOTA had different number plates | |
| See in this check if this TOYOTA had different number plates. | |
| | |
| Number of plates | , |
| | |
| Current registration | UK ME |
| Flate since | |
| | |
| Current registration | NK SIE |
| Plate since | |
| | |
| | More info > |

CarCheck.co.uk page 11/14



ACO7DAA report date: 2024-03-28

Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-28

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 19 |
| First mileage registration | 2007-06-20 |
| Last registration | 2022-11-16 |
| Complete history | See info |



| Registration #1 | 2007-06-20 | 6 mi |
|------------------|------------|-----------|
| Registration #2 | 2010-07-03 | 42.504 mi |
| Registration #3 | 2010-07-03 | 42.504 mi |
| Registration #4 | 2011-07-12 | 52.977 mi |
| Registration #5 | 2012-06-23 | 62.525 mi |
| Registration #6 | 2013-04-05 | 71.221 mi |
| Registration #7 | 2014-04-29 | 74.128 mi |
| Registration #8 | 2015-05-01 | 80.633 mi |
| Registration #9 | 2016-06-15 | 86.868 mi |
| Registration #10 | 2017-06-12 | 92.517 mi |
| Registration #11 | | 11.777 es |
| Registration #12 | | 11.777 au |
| Registration #13 | | 11.777 es |
| Registration #14 | | 11.777 au |
| Registration #15 | | 11.777 es |
| Registration #16 | | 11.777 au |
| Registration #17 | | 11.777 es |
| Registration #18 | | 11.777 es |
| Registration #19 | | 71,777 au |

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-28

Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| 50482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|-------------|-----------------|
| Video | see crash video |



Dimensions & weight

| Width | 1815 mm |
|---------------------|---------|
| Height | 1685 mm |
| Length | 4395 mm |
| Wheel base | 2560 mm |
| Kerb weight | 1465 kg |
| Max. allowed weight | 2070 kg |

Additional information

| Fuel tank capacity | 60 I |
|-----------------------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 14/1 |

Number of axles 2

Engine number 1AZ5562494