





report date: 2024-03-28

#### General information

Make	VOLVO
Model	XC70 D5 SE LUX NAV AWD
Colour	Silver
Year of manufacture	2015
Top speed	127 mph
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	212 BHP
Max. torque	440 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	32.8 mpg
Consumption extra urban	54.3 mpg
Consumption combined	44.1 mpg
CO2 emission	169 g/km
CO2 label	Н



CarCheck.co.uk page 1/11



report date: 2024-03-28

## Internet history

#### Entry 1

Date 2021-07-28

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



KT64DBX report date: 2024-03-28

	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2024-10-06
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	6
Total items failed	2

MOT #8	2023-10-03 09:58
MOT test number	563256304974
Result	✓ Passed
Next expiry date	2024-10-06

MOT #7	2022-10-03 09:48	3
MOT test	number 129711039083	_
Result	✓ Passed	k
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #6	2021-10-04 09:36
MOT test number	591518734377
Result	✓ Passed

MOT #5	2020-10-07 16:41
MOT test number	765065080605
Result	✓ Passed

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #4 2020-01-17 09:47

**MOT test number** 327236312676

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #3 2020-01-10 13:11

MOT test number 809853069369

**Result** X Failed

**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #2 2019-01-18 10:13

**MOT test number** 637004072232

MOT #1 2018-01-26 10:05

**MOT test number** 958527922821

Result \rightarrow Passed

CarCheck.co.uk page 4/11



report date: 2024-03-28

#### Tax & MOT check



Tax status	Valid until 1 October
Days left	156
MOT expiry date	6 October 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

#### Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

### Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full	
***************************************	
*********	
***************************************	
	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	
Current registration	OK SIE
Plate since	
Current registration	NK NE
Plate since	
	More info

CarCheck.co.uk page 8/11



KT64DBX report date: 2024-03-28

#### Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



KT64DBX report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-01-30
Last registration	2023-10-03
Complete history	See info



Registration #1	2015-01-30	16 mi
Registration #2	2018-01-26	39.134 mi
Registration #3	2019-01-18	59.093 mi
Registration #4	2020-01-10	77.787 mi
Registration #5	2020-01-17	78.232 mi
_		
Registration #6		71.777 es
Registration #6 Registration #7		11.777 ea
-		1.77 m
Registration #7		11,777 es 11,777 es 11,777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

## Safety ratings

NCAP rating	****
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	see crash video



# Dimensions & weight

Width	2119 mm
Height	1604 mm
Length	4838 mm
Wheel base	2815 mm
Kerb weight	1883 kg
Max. allowed weight	2400 kg

## Additional information

Fuel tank capacity	70	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 11/11

Number of axles 2

Engine number 1543773