



report date: 2024-03-28

## General information

Make	VAUXHALL
Model	TIGRA SXI AC 16V
Colour	Red
Year of manufacture	2009
Top speed	107 mph
0 - 60 mph	11.8 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	89 BHP
Max. torque	125 Nm at 4.000 rpm
Engine capacity	1.364 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	56.5 mpg
Consumption combined	46.3 mpg
CO2 emission	146 g/km
CO2 label	F






Internet history

Entry 1

Date	2021-06-27
Pictures	37
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-09
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	16
Total items failed	12

MOT #20	2024-01-10 16:02
MOT test number	958087806278
Result	✓ Passed
Next expiry date	2025-01-09

MOT #19	2024-01-04 17:54
MOT test number	693460718251
Result	✗ Failed
Fail	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #18	2022-12-13 09:16
MOT test number	814310808131
Result	✓ Passed

MOT #17	2021-12-10 15:02
MOT test number	656243068060
Result	✓ Passed

**MOT #16** 2021-12-10 08:19**MOT test number** 357939465805**Result** ✗ Failed

- Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

**MOT #15** 2020-12-18 10:20**MOT test number** 732109948346**Result** ✓ Passed**MOT #14** 2020-12-18 10:20**MOT test number** 206420854142**Result** ✗ Failed

- Pass with rectification** Offside Rear Position lamp not working (4.2.1 (a) (ii))

**MOT #13** 2019-12-16 14:47**MOT test number** 852192617717**Result** ✓ Passed**MOT #12** 2019-12-16 10:22**MOT test number** 928334651087**Result** ✗ Failed

- Advice** Nearside Front Tyre slightly damaged (5.2.3 (d) (ii))
- Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Fail** Offside Side repeater incorrect colour (4.4.3 (a))

**MOT #11** 2018-12-13 11:42**MOT test number** 916730513814**Result** ✓ Passed**MOT #10** 2017-12-04 10:23**MOT test number** 740193792165**Result** ✓ Passed**MOT #9** 2016-12-29 12:51**MOT test number** 418029282477**Result** ✓ Passed**Advice** Covers fitted upper and lower**MOT #8** 2016-03-08 10:57**MOT test number** 993505479979**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Advise n/s/f wheel binding when turned by hand**Advice** Advise sub frame getting rusty**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Advise condition of exhaust**MOT #7** 2015-03-12 11:21**MOT test number** 736031575005**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #6** 2015-03-11 11:48**MOT test number** 325360775064**Result** ✗ Failed**Fail** Rear brake application uneven (3.7.B.2)**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Pass with rectification** Offside Headlamp aim too high (1.8)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Pass with rectification** Nearside Headlamp aim too high (1.8)**MOT #5** 2014-03-12 12:00**MOT test number** 376041674008**Result** ✓ Passed**Notice** Both front tyres worn badly on far inner edges**MOT #4** 2014-03-12 09:02**MOT test number** 227221874067**Result** ✗ Failed**Notice** Both front tyres worn badly on far inner edges**Fail** Parking brake: efficiency below requirements (3.7.B.7)**MOT #3** 2013-03-09 08:31**MOT test number** 156928663079**Result** ✓ Passed**Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)



MOT #2	2013-03-08 09:49
MOT test number	179387863019
Result	✗ Failed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)
Fail	Parking brake: efficiency below requirements (3.7.B.7)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2012-02-24 14:57
MOT test number	118625852444
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
9 January 2025

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	64
<b>MOT expiry date</b>	9 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-





Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	WV09FVY
Plate since	2019-09-29
Current registration	WV09FVY
Plate since	2019-09-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2009-03-21
Last registration	2024-01-10
Complete history	<a href="#">See info</a>



Registration #1	2009-03-21	15 mi
Registration #2	2012-02-24	33.099 mi
Registration #3	2013-03-08	43.696 mi
Registration #4	2013-03-09	43.698 mi
Registration #5	2014-03-12	52.887 mi
Registration #6	2014-03-12	52.888 mi
Registration #7	2015-03-11	62.117 mi
Registration #8	2015-03-12	62.117 mi
Registration #9	2016-03-08	72.570 mi
Registration #10	2016-12-29	76.463 mi
Registration #11	2017-12-04	88.257 mi
Registration #12	2018-01-29	91.257 mi
Registration #13	2018-03-29	91.257 mi
Registration #14	2018-05-29	91.257 mi
Registration #15	2018-07-29	91.257 mi
Registration #16	2018-09-29	91.257 mi
Registration #17	2018-11-29	91.257 mi
Registration #18	2019-01-29	91.257 mi
Registration #19	2019-03-29	91.257 mi
Registration #20	2019-05-29	91.257 mi
Registration #21	2019-07-29	91.257 mi
Registration #22	2019-09-29	91.257 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1707 mm
Height	1494 mm
Length	3999 mm
Wheel base	2511 mm
Kerb weight	1102 kg
Max. allowed weight	1615 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	19SC2680