



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	I10 SE
Colour	Silver
Year of manufacture	2019
Top speed	103 mph
Gearbox	4 speed automatic

Engine & fuel consumption

Power	86 BHP
Max. torque	120 Nm at 4.000 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.8 mpg
Consumption combined	41.5 mpg
CO2 emission	141 g/km
CO2 label	F






Internet history

Entry 2


Date	2022-02-18
Pictures	22
Listing price	View report



source: [yesauto.com](#)

Entry 1

Date	2022-02-16
Pictures	23
Listing price	View report



source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2025-04-12
MOT pass rate	50 %
MOT passed	3
Failed MOT tests	3
Total advice items	6
Total items failed	11

MOT #6	2024-03-21 12:03
MOT test number	179379716233
Result	✓ Passed
Next expiry date	2025-04-12
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Lamp has water inside

MOT #5	2024-03-21 12:03
MOT test number	169124278121
Result	✗ Failed
Pass with rectification	Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Lamp has water inside

MOT #4	2023-04-13 15:49
MOT test number	151408663734
Result	✓ Passed

**MOT #3**

2023-03-09 14:25

MOT test number

959647106144

Result

✗ Failed

Fail Rear Rear fog lamp switch inoperative rear fog lamp switch not working (4.5.3 (a))**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Tested under wet conditions**MOT #2**

2023-03-01 13:53

MOT test number

474620692352

Result

✗ Failed

Fail Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Offside Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Fail** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))**Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #1**

2022-02-08 07:24

MOT test number

524155733094

Result

✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 April 2025

✓
MOT

Expires:
12 April 2025

Tax status	Valid until 1 April
Days left	337
MOT expiry date	12 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
First licence fee (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	YW68OHU
Plate since	2019-09-29
Current registration	YW68OHU
Plate since	2019-09-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2019-02-18
Last registration	2024-03-21
Complete history	See info



Registration #1	2019-02-18	12 mi
Registration #2	2022-02-08	36.387 mi
Registration #3		
Registration #4		
Registration #5	2023-03-01	49.964 mi
Registration #6		
Registration #7		
Registration #8		
Registration #9		

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	79%
Children	80%
Pedestrian	71%
Safety systems	56%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1660 mm
Height	1500 mm
Length	3665 mm
Wheel base	2385 mm
Kerb weight	961 kg
Max. allowed weight	1080 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G4LAJM060192