





report date: 2024-03-29

General information

Make	MERCEDES-BENZ
Model	CLS CLS250 CDI BLUEEFFICIENCY AMG SPORT
Colour	Black
Year of manufacture	2014
Top speed	150 mph
0 - 60 mph	7.5 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	204 BHP
Max. torque	500 Nm at 1.800 rpm
Engine capacity	2.143 сс
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	64.2 mpg
Consumption combined	55.4 mpg
CO2 emission	138 g/km
CO2 label	E



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1

Date 2022-02-12

Pictures 24

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT history

MOT expiry date	2025-02-12
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	13
Total items failed	0

MOT #10	2024-02-01 12:46
MOT test number	768884717688
Result	✓ Passed
Next expiry date	2025-02-12
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #9		2023-02-13 12:47
MOT test	number	651285750106
Result		✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

	2022-02-03 15:55
r	823577004747
	✓ Passed
	2022-02-02 16:58
r	259249657522
	× Failed
Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Front Inner Tyre tread depth below requirements of 1.6mm both (5.2.3 (e))
	r Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) Front Inner Tyre tread depth below requirements of 1.6mm both (5.2.3 (e)

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #6		2021-06-18 10:04
MOT test	number	115603318352
Result		✓ Passed
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge slight worn inner ed	dge (5.2.3 (e))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened	d (1.1.14 (a) (ii))
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge slight worn inner	edge (5.2.3 (e))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened	(1.1.14 (a) (ii))

MOT #5		2020-06-25 13:57
MOT test	number	662906420591
Result		✓ Passed
MOT #4		2020-06-23 14:29
MOT test	number	874665865559
Result		★ Failed
MAJOR	Parking brake efficiency below requirements (1.4.2 (a) (i))	
MAJOR	Nearside Rear Parking brake inoperative on one side (1.4.1 (a))	

,	ranking brake emerciney below regularities (21 Hz (a) (1))	
MAJOR	Nearside Rear Parking brake inoperative on one side (1.4.1 (a))	
		2012 02 16 00 50
MOT #3		2019-03-16 09:50
MOT test	number	833997451870
Result		✓ Passed
MOT #2		2018-03-23 08:58
MOT test	number	870747641033
Result		✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #1 2017-03-15 16:39

MOT test number 732926010468

Result ✓ Passed

CarCheck.co.uk page 5/12



WA14SGX report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 March
Days left	305
MOT expiry date	12 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12




report date: 2024-03-29

Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report here for the results.

Damage 1

Date
Category
Type
Damage 2
Date
Category



Extra MERCEDES-BENZ salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



WA14SGX report date: 2024-03-29

Owner history	
For how long did the current and previous owner(s) have this MERCEDES-BENZ? How man MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Description of the premium report here.	

	More info >
Plate changes	
See in this check if this MERCEDES-BENZ had different number plates.	
Number of plates	,
Current registration	NK NK
Plate since	
Current registration	NE SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-03-31
Last registration	2024-02-01
Complete history	See info



Registration #1	2014-03-31	19 mi
Registration #2	2017-03-15	32.450 mi
Registration #3	2018-03-23	42.661 mi
Registration #4	2019-03-16	47.864 mi
Registration #5	2020-06-23	52.017 mi
Registration #6	2020-06-25	52.017 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		

More info >

CarCheck.co.uk page 11/12



WA14SGX report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	93%
Children	81%
Pedestrian	67%
Safety systems	86%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1881 mm
Height	1416 mm
Length	4940 mm
Wheel base	2874 mm
Kerb weight	1785 kg
Max. allowed weight	2270 kg

Additional information

Fuel tank capacity	59 I
Fuel delivery	Direct Injection
Number of doors	4
CarChack co. uk	nago 12/12

CarCheck.co.uk page 12/12

Number of seats	4
Number of axles	2
Engine number	65192432196048