



report date: 2024-03-28

General information

Make	CITROEN
Model	NEMO HDI 8V
Colour	Grey
Year of manufacture	2009
Top speed	94 mph
0 - 60 mph	18.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	160 Nm at 1.750 rpm
Engine capacity	1.399 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C






Internet history

Entry 1

Date	2022-01-31
Pictures	21
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-08
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	18
Total items failed	16

MOT #19	2024-01-18 20:39
MOT test number	373272631367
Result	✓ Passed
Next expiry date	2025-02-08
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Nearside Obligatory mirror slightly damaged (3.3 (b) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #18	2023-01-27 13:38
MOT test number	680571694178
Result	✓ Passed
Advice	Suspension components fuel and brake lines slighty corroded

**MOT #17**

2023-01-21 08:00

MOT test number

980898230144

Result**✗ Failed****Advice** Nearside Front Position lamp slightly affected by the operation of another lamp (4.2.3 (c))**Fail** Nearside Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))**Fail** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Windscreen washer not working (3.5 (a))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Fail** Nearside Outer Seat belt anchorage prescribed area strength or continuity significantly reduced sill (7.1.1 (a) (i))**Fail** Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #16**

2022-02-09 13:32

MOT test number

803251021615

Result**✓ Passed****MOT #15**

2021-03-10 12:32

MOT test number

846000861595

Result**✓ Passed****MOT #14**

2021-03-04 09:58

MOT test number

515489070229

Result**✗ Failed****Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #13** 2020-03-11 11:46**MOT test number** 393255437003**Result** ✓ Passed

Advice Nearside Rear Outer Suspension component mounting prescribed area is corroded but not considered excessive sill (5.3.6 (a) (i))

MOT #12 2020-03-10 11:24**MOT test number** 121450522075**Result** ✗ Failed

Advice Nearside Rear Outer Suspension component mounting prescribed area is corroded but not considered excessive sill (5.3.6 (a) (i))

Fail Nearside Rear Upper Shock absorbers has an excessively worn bush (5.3.2 (c))

Fail Nearside Front Outer Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting sill (6.2.2 (d) (i))

Fail Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Fail Offside Rear Upper Shock absorbers has an excessively worn bush (5.3.2 (c))

MOT #11 2019-03-12 14:57**MOT test number** 443766061232**Result** ✓ Passed**MOT #10** 2019-03-12 10:29**MOT test number** 791332968413**Result** ✗ Failed

Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #9** 2018-03-12 12:26**MOT test number** 132473138707**Result** ✓ Passed**Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #8** 2017-03-07 11:24**MOT test number** 963273668004**Result** ✓ Passed**MOT #7** 2016-03-02 13:38**MOT test number** 604100570320**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened both sides (3.5.1i)**Advice** Offside Front steering rack end has slight play**MOT #6** 2015-03-03 11:07**MOT test number** 426272165049**Result** ✓ Passed**MOT #5** 2014-03-10 16:12**MOT test number** 466479864095**Result** ✓ Passed**Notice** Nearside front tyre worn on inner edge**Notice** Offside front tyre worn on inner edge

**MOT #4** 2014-03-06 10:43**MOT test number** 568475464034**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)**Notice** Nearside front tyre worn on inner edge**Notice** Offside front tyre worn on inner edge**MOT #3** 2013-03-15 16:23**MOT test number** 586284373086**Result** ✓ Passed**MOT #2** 2013-03-14 12:27**MOT test number** 816773273035**Result** ✗ Failed**Fail** Nearside Front coil spring fractured (2.4.C.1a)**MOT #1** 2012-03-09 11:32**MOT test number** 196089562095**Result** ✓ Passed**Notice** Headlamp masks/converters fitted**Notice** Items removed from driver's view prior to test



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
8 February 2025

Tax status	Valid until 1 February
Days left	279
MOT expiry date	8 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-03-31
Last registration	2024-01-18
Complete history	See info



Registration #1	2009-03-31	22 mi
Registration #2	2012-03-09	37.348 mi
Registration #3	2013-03-14	45.124 mi
Registration #4	2013-03-15	45.124 mi
Registration #5	2014-03-06	49.376 mi
Registration #6	2014-03-10	49.376 mi
Registration #7	2015-03-03	54.233 mi
Registration #8	2016-03-02	59.539 mi
Registration #9	2017-03-07	63.151 mi
Registration #10	2018-03-12	67.378 mi
Registration #11	2019-03-12	72.457 mi
Registration #12	2020-03-20	75.277 mi
Registration #13	2021-03-20	75.277 mi
Registration #14	2022-03-20	75.277 mi
Registration #15	2023-03-20	75.277 mi
Registration #16	2024-01-18	75.277 mi
Registration #17	2024-01-18	75.277 mi
Registration #18	2024-01-18	75.277 mi
Registration #19	2024-01-18	75.277 mi
Registration #20	2024-01-18	75.277 mi
Registration #21	2024-01-18	75.277 mi

More info >



Dimensions & weight

Width	1816 mm
Height	1721 mm
Length	3959 mm
Wheel base	2513 mm
Kerb weight	1185 kg
Max. allowed weight	1710 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	FD982532186